



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLV 3580 P
KIA CARENS

Not Authorised
13/11/18
3 days before party.

P/P # 2 898.99

ATTN:			QTY	PRICE
NO.	DESCRIPTION - PARTS			
	REAR BOOTLID	12 X		\$ 1,088.00 X
	REAR BOOTLID WEATHERSTRIP	11 X		\$ 131.00 X
	REAR BOOTLID LOGO	11 X		\$ 48.00 X
	REAR BOOTLID EMBLEM - CRDI	11 X		\$ 39.00 X
	REAR BOOTLID EMBLEM - CARENS	11 X		\$ 36.00 X
	REAR BOOTLID EMBLEM - C&C	11 X		\$ 56.00 X
	REAR BOOTLID CENTER CHROME MOULDING	11 X		\$ 104.00 X
	REAR BOOTLID PROTECTOR	11 X		\$ 135.00 X
	BOOTLID LAMP RH	11 X		\$ 670.00 X
	REAR WINDSCREEN COMPLETE SET WITH MOULDING	11 X		\$ 850.00 X
	TAILLAMP RH	11 X	381.99	\$ 850.00 X
	RH REAR FENDER	12 X		\$ 576.00 X
	RH REAR FENDER COWLING	11 X		\$ 189.00 X
	REAR BUMPER - UPPER	Dis		\$ 10.00 X
	REAR BUMPER - LOWER	200A		\$ 116.00 X
	REAR BUMPER TOW COVER	11 X		\$ 285.00 X
	REAR BUMPER REFLECTOR	015 one		\$ 25.00 X
	REAR BUMPER CENTER PROTECTION LOWER	11 X		\$ 367.00 X
	REAR BUMPER BRACKET	11 X		\$ 18.00 X
	REAR BUMPER REINFORCEMENT	34		\$ 162.00 X
	REAR BUMPER SIDE RETAINER	34		\$ 18.00 X
	REVERSE SENSOR	shred 1pc		\$ 18.00 X
	REVERSE SENSOR HOLDER	11 X		\$ 453.00 X
	REAR END PANEL	12 X		\$ 285.00 X
	REAR END PANEL TOP GARNISH	11 X		\$ 485.00 X
	REAR FLOOR PANEL TOP BOARD	11 X		
		P-1809.99	SUBTOTAL	\$ 6,146.00
		10%	LESS 10%	\$ 614.60
		1628.99	PARTS TOTAL	\$ 5,531.40
	SPECIAL NETT		QTY	PRICE
	REAR NUMBER PLATE	11 X		\$ 80.00 X
	REAR END PANEL SEALANT	11 X		\$ 100.00 X
	BOOTLID INNER TRIM CLIPS	11 X		\$ 100.00 X
	REAR BUMPER CLIPS	11 X		\$ 80.00 X
	REAR END PANEL TOP GARNISH CLIPS	11 X		\$ 100.00 X
			SPECIAL NETT TOTAL	\$ 460.00
	LABOUR		QTY	PRICE

TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	480	\$ 1,200.00
TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	600	\$ 1,000.00
TO RUST PROOF ACCIDENT AFFECTED AREA	11X	\$ 80.00
TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	60	\$ 400.00
TO RNR REAR BOOT MECHANISM	11X	\$ 250.00
TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	\$ 100.00
TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	20	\$ 80.00
TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11X	\$ 150.00
TO DO WATER LEAK TEST .	11X	\$ 100.00
	LABOUR TOTAL	\$ 3,360.00
	GRAND TOTAL COST	\$ 9,351.40
	1210	

PAGE 2 OF 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

8-1809.99
 102
 1628.99
 5.21 + 60.00
 1628.99 + 1210.00
 2838.99