

























PAR Automotive Consultancy

Regn No: S2986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0527-18-N51

03 September 2018

ACCIDENT VEHICLE SURVEY REPORT

Chen Han Yen
Blk 211 Pasir Ris St 21 #04-248
Singapore 510211

VEHICLE INFORMATION:

<i>Vehicle Reg No:</i>	SGX343B	<i>Odometer:</i>	172057km
<i>Make & Model:</i>	Toyota Yaris G Auto	<i>Colour:</i>	Silver
<i>Chassis number:</i>	MR054HY9104021086	<i>Date of accident:</i>	13/12/2017
<i>Year of Regn.:</i>	08/08/2007	<i>Date inspected:</i>	15/12/2017
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	23/12/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

















































