



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKZ3898P

Date of Accident : 01 November 2018

Messrs Malaysia Dairy Industries Pte Ltd

Date : 07 November 2018

Estimate To Repair YP5034P - Mitsubishi FUSO FK62FMZ1RDEB
Chassis No : FK62FMA30196

Lkk Marcus
21/11/18 0900hrs

S/No	Quantity	Description	Amount
SPECIAL NETT ITEMS			
01	1 pc	right lower side rail	\$ 1,500.00
02	1 pc	right rear wheel arch	\$ 380.00
			\$ 1,880.00
LABOUR & MISC. CHARGES			
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
02		Putty and spray painting of the affected portion.	\$ 400.00
			\$ 800.00
		Total	\$ 2,680.00

not allocated
Lkr
1 dr.
21/11/18
The photo attached
p/p \$500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: