

ASS. REC. BY:

REF:

CS/GAI/8020580/Rlsd3ed

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Kelvyna Ngian

of GAI

Date/Time: 14/11/18 @ 11:10am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCM 6525J

Insured:

GBG 29655

at Workshop m/s:

Trans Eurokars

Tel:

6331 0682

of

27A Tanjong Penjuru

Policy No:

Claim No:

CLMOMVC000003546

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 09/11/2018

15/11/18 @ 11am - 11:30am

CA / REV / REP. / REV 24 HRS

^(up)

H.O.D. Endorsement:

Date/Time:

11:32am @ 14/11/18

Person Contacted:

Jobi

Vehicle IN

☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SCM 6525J - X

GBG 29655 - X

16/11/18

@ 13:33p.m. revised RA to Kelvyna via email.

(08/11/13)

Surveyor: *Pam*

REF:

18459

COE X 124. 2008/86P

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCM 65253at Workshop m/s TRANS EUROKARSof 21A, TONGLOH PLAZAInsured: GAI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

*11am-1130 Job
GAI m/s*Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SCM 65253 Yr Regn: 2008 / 86PType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MINICOOPER ONE 1.4 AT c.c. 1397Colour: yellow A/C: Insured / Std / NI / NASp. Reading: 057847 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMWME 32010TM 76349Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 09/11/18 D.O.I. 15/11/18Survey held at TRANS EUROKARSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/12/18	Confirmed P/P \$11,740.52 @ 8 days with Resul. (\$ 3,222.76 Red - 22%)

RECEIVED 11 DEC 2018

10/12/2018

Date/Time, File Pass to?

11/12/18

☐ : Preli. Report☒ : Final Report1) Typist
Date/Time, File Return to?

2) _____

Days Of Repair: 8Resurvey No. of Trip: 1Survey Fee: 350

Transportation: _____ \$ + RS _____ \$

Photos

Others

TOTAL

350

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I.: (\$ 11,740.52 P/P)

Nivitha (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Wednesday, 14 November 2018 11:10 AM
To: Admin-D (LKKAuto); 'Admin A'
Subject: GA REF: GBG2965S / OUR REF: SCM6525J THIRD PARTY CLAIM
Attachments: 1237_001.pdf; SCM6525J (NTUC).pdf

Hi team

Please conduct TP survey.

Thanks
Kelvyna

From: jobithomas@eurokars.com.sg <jobithomas@eurokars.com.sg>
Sent: Wednesday, November 14, 2018 11:04 AM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: eva.kok@eurokars.com.sg; rickteo@eurokars.com.sg
Subject: [External] RE: YOUR REF: GBG2965S / OUR REF: SCM6525J THIRD PARTY CLAIM

Dear Kelvyna,

Kindly assign to LKK, thanks.

Best Regards.



Jobi Thomas
Insurance Claims Executive
27A Tanjong Penjuru, Singapore 609042
T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690
E: jobithomas@eurokars.com.sg W: www.eurokarsgroup.com

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 16 November 2018 1:33 PM
To: 'Ngian, Kelvyna'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: GA REF: GBG2965S / OUR REF: SCM6525J THIRD PARTY CLAIM
Attachments: SCM 6525J - Preli Advise.pdf

Dear Kelvyna,

Enclosed preliminary revised of vehicle SCM 6525J.

Please provide us the claim reference no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 14 November 2018 11:36 AM
To: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GA REF: GBG2965S / OUR REF: SCM6525J THIRD PARTY CLAIM

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]
Sent: Wednesday, 14 November 2018 11:10 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Subject: GA REF: GBG2965S / OUR REF: SCM6525J THIRD PARTY CLAIM

Hi team

Please conduct TP survey.

Thanks
Kelvyna

From: jobithomas@eurokars.com.sg <jobithomas@eurokars.com.sg>
Sent: Wednesday, November 14, 2018 11:04 AM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: eva.kok@eurokars.com.sg; rickteo@eurokars.com.sg
Subject: [External] RE: YOUR REF: GBG29655 / OUR REF: SCM6525J THIRD PARTY CLAIM

Dear Kelvyna,

Kindly assign to LKK, thanks.

Best Regards.



Jobi Thomas
Insurance Claims Executive
27A Tanjong Penjuru, Singapore 609042
T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690
E: jobithomas@eurokars.com.sg W: www.eurokarsgroup.com

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 11 December 2018 1:15 PM
To: jessicahs@eurokars.com.sg; jobithomas@eurokars.com.sg
Cc: SUR; Rasul (LKKAuto); sarah.candida@eurokars.com.sg
Subject: RE: FINALIZATION SCM6525J TP GAI

Hi Jessica,

Confirmed final fig of \$ 11,740.52 (part by part) @ 8 days of repairs before GST.

Final invoice and all supporting documents sent over to Great American Insurance Company.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg [mailto:jessicahs@eurokars.com.sg]
Sent: Monday, 10 December 2018 10:56 AM
To: jobithomas@eurokars.com.sg; ShirleyHiew@lkkauto.com
Cc: sur@lkkauto.com; Rasul@lkkauto.com; sarah.candida@eurokars.com.sg
Subject: FINALIZATION SCM6525J TP GAI

Dear Rasul,

Please find our computation attached for your agreement.

COR: \$11,740.52 before GST

08 repair days (not including preparation of estimate, wait for liability/wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirmation for this case urgently.

Thank you very much.

Regards,

JESSICA SHASTRI

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com

From: Jobi Thomas
Sent: 07 December 2018 11:48 AM



To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Jessica Harry Shastri <jessicahs@eurokars.com.sg>; SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: RE: SCM6525J BEFORE PAINT & CHECK ITEM PHOTOS

Hi Shirley,

Kindly refer to the photos below, Tail pipe chrome used back.



Best Regards.

Jobi Thomas

Insurance Claims Executive

27A Tanjong Penjuru, Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690

E: jobithomas@eurokars.com.sg W: www.eurokarsgroup.com

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>**Sent:** 07 December 2018 11:35 AM**To:** Jobi Thomas <jobithomas@eurokars.com.sg>**Cc:** Jessica Harry Shastri <jessicahs@eurokars.com.sg>; SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>**Subject:** RE: SCM6525J BEFORE PAINT & CHECK ITEM PHOTOS

Hi Jobi,

According to our surveyor, Rasul request the photo as below:

- 1) Reinforcement Foam (no photo)
- 2) Tail Pipe Chrome (no photo)
- 3) Number Plate Lights (damage unseen)

Thank you,

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jobithomas@eurokars.com.sg [<mailto:jobithomas@eurokars.com.sg>]**Sent:** Wednesday, 5 December 2018 4:59 PM**To:** Rasul@lkkauto.com**Cc:** jessicahs@eurokars.com.sg; sur@lkkauto.com**Subject:** SCM6525J BEFORE PAINT & CHECK ITEM PHOTOS

Dear Rasul,

Kindly refer to the attached SCM6525J BEFORE PAINT & CHECK ITEM PHOTOS.

Best Regards.

Jobi Thomas

Insurance Claims Executive

27A Tanjong Penjuru, Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690

E: jobithomas@eurokars.com.sg W: www.eurokarsgroup.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 16 November 2018

Our Ref: CS/GAI18020580/R1sd3

The Motor Claims Department
Great American Insurance Company

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SCM 6525J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/11/2018 at the premises of M/s Eurokars Habitat Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 14,963.28</u>
Revised Estimate Amount	: <u>S\$ 11,242.01</u>
"Check" Items Amount	: <u>S\$ 949.89</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 8 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/11/2018 16:03
Date Of Accident	09/11/2018 13:55
Exact Location Of Accident	JUNCTION OF HOLLAND AND DEMPSEY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCM6525J
Insured/Policyholder	
Name Of Registered Owner	LEE KWANG HONG
NRIC No	S1391845G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96880569
Alternative Phone No	OFFICE-96880569

Vehicle Particulars

Manufacturer	MINI
Model	ONE 1.4 (R)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103974184 (PREMIUM)
Cover Note Number	

Driver

Name of Driver	LEE KWANG HONG
NRIC No	S1391845G
Date Of Birth	25/05/1959
Occupation	INDOOR
Date Of Driving Pass	23/05/1977
Driving Experience	41 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96880569
Fax Number	
Contact Number	OFFICE-96880569
Email Address	NOEMAIL

Address	700 LORONG 1 TOA PAYOH #17-16
Postcode	S319773
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SENT TO INSURANCE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	G8G2965S
Vehicle Make/Model/Colour	TOYOTA VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHEW KONG LAM(K LAM ENGTERPRISE)
NRIC/Passport Number	S1360663C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claim(s);
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 650545
Tel: 6569 3312 Fax: 6569 0722
Email: vacbu@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

STOPPED AT TRAFFIC JUNCTION
GBC 29655 HIT ME FROM BEHIND.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Wm. L. Galt

Policyholder's Signature
Date & Time:

01-10-2004

Driver's Signature
(If driver is not the policyholder)
Date & Time:

~~9 NOV 1979~~

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 22
Singapore 659441
Tel: 6500 3312 Fax: 6500 0000
Email: vacbu@singnet.sg

Reporting Centre Personnel's Signature
Name: _____
NRIC/TIN No.: _____

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5103974184

Cover : drive PREMIUM

- | | |
|---|---------------------|
| 1. Index mark and Registration Number of Vehicle | : SCM652SJ |
| Chassis Number | : WMWME32010TM76349 |
| 2. Name of Policyholder | : LEE KWANG HONG |
| 3. Effective Date of Insurance | : 19 Sep 2018 |
| 4. Expiry Date of Insurance | : 24 Sep 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |

This Policy does not cover

- (a) Use for hire or reward.
 - (b) Use for racing, pace-making, reliability trial or speed-testing.
 - (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
 - (d) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: S\$1,000
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: YES
INSURE WITH COE	: YES
NCD PROTECTION	: YES
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: LEE KWANG HONG
NAMED DRIVER (1)	: LIEU KIM LAN
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : AVJ AGENCY & SERVICES (00000572253)
Date of Issue : 18 Sep 2018 10:27 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S1391845G**

Name: **LEE KWANG HONG**

Birth Date: **25 May 1959**

Issue Date: **29 Apr 2003**

10004334325




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1391845G**

Name: **LEE KWANG HONG**

Race: **CHINESE**

Date of Birth: **25-05-1959**

Country of Birth: **SINGAPORE**

Sex: **M**

S1391845G






YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **23 May 1977**

NP 428A

Licence No: **S1391845G**



0285303

Barcode

NRIC No: **S1391845G**

700 LORONG 1 TOA PAYOH #17-16
SINGAPORE 319773

NRIC No: **S1391845G**

Date: **23/05/2008**

No: **5923605**

Class of Issue: **O+**

Date of Issue: **29-03-1992**



96880569



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-173870

Date of Request: 09/11/2018

Your Ref No:

Online Purchase

Eurokars Habitat Pte Ltd
12 Sungei Kadut Avenue
Singapore 729648

Dear Sir/Madam,

Enquiry Date 09/11/2018
Enquiry By Jessica Harry Shastri
TP Vehicle No. GBG2965S
Accident Date 09/11/2018

SCM6525J (mimi)

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBG2965S	Great American Insurance Company	15/07/2018-14/07/2019	6804 6047

Thank You.

The Images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



Great American Insurance Company #16-01 Centennial Tower Singapore 039190.		NAME : MR LEE KWANG HONG		WIP : 23560	
ATTN : MOTOR CLAIMS		ADDRESS : 700 LORONG 1 TOA PAYOH #17-16 Singapore 319773		EXCESS :	
FAX :		TEL : 96880569		DATE: 12.11.2018	
VEH NO :	SCM6525J	DATE IN :		CONTACT PERSON :	JOBI THOMAS 63310682
CHASSIS NO :	WMWME32010TM76349	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	R56 MINI ONE	DATE REG.:	25.09.2008	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
		QTY			
1	TAILGATE <i>neu /</i>	1	M41.00.2.752.015		\$ 1,185.56
2	TAILGATE CLIPS <i>neu /</i>	3	B07.14.7.141.218		\$ 13.14
3	PLUG IN NUT <i>neu /</i>	4	M51.25.2.753.575		\$ 7.76
4	REAR WINDSCREEN TOP MOULDING <i>neu /</i>	1	M51.31.7.151.130		\$ 40.13
5	REAR WINDSCREEN LOWER MOULDING INSERT <i>neu /</i>	1	M51.31.2.754.853		\$ 40.13
6	REAR WINDSCREEN LOWER MOULDING CHROM <i>neu /</i>	1	M51.31.2.754.852		\$ 124.00
7	CLIP <i>neu /</i>	5	M07.14.2.754.954		\$ 7.80
8	REAR WINDSCREEN TOP MOULDING <i>neu /</i>	2	M51.37.2.756.103		\$ 26.88
9	REAR EMBLEM "MINI" <i>neu /</i>	1	M51.14.7.026.186		\$ 75.69
10	EMBLEM "ONE" <i>neu /</i>	1	M51.14.2.755.615		\$ 68.13
11	TAILGATE GARNISH CHROME <i>neu /</i>	1	M51.13.2.753.603		\$ 208.25
12	PLASTIC SCREW <i>neu /</i>	4	B84.13.7.007.031		\$ 13.76
13	TAILGATE GARNISH GASKET <i>neu /</i>	1	M51.13.7.361.202		\$ 26.13
14	REAR BUMPER <i>DE /</i>	1	M51.12.7.128.962		\$ 803.56
15	TOW COVER <i>cut /</i>	1	M51.12.2.755.693		\$ 38.94
16	REAR BUMPER RAIL GUIDE <i>neu /</i>	1	M51.12.7.127.744		\$ 34.19
17	REAR BUMPER BRACKET <i>neu /</i>	1	M51.12.7.126.172		\$ 25.13
18	REAR BUMPER SIDE RETAINER LH <i>neu /</i>	1	M51.12.2.751.303		\$ 22.81
19	REAR BUMPER SIDE RETAINER RH <i>neu /</i>	1	M51.12.2.751.304		\$ 22.81
20	REAR BUMPER BREATHER <i>? neu /</i>	1	M64.22.9.242.797		\$ 49.19
21	EXPANDING NUT <i>neu /</i>	10	M63.25.2.758.031		\$ 19.40
22	RIVET <i>neu /</i>	10	M51.47.2.754.477		\$ 23.10
23	EXPANDING RIVET <i>neu /</i>	2	M07.13.0.702.966		\$ 2.76
24	REAR BUMPER LOWER SPOILER <i>DE /</i>	1	M51.12.7.147.876		\$ 155.06
25	FOG LAMP TRIM <i>neu /</i>	1	M51.12.2.753.653		\$ 46.56
26	LOWER SPOILER EXPANDING RIVET <i>neu /</i>	2	M51.48.1.915.964		\$ 3.00
27	REAR BUMPER REINFORCEMENT <i>? neu /</i>	1	M51.12.2.751.305		\$ 462.00
28	REINFORCEMENT FOAM <i>neu /</i>	1	M51.12.2.754.466		\$ 48.56
29	TAILGATE TRIM PANEL <i>neu /</i>	1	M51.49.7.148.904		\$ 307.63
30	TRIM PANEL CLIP <i>neu /</i>	2	M07.13.1.503.417		\$ 6.00
31	TRIM PANEL SLEEVE <i>neu /</i>	2	M51.47.0.744.888		\$ 9.76
32	EXPANDING NUT <i>neu /</i>	2	B63.17.1.367.868		\$ 1.38
33	REAR FOG LAMP <i>neu /</i>	1	M63.24.6.946.904		\$ 159.38
34	TAIL LAMP TRIM LH <i>X inconsistent neu /</i>	1	M51.13.2.752.243		\$ 90.69

35	TAIL LAMP TRIM RH	x inconstat n x	1	M51.13.2.752.244		\$	90.69
36	SENSOR SOCKET HOUSING	ne /	1	M61.13.6.934.315		\$	6.94
37	SENSOR PARKASSIST	n /	1 PC	M66.20.9.196.705		\$	592.12
38	SENSOR GASKET	ne /	1 PC	M66.20.6.923.000		\$	12.62
39	MUFFLER INSULATION	? pt /	1	M51.48.2.757.191		\$	254.75
40	TAIL PIPE CHROME	? X 8m	1	M18.30.2.753.086		\$	106.13
41	NUMBER PLATE LIGHTS	? CRA /	2	M51.13.2.756.227		\$	29.26
42	PLUG-IN NUT	ne /	2	M51.18.8.242.693		\$	1.50
TOTAL PARTS						\$	5,263.28
						\$	-
TOTAL PARTS COST						\$	5,263.28
<u>Labour Description</u>							
1	TO REMOVE / REPLACE TAILGATE, REAR BUMPER & TO REPAIR LH REAR FENDER, RH REAR FENDER & REAR END PANEL AREAS AFFECTED BY THE ACCIDENT.				2520	\$	2,500.00
2	TO RESPRAY TAILGATE, REAR BUMPER, LH REAR FENDER, RH REAR FENDER & REAR END PANEL.				2400	\$	4,200.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.				150	\$	250.00
4	TO TRANSFER THE TAILGATE MECHANISM.				420	\$	500.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.				NETT	\$	560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.				NETT	\$	120.00
7	TO TRANSFER THE REVERSE SENSORS.				420	\$	500.00
8	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.				NETT	\$ 74	70.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				150	\$	250.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				250	\$	350.00
11	SUNDRIES.				NETT	\$ 50	100.00
TOTAL LABOUR					\$	-	\$ 9,700.00
TOTAL PARTS					\$	-	\$ 5,263.28
TOTAL					\$	-	\$ 14,963.28
LESS EXCESS					\$	-	\$ -
TOTAL AFTER EXCESS					\$	-	
GST 7%					\$	-	\$ -
GRAND TOTAL					\$	-	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A
QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED
IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Resum

HP 900/0668

8 days

9/p

15/11/18 @ 1000

Resum 54 paint

15/11/18

LRC Auto Consultants hence notify
the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



Great American Insurance Company		NAME :	MR LEE KWANG HONG		WIP :	23560	
#16-01 Centennial Tower		ADDRESS :	700 LORONG 1 TOA PAYOH		EXCESS :		
Singapore 039190.			#17-16		DATE:	12.11.2018	
			Singapore 319773				
ATTN. : MOTOR CLAIMS		TEL :	96880569				
FAX :							
VEH NO :	SCM6525J	DATE IN :		CONTACT PERSON :	JOBI THOMAS 63310682		
CHASSIS NO :	WMWME32010TM76349	MILEAGE :		TYPE OF CLAIM :	TP		
MODEL :	R56 MINI ONE	DATE REG.:	25.09.2008	POLICY NO. :			

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	TAILGATE	1	M41.00.2.752.015	\$ 1,185.56	\$ 1,185.56
2	TAILGATE CLIPS	3	B07.14.7.141.218	\$ 13.14	\$ 13.14
3	PLUG IN NUT	4	M51.25.2.753.575	\$ 7.76	\$ 7.76
4	REAR WINDSCREEN TOP MOULDING	1	M51.31.7.151.130	\$ 40.13	\$ 40.13
5	REAR WINDSCREEN LOWER MOULDING INSERT	1	M51.31.2.754.853	\$ 40.13	\$ 40.13
6	REAR WINDSCREEN LOWER MOULDING CHROM	1	M51.31.2.754.852	\$ 124.00	\$ 124.00
7	CLIP	5	M07.14.2.754.954	\$ 7.80	\$ 7.80
8	REAR WINDSCREEN TOP MOULDING	2	M51.37.2.756.103	\$ 26.88	\$ 26.88
9	REAR EMBLEM "MINI"	1	M51.14.7.026.186	\$ 75.69	\$ 75.69
10	EMBLEM "ONE"	1	M51.14.2.755.615	\$ 68.13	\$ 68.13
11	TAILGATE GARNISH CHROME	1	M51.13.2.753.603	\$ 208.25	\$ 208.25
12	PLASTIC SCREW	4	B84.13.7.007.031	\$ 13.76	\$ 13.76
13	TAILGATE GARNISH GASKET	1	M51.13.7.361.202	\$ 26.13	\$ 26.13
14	REAR BUMPER	1	M51.12.7.128.962	\$ 803.56	\$ 803.56
15	TOW COVER	1	M51.12.2.755.693	\$ 38.94	\$ 38.94
16	REAR BUMPER RAIL GUIDE	1	M51.12.7.127.744	\$ 34.19	\$ 34.19
17	REAR BUMPER BRACKET	1	M51.12.7.126.172	\$ 25.13	\$ 25.13
18	REAR BUMPER SIDE RETAINER LH	1	M51.12.2.751.303	\$ 22.81	\$ 22.81
19	REAR BUMPER SIDE RETAINER RH	1	M51.12.2.751.304	\$ 22.81	\$ 22.81
20	REAR BUMPER BREATHER	1	M64.22.9.242.797	\$ -	\$ 49.19
21	EXPANDING NUT	10	M63.25.2.758.031	\$ 19.40	\$ 19.40
22	RIVET	10	M51.47.2.754.477	\$ 23.10	\$ 23.10
23	EXPANDING RIVET	2	M07.13.0.702.966	\$ 2.76	\$ 2.76
24	REAR BUMPER LOWER SPOILER	1	M51.12.7.147.876	\$ 155.06	\$ 155.06
25	FOG LAMP TRIM	1	M51.12.2.753.653	\$ 46.56	\$ 46.56
26	LOWER SPOILER EXPANDING RIVET	2	M51.48.1.915.964	\$ 3.00	\$ 3.00
27	REAR BUMPER REINFORCEMENT	1	M51.12.2.751.305	\$ 462.00	\$ 462.00
28	REINFORCEMENT FOAM	1	M51.12.2.754.466	\$ 48.56	\$ 48.56
29	TAILGATE TRIM PANEL	1	M51.49.7.148.904	\$ 307.63	\$ 307.63
30	TRIM PANEL CLIP	2	M07.13.1.503.417	\$ 6.00	\$ 6.00
31	TRIM PANEL SLEEVE	2	M51.47.0.744.888	\$ 9.76	\$ 9.76
32	EXPANDING NUT	2	B63.17.1.367.868	\$ 1.38	\$ 1.38
33	REAR FOG LAMP	1	M63.24.6.946.904	\$ 159.38	\$ 159.38
34	TAIL LAMP TRIM LH	1	M51.13.2.752.243	\$ -	\$ 90.69

35	TAIL LAMP TRIM RH	1	M51.13.2.752.244	\$ -	\$ 90.69
36	SENSOR SOCKET HOUSING	1	M61.13.6.934.315	\$ 6.94	\$ 6.94
37	SENSOR PARKASSIST	1	M66.20.9.196.705	\$ 296.06	\$ 592.12
38	SENSOR GASKET	2	M66.20.6.923.000	\$ 12.62	\$ 12.62
39	MUFFLER INSULATION	1	M51.48.2.757.191	\$ 254.75	\$ 254.75
40	TAIL PIPE CHROME	1	M18.30.2.753.086	\$ -	\$ 106.13
41	NUMBER PLATE LIGHTS	2	M51.13.2.756.227	\$ 29.26	\$ 29.26
42	PLUG-IN NUT	2	M51.18.8.242.693	\$ 1.50	\$ 1.50
			TOTAL PARTS	\$ 4,630.52	\$ 5,263.28
					\$ -
			TOTAL PARTS COST	\$ 4,630.52	\$ 5,263.28
			Labour Description		
1	TO REMOVE / REPLACE TAILGATE, REAR BUMPER & TO REPAIR LH REAR FENDER, RH REAR FENDER & REAR END PANEL AREAS AFFECTED BY THE ACCIDENT.			\$ 2,520.00	\$ 2,700.00
2	TO RESPRAY TAILGATE, REAR BUMPER, LH REAR FENDER, RH REAR FENDER & REAR END PANEL.			\$ 2,400.00	\$ 4,300.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 150.00	\$ 250.00
4	TO TRANSFER THE TAILGATE MECHANISM.			\$ 420.00	\$ 500.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.			\$ 560.00	\$ 560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.			\$ 120.00	\$ 120.00
7	TO TRANSFER THE REVERSE SENSORS.			\$ 420.00	\$ 500.00
8	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.			\$ 70.00	\$ 70.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 150.00	\$ 250.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 250.00	\$ 350.00
11	SUNDRIES.			\$ 50.00	\$ 100.00
			TOTAL LABOUR	\$ 7,110.00	\$ 9,700.00
			TOTAL PARTS	\$ 4,630.52	\$ 5,263.28
			TOTAL	\$ 11,740.52	\$ 14,963.28
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ 11,740.52	
			GST 7%	\$ 821.84	\$ -
			GRAND TOTAL	\$ 12,562.36	\$ -

NUMBER OF DAYS: 8 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SATURDAY,SUNDAY AND PUBLIC HOLIDAY)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18020580/R1sd3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 28-12-2018	
		Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 2965S	Veh. Inspected	SCM 6525J
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003546	Excess (\$)	0.00
Assign From	KELVYNA NGIAN	Assign Date	14/11/2018
2. Vehicle Particulars & Condition			
Make & Model	MINI ONE 1.4 AT	c.c	1397
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WMWME32010TM76349	Colour	YELLOW
Odometer	57847	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/65 R15	KUMHO	6 mm
L/H Front Tyre	175/65 R15	KUMHO	6 mm
R/H Rear Tyre	175/65 R15	KUMHO	6 mm
L/H Rear Tyre	175/65 R15	KUMHO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/11/2018	Inspection Date	15/11/2018
Survey held at	27A TANJONG PENJURU		
Repairer	TRANS EUROKARS PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCM 6525J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BUCKLED	1,185.56	1,185.56
3	TAILGATE CLIPS	NECESSARY	13.14	13.14
4	PLUG IN NUT	NECESSARY	7.76	7.76
1	REAR WINDSCREEN TOP MOULDING	NECESSARY	40.13	40.13
1	REAR WINDSCREEN LOWER MOULDING INSERT	NECESSARY	40.13	40.13
1	REAR WINDSCREEN LOWER MOULDING CHROM	NECESSARY	124.00	124.00
5	CLIP	NECESSARY	7.80	7.80
2	REAR WINDSCREEN TOP MOULDING	NECESSARY	26.88	26.88
1	REAR EMBLEM "MINI"	NECESSARY	75.69	75.69
1	EMBLEM "ONE"	NECESSARY	68.13	68.13
1	TAILGATE GARNISH CHROME	CRACKED	208.25	208.25
4	PLASTIC SCREW	NECESSARY	13.76	13.76
1	TAILGATE GARNISH GASKET	NECESSARY	26.13	26.13
1	REAR BUMPER	DEFORMED	803.56	803.56
1	TOW COVER	CUT	38.94	38.94
1	REAR BUMPER RAIL GUIDE	NECESSARY	34.19	34.19
1	REAR BUMPER BRACKET	NECESSARY	25.13	25.13
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	22.81	22.81
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	22.81	22.81
1	REAR BUMPER BREATHER	NOT NECESSARY	49.19	-
10	EXPANDING NUT	NECESSARY	19.40	19.40
10	RIVET	NECESSARY	23.10	23.10
2	EXPANDING RIVET	NECESSARY	2.76	2.76
1	REAR BUMPER LOWER SPOILER	DEFORMED	155.06	155.06
1	FOG LAMP TRIM	SCRATCHED	46.56	46.56
2	LOWER SPOILER EXPANDING RIVET	NECESSARY	3.00	3.00
1	REAR BUMPER REINFORCEMENT	BENT	462.00	462.00
1	REINFORCEMENT FOAM	CRACKED	48.56	48.56
1	TAILGATE TRIM PANEL	CRACKED	307.63	307.63
2	TRIM PANEL CLIP	NECESSARY	6.00	6.00
2	TRIM PANEL SLEEVE	NECESSARY	9.76	9.76

Report Ref No. CS/GAI18020580/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	EXPANDING NUT	NECESSARY	1.38	1.38
1	REAR FOG LAMP	CRACKED	159.38	159.38
1	TAIL LAMP TRIM LH (NOT NECESSARY)	NOT CONSISTENT WITH THE IMPACT	90.69	-
1	TAIL LAMP TRIM RH (NOT NECESSARY)	NOT CONSISTENT WITH THE IMPACT	90.69	-
1	SENSOR SOCKER HOUSING	NECESSARY	6.94	6.94
2	SENSOR PARKASSIST	NOT WORKING-1PC ONLY	592.12	296.06
2	SENSOR GASKET	NECESSARY	12.62	12.62
1	MUFFLER INSULATION	BENT	254.75	254.75
1	TAIL PIPE CHROME	SERVICEABLE	106.13	-
2	NUMBER PLATE LIGHTS	CRACKED	29.26	29.26
2	PLUG-IN NUT	NECESSARY	1.50	1.50
			5,263.28	4,630.52
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE WITH CASING (SN)	BENT	70.00	70.00
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
			170.00	120.00
	<u>LABOUR</u>			
	TO REMOVE / REPLACE TAILGATE, REAR BUMPER & TO REPAIR LH REAR FENDER, RH REAR FENDER & REAR END PANEL AREAS AFFECTED BY THE ACCIDENT.		2,700.00	2,520.00
	TO RESPRAY TAILGATE, REAR BUMPER, LH REAR FENDER, RH REAR FENDER & REAR END PANEL.		4,300.00	2,400.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO TRANSFER THE TAILGATE MECHANISM.		500.00	420.00
	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.		560.00	560.00
	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.		120.00	120.00
	TO TRANSFER THE REVERSE SENSORS.		500.00	420.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	250.00
			9,530.00	6,990.00
GRAND TOTAL			14,963.28	11,740.52
RECOMMENDED COST OF REPAIRS				11,740.52

Report Ref No. CS/GAI18020580/R1sd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.