

ASS. REC. BY:

REF:

CS/TMI18020582/Ktd3m

Special Instruction:

Surveyor:  
Munmen

Kenneth

ASSIGNMENT (Office)

From (Person): Fiona Gan Bee Song

of

TMI

Date/Time: 14/11/18 @ 10:42am

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 3010 Z

Insured:

SLX 2397Z

at Workshop m/s

T &amp; B Motor Repairs

Tel:

6458 0296

of

Blk 20 # 01-28 Sin Ming Rd

Policy No:

MJ 000597

Claim No:

M1805768

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 10/11/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 11:03am @ 14/11/18

Person Contacted:

Judy

Vehicle ☒ IN / ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	Insp: 160 Sin Ming Drive #08-03
	SLB 3010Z-X
	SLX 2397Z-X
6/12	\$4614.24 enal & confirm (Red: 3513.22 :43%)

ASS. REC. BY:

REF:

TM1/

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop mv/s \_\_\_\_\_ T &amp; B

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4-6 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLB 30107 Yr Regn: 03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1491

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 75963 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU1 1113333

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/R/m / STD A/R/m or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. 2 mm L/Bal. 2 mm

D.O.A. 10/11/18 D.O.I. 14/11/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/11 File pass to Catherine

RECEIVED 07 DEC 2018

Date/Time, File Pass to?

1) 6/12/18

Date/Time, File Return to?

2)

☐: Prell. Report☐: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech Invs (\$☐: Weekend (\$

Survey Fee

Transportation:

S - RS - SI

Fixings

Others

TOTAL

Report Format: TP

Lump Sum / J.B.I. (\$ 4614.24)

350

10

360

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2018		14 Nov 2018 10:42 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHAN SUN WEI ALVIN, ID: S8737100Z			
Main Claimant:	KOH KIM LENG, ID: S7330616G			
Vehicle Reg. No.:	SLB3010Z	Date of Loss:	10/11/2018 10:00 - :59	
Claim Type:	TP / M1805768	Policy/Cover Note No.:	MJ000597 (Comprehensive) Coverage: 03/05/2018 - 02/05/2019	
Vehicle Reg. No. (Insured):	SLX2397Z	Policy No. (Claimant):	D18MTPV01004219	
		Excess:	S\$2,000.00	
Repairer:	T & B Motor Repairs Services Pte Ltd (HQ) Blk 20, #01-28, Sin Ming Road, 575678 Sin Ming - Tel: 64546958/64580296			
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]			
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/11/2018]			
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE & PARTS PRICE. ** DO NOT SEND REQUESTED SURVEYOR. THKS			
Claimant's Solicitor:	CHEONGHOH LAW CORPORATION - Tel: 63378700			

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Too Joon Hwa

---

**From:** Too Joon Hwa  
**Sent:** Wednesday, 14 November, 2018 10:41 AM  
**To:** 'Cheong Hoh Lee'  
**Subject:** RE: M1805768-FG - RE: Notice of Accident - Traffic accident involving SLB 3010 Z and SLX 2397 Z (your insured) on 10 November 2018 at/along Ang Mo Kio Ave 3 Towards the CTE ; Our ref: LCH.my/SMTB-81030.18

Hi Melody

Without Prejudice

We have assign LKK Auto Consultants Pte Ltd to conduct the PRS.

Thanks.

### Shirley Too

Administrative Assistant, Motor Claims

Tokio Marine Insurance Singapore Ltd.  
20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046  
T (65) 6592 6409 | F (65) 6221 2101 |  
E shirleytoo@tokiomarine.com.sg | W www.tokiomarine.com

---

A member of the  
Tokio Marine Group

Please note that all personal information provided to Tokio Marine Insurance Singapore Ltd. is subject to the Personal Data Protection Policy Statement posted at [www.tokiomarine.com](http://www.tokiomarine.com).

---

**From:** Cheong Hoh Lee [mailto:mail@cheonghoh.sg]  
**Sent:** Tuesday, 13 November, 2018 6:02 PM  
**To:** Too Joon Hwa <shirleytoo@tokiomarine.com.sg>  
**Subject:** Re: M1805768-FG - RE: Notice of Accident - Traffic accident involving SLB 3010 Z and SLX 2397 Z (your insured) on 10 November 2018 at/along Ang Mo Kio Ave 3 Towards the CTE ; Our ref: LCH.my/SMTB-81030.18

Dear Sir/ Madam,

We refer to your email of even date.

Our client hereby nominate Mr Kenneth Kong of LKK Auto Consultants Pte Ltd to conduct the pre-repair survey of the damages to our client's vehicle SLB 3010 Z arising out of the above mentioned accident.

Kindly inform Mr Kenneth Kong of LKK Auto Consultants Pte Ltd to contact Mr Tay at 6458 0296 from T & B Motor Repairs Services Pte Ltd, Blk 160 Sin Ming Drive #08-03 Sin Ming Auto City Singapore 575722 for the said arrangement on an urgent basis.

Regards,  
Melody  
Cheonghoh Law Corporation  
Blk 53 Chin Swee Road #03-05  
Singapore 160053  
Tel: 6337 8700  
Fax: 6337 3700

On Nov 13, 2018, at 12:25 PM, Too Joon Hwa <[shirleytoo@tokiomarine.com.sg](mailto:shirleytoo@tokiomarine.com.sg)> wrote:

Hi Melody

Without Prejudice

See below:

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO : SLB3010Z  
TMiS VEHICLE NO. : SLX2397Z  
DATE OF LOSS : 10.11.18

We refer to your Notice of Accident dated 12.11.18.

Please provide workshop info. We are not liable for any delay in the PRS if information not provided.

We intend to conduct a Pre-Repair Survey of the damage to your client's/your customer's vehicle and propose to use one of the motor surveyors named in the list below, as a single joint expert.

**List of our motor surveyors**

- LKK Auto Consultants Pte Ltd
- FormTeam Consultancy Pte Ltd
- STA Inspection Pte Ltd
- Kelvin Automotive Appraising Services
- Appraisal Associates Pte Ltd
- HM Automotive Appraisal Services
- Koays Accident Reconstruction Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one or more of the listed motor surveyors.

Please reply either by fax (6221 2101) or by email ([shirleytoo@tokiomarine.com.sg](mailto:shirleytoo@tokiomarine.com.sg)).

We are not liable for any delay caused, if otherwise. Thank you.  
Regards,

**Shirley Too**

Administrative Assistant, Motor Claims

Tokio Marine Insurance Singapore Ltd.

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

T (65) 6592 6409 | F (65) 6221 2101 |

E [shirleytoo@tokiomarine.com.sg](mailto:shirleytoo@tokiomarine.com.sg) | W [www.tokiomarine.com](http://www.tokiomarine.com)

<image001.jpg>

A member of the  
Tokio Marine Group

Please note that all personal information provided to Tokio Marine Insurance Singapore Ltd. is subject  
to the Personal Data Protection Policy Statement posted at [www.tokiomarine.com](http://www.tokiomarine.com).

---

**From:** Cheong Hoh Lee [<mailto:mail@cheonghoh.sg>]

**Sent:** Monday, 12 November, 2018 6:40 PM

**To:** Zheng Hanyang <[Hanyang@tokiomarine.com.sg](mailto:Hanyang@tokiomarine.com.sg)>; Too Joon Hwa

<[shirleytoo@tokiomarine.com.sg](mailto:shirleytoo@tokiomarine.com.sg)>

**Subject:** Notice of Accident - Traffic accident involving SLB 3010 Z and SLX 2397 Z (your insured) on  
10 November 2018 at/along Ang Mo Kio Ave 3 Towards the CTE ; Our ref: LCH.my/SMTB-81030.18

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Regards,

Melody

Cheonghoh Law Corporation

Blk 53 Chin Swee Road #03-05

Singapore 160053

Tel: 6337 8700

Fax: 6337 3700

This message contains confidential information and is intended only for the addressee named. If  
you are not the named addressee (or authorised to receive for the addressee) you must not  
disseminate, distribute or copy this email. Please notify the sender immediately by e-mail if you  
have received this e-mail by mistake and delete this e-mail from your system.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/11/2018 16:09
Date Of Accident	10/11/2018 10:50
Exact Location Of Accident	ALONG ANG MO KIO AVE 3 TOWARDS CTE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB3010Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KOH KIM LENG
NRIC No	S7330616G
Email Address	KOHL@STENG.COM
Mobile Phone No	(LOCAL) +65-92477477
Alternative Phone No	OTHERS-92477477

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01004219
Cover Note Number	

### Driver

Name of Driver	KOH KIM LENG
NRIC No	S7330616G
Date Of Birth	28/08/1973
Occupation	INDOOR
Date Of Driving Pass	07/01/1997
Driving Experience	21 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92477477
Fax Number	
Contact Number	OTHERS-92477477
EMail Address	KOHL@STENG.COM

Address	BLK 613 HOUGANG AVENUE 8 #05-430
Postcode	530613
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX2397Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN SUN WEI ALVIN
NRIC/Passport Number	S8737100Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

12 NOV 2018

06:09h

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Poh Kwee Choo

NRIC/FIN No.: S6840583A

CH PLAN

A SLB3010Z

B SLX2397Z



C.T.E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10 Nov 2018 (Sat) at around 1050hrs  
 I (driver of veh A) was driving along  
 Ang Mo Kio Ave 3 heading toward ramp onto  
 CTE (town direction). After I <sup>drove</sup> passed the  
 bus stop, there were many cars filtering  
 to enter the ramp. As my car joined in  
 to filter towards the ramp onto CTE (City Direction)  
 Veh B hit my car (veh A) at the rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 10 Nov 2018

Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name: Poh Kwee Choo  
 NRIC/FIN No.: S6840583A

# T & B MOTOR REPAIRS SERVICES PTE LTD

Page 1 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

KOH KIM LENG

BLK 613 HOUGANG AVENUE 8 #05-430

SINGAPORE 530613

Attention : Motor Claim Department

Estimate : ES003331

Date : 12/11/2018

Vehicle Num. : SLB3010Z

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 10/11/2018

Claim No. :

Reference :

Policy No. : D18MTPV01004219

*Not Authorized  
Resurvey By PAINT  
4-5 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- LIST ITEMS :
1. 1 REAR BOOT COVER
  2. 1 REAR BOOT COVER NUMBER PLATE GARNISH
  3. 1 REAR BOOT COVER STAY LH
  4. 1 REAR BOOT COVER STAY RH
  5. 1 REAR BOOT COVER REFLECTOR LH
  6. 1 REAR BOOT COVER REFLECTOR RH
  7. 1 REAR BOOT INNER LOCK
  8. 1 REAR BOOT COVER NUMBER PLATE LAMP L/H
  9. 1 REAR BOOT COVER NUMBER PLATE LAMP R/H
  10. 1 REAR BOOT COVER STOPPER LH
  11. 1 REAR BOOT COVER STOPPER RH
  12. 1 REAR BUMPER
  13. 1 REAR BUMPER SIDE RETAINER LH
  14. 1 REAR BUMPER SIDE RETAINER RH
  15. 1 REAR END PANEL

List Total S\$ :

20.00% Discount S\$ :

Bu	1,048.90	✓
SL	1,078.00	X
SL	198.00	X
SL	198.00	X
SL	264.00	X
SL	264.00	A
SL	198.00	?
SL	38.50	X
SL	38.50	X
SL	22.00	X
SL	22.00	X
Bu	849.30	✓
SL	17.50	X
SL	17.50	X
	365.70	?
	4,619.90	
	923.98	
	3,695.92	

- NETT ITEMS :
1. 1 REAR BOOT COVER WINDSCREEN SEALANT
  2. 1 SET REAR BUMPER CLIPS
  3. 1 REAR BOOT COVER HONDA EMBLEM
  4. 1 REAR BOOT COVER VEZEL EMBLEM

Nett Total S\$ :

LABOUR :

1. REMOVE & REFIX REAR BOOT WINDSCREEN GLASS

SL	120.00	40% ✓
SL	80.00	50% ✓
SL	31.00	X
SL	43.00	✓
	274.00	
	160.00	12% ✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

# T & B MOTOR REPAIRS SERVICES PTE LTD

Page 2 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : [tbmotor@hotmail.sg](mailto:tbmotor@hotmail.sg)

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

KOH KIM LENG

BLK 613 HOUGANG AVENUE 8 #05-430

SINGAPORE 530613

Attention : Motor Claim Department

Estimate : ES003331

Date : 12/11/2018

Vehicle Num. : SLB3010Z

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 10/11/2018

Claim No. :

Reference :

Policy No. : D18MTPV01004219


S/N	Quantity	Particular	Unit Price	Amount S\$
				401
		2. REMOVE & REFIX REAR BOOT COVER VIDEO CAMERA	80.00	80.00
		3. REMOVE & REFIX REAR BOOT COVER REVERSE CAMERA	80.00	80.00 501
		4. SUPPLY & INSTALL ONE SET OF NEW REAR BUMPER REVERSE SENSOR	320.00	7
		5. CHECK & REPAIR WIRING	80.00	201
		6. SPRAY PAINT ANTI-RUST COATING	180.00	7
		7. SPRAY PAINT ON AFFECTED PORTIONS	1,250.00	4501
		8. LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING, WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE	1,200.00	7
		Labour Total S\$ :		3,350.00

SingDollars : Seven Thousand Three Hundred Nineteen & Cents Ninety-Two Only

E. & O.E.

Total S\$ : 7,319.92

=====

  
for T & B MOTOR REPAIRS SERVICES PTE LTD

# T & B MOTOR REPAIRS SERVICES PTE LTD

Page 1 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

KOH KIM LENG

BLK 613 HOUGANG AVENUE 8 #05-430

SINGAPORE 530613

Attention : Motor Claim Department

Estimate : ES003331

Date : 12/11/2018

Vehicle Num. : SLB3010Z

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 10/11/2018

Claim No. :

Reference :

Policy No. : D18MTPV01004219

Not Authorized  
Resurvey B4 panel  
\$4614.24 6 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

## LIST ITEMS :

- |     |   |                                       |
|-----|---|---------------------------------------|
| 1.  | 1 | REAR BOOT COVER                       |
| 2.  | 1 | REAR BOOT COVER NUMBER PLATE GARNISH  |
| 3.  | 1 | REAR BOOT COVER STAY LH               |
| 4.  | 1 | REAR BOOT COVER STAY RH               |
| 5.  | 1 | REAR BOOT COVER REFLECTOR LH          |
| 6.  | 1 | REAR BOOT COVER REFLECTOR RH          |
| 7.  | 1 | REAR BOOT INNER LOCK                  |
| 8.  | 1 | REAR BOOT COVER NUMBER PLATE LAMP L/H |
| 9.  | 1 | REAR BOOT COVER NUMBER PLATE LAMP R/H |
| 10. | 1 | REAR BOOT COVER STOPPER LH            |
| 11. | 1 | REAR BOOT COVER STOPPER RH            |
| 12. | 1 | REAR BUMPER                           |
| 13. | 1 | REAR BUMPER SIDE RETAINER LH          |
| 14. | 1 | REAR BUMPER SIDE RETAINER RH          |
| 15. | 1 | REAR END PANEL                        |

List Total S\$ :

20.00% Discount S\$ :

Bt	1,048.90	✓
sn	1,078.00	X
sn	198.00	X
sn	198.00	X
sn	264.00	X
sn	264.00	X
sd	198.00	✓
sn	38.50	X
sn	38.50	X
sn	22.00	X
sn	22.00	X
Bu	849.30	✓
car	17.50	X
cm	17.50	X
Bt	415.60	✓
	4,669.80	
	933.96	
	3,735.84	

## NETT ITEMS :

- |     |       |                                    |
|-----|-------|------------------------------------|
| 1.  | 1     | REAR BOOT COVER WINDSCREEN SEALANT |
| 2.  | 1 SET | REAR BUMPER CLIPS                  |
| 3.  | 1     | REAR BOOT COVER HONDA EMBLEM       |
| 4.  | 1     | REAR BOOT COVER VEZEL EMBLEM       |
| *5. | 1     | REAR BUZZER                        |

Nett Total S\$ :

sn	120.00	40sn
sn	80.00	50sn
sn	31.00	X
sn	43.00	✓
cm	95.00	✓
	369.00	

CONTINUE / ...

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# T & B MOTOR REPAIRS SERVICES PTE LTD

Page 2 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

KOH KIM LENG

BLK 613 HOUGANG AVENUE 8 #05-430  
SINGAPORE 530613

Attention : Motor Claim Department

Estimate : ES003331

Date : 12/11/2018

Vehicle Num. : SLB3010Z

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 10/11/2018

Claim No. :

Reference :

Policy No. : D18MTPV01004219

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

## LABOUR :

1. REMOVE & REFIX REAR BOOT WINDSCREEN GLASS
2. REMOVE & REFIX REAR BOOT COVER VIDEO CAMERA
3. REMOVE & REFIX REAR BOOT COVER REVERSE CAMERA
4. SUPPLY & INSTALL ONE SET OF NEW REAR BUMPER REVERSE SENSOR
5. CHECK & REPAIR WIRING
6. SPRAY PAINT ANTI-RUST COATING
7. SPRAY PAINT ON AFFECTED PORTIONS
- \* 8. LABOUR CHARGE FOR REPAIRING, REMOVE REAR END PANEL AND PULL FLOORBOARD, ADJUSTING, KNOCKING AND WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE

Labour Total S\$ :

160.00	1201
80.00	401
80.00	501
320.00	2005n
80.00	201
180.00	601
1,250.00	6601
1,200.00	7001

3,350.00

SingDollars : Seven Thousand Four Hundred Fifty-Four & Cents Eighty-Four Only

8153.64

E. & O.E.

Total S\$ : 7,454.84

=====

for T & B MOTOR REPAIRS SERVICES PTE LTD

# T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

KOH KIM LENG

BLK 613 HOUGANG AVENUE 8 #05-430

SINGAPORE 530613

Attention : Motor Claim Department

Supplementary Estimate : ES003332

Date : 12/11/2018

Vehicle Num. : SLB3010Z

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 10/11/2018

Claim No. :

Reference :

Policy No. : D18MTPV01004219

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	4	REAR BOOT COVER WINDSCREEN GLASS MOULDING	35.00	140.00 ✓
2.	1	REAR BOOT WEATHERSTRIP		148.50 ✓
3.	1	REAR FLOOR UNDER BASE COVER		195.00 ✓
4.	4	REAR FLOOR UNDER BASE COVER CLIPS	10.00	40.00 ✓
List Total S\$ :				528.50
25.00% Discount S\$ :				130.88
30				392.62
LABOUR :				
REMOVE & STRIAGHTEN THE TAIL PIPE EXHAUST SLIENCER BOX				280.00 80/
Labour Total S\$ :				280.00

SingDollars : Six Hundred Seventy-Two & Cents Sixty-Two Only

E. & O.E.

Total S\$ :

672.62

=====

  
for T & B MOTOR REPAIRS SERVICES PTE LTD

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI18020582/KTD3N2

Date: 13/12/2018

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ000597
Claimant Vehicle No :	SLB3010Z	Insured Vehicle No :	SLX2397Z
Date of Loss:	10/11/2018	Nature of Claim:	TP
		Claim No:	M1805768

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLB3010Z	Engine No:	L15B4033338
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11113333
Reg. Date:	31/03/2016 (Man. Year: 2015)	Odometer:	75963 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 2 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Dunlop 2 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,843.64	2,884.24	1,959.40	40.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	1,730.00	1,580.00	47.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>8,153.64</b>	<b>4,614.24</b>	<b>3,539.40</b>	<b>43.41</b>

## INSPECTION

Date of Assignment:	14/11/2018	
Date Inspected:	14/11/2018	Inspected At: 160 SIN MING DRIVE#08-03 REPAIRER: T & B MOTOR REPAIRS SERVICES PTE LTD BLK 20 SIN MING ROAD #01-28 SINGAPORE 575678

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2018)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLB3010Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Bent	1,048.90 FL	*1,048.90 FL
2	1		*REAR BOOT COVER NUMBER PLATE GARNISH	Serviceable	1,078.00 FL	*- FL
3	1		*REAR BOOT COVER STAY LH	Serviceable	198.00 FL	*- FL
4	1		*REAR BOOT COVER STAY RH	Serviceable	198.00 FL	*- FL
5	1		*REAR BOOT COVER REFLECTOR LH	Serviceable	264.00 FL	*- FL
6	1		*REAR BOOT COVER REFLECTOR RH	Serviceable	264.00 FL	*- FL
7	1		*REAR BOOT INNER LOCK	Dented	198.00 FL	*198.00 FL
8	1		*REAR BOOT COVER NUMBER PLATE LAMP L/H	Serviceable	38.50 FL	*- FL
9	1		*REAR BOOT COVER NUMBER PLATE LAMP R/H	Serviceable	38.50 FL	*- FL
10	1		*REAR BOOT COVER STOPPER LH	Serviceable	22.00 FL	*- FL
11	1		*REAR BOOT COVER STOPPER RH	Serviceable	22.00 FL	*- FL
12	1		*REAR BUMPER	Buckled	849.30 FL	*849.30 FL
13	1		*REAR BUMPER SIDE RETAINER LH	Cracked	17.50 FL	*17.50 FL
14	1		*REAR BUMPER SIDE RETAINER RH	Cracked	17.50 FL	*17.50 FL
15	1		*REAR END PANEL	Bent	415.60 FL	*415.60 FL
16	4		*REAR BOOT COVER WINDSCREEN GLASS MOULDING	Necessary	140.00 FL	*140.00 FL
17	1		*REAR BOOT WEATHERSTRIP	Dented/Distorted	148.50 FL	*148.50 FL
18	1		*REAR FLOOR UNDER BASE COVER	Buckled	195.00 FL	*195.00 FL
19	4		*REAR FLOOR UNDER BASE COVER CLIPS	Necessary	40.00 FL	*40.00 FL
20	1		*REAR BOOT COVER WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
21	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
22	1		*REAR BOOT COVER HONDA EMBLEM	Not Necessary	31.00 FS	*- FS
23	1		*REAR BOOT COVER VEZEL EMBLEM	Necessary	43.00 FS	*43.00 FS
24	1		*REAR BUZZER	Cracked	95.00 FS	*95.00 FS
25	1		*REAR BUMPER REVERSE SENSOR	Shorted	320.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,882.30</b>	<b>3,498.30</b>
- List Item Discount on L Items 20.00/20.00% (S\$)	1,038.66	614.06
<b>Total Parts (S\$)</b>	<b>4,843.64</b>	<b>2,884.24</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR BOOT WINDSCREEN GLASS	New	160.00	120.00
2	REMOVE & REFIX REAR BOOT COVER VIDEO CAMERA	New	80.00	40.00
3	REMOVE & REFIX REAR BOOT COVER REVERSE CAMERA	New	80.00	50.00
4	CHECK & REPAIR WIRING	New	80.00	20.00
5	SPRAY PAINT ANTI-RUST COATING	New	180.00	60.00
6	SPRAY PAINT ON AFFECTED PORTIONS	New	1,250.00	660.00
7	LABOUR CHARGE FOR REPAIRING,REMOVE REAR END PANEL AND PULL FLOORBOARD,ADJUSTING,KNOCKING AND WELDING THE DAMAGED PARTS,STRAIGHTEN THE ABOVE	New	1,200.00	700.00
8	REMOVE & STRAIGHTEN THE TAIL PIPE EXHAUST SILENCER BOX	New	280.00	80.00
Gross Labour Cost (S\$)			3,310.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >