

REF: NAZ

REF: NS/INC 18030585 / Ngbn2

TAX/11/18/2022

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: GQ 8343K

Policy No. 5090039049-01 50518-140519

Claims No. MT/1018818-03

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 86 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHB 996X Yr Regn: 7 FEB 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIMA C.G. 1798

Colour: MAROON A/C: Insured / Std / NI / NA

Sp. Reading: 447,377 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKN36U005720746

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ACHILLES (CF), PALKEN (CR)

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 5/11/18 U.O.I. 2/11/18

Survey held at S.MRT WOODLAND

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REAR SENSORS working.

SHB 996X - NS/INC15012436 / Ngbn2

GQ 8343K - X

NAZ finalised LS \$3550, 6 days (red \$10422.60, 75%)

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

☐ : Preli Report

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / L.B.I. (\$) 3550

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) S + RS SI

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$)

TOTAL

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate
1	MT/1018818-003	SMRT TAXIS PTE LTD	SHB 996X	GQ 8343K	05/11/2018	\$ 13,972.60
2	MT/1024768-002	CITYCAB PTE LTD	SHA 9592Z	SKA 5169D	19/12/2018	\$ 2,273.54
3	MT/1024650-002	COMFORT TRANSPORTATION PTE LTD	SHD 3102D	SIQ 7181G	19/12/2018	\$ 4,301.92
4	MT/1025318-002	COMFORT TRANSPORTATION PTE LTD	SH 8356D	SMC 3831D	26/12/2018	\$ 1,868.80
5	MT/1025432-002	COMFORT TRANSPORTATION PTE LTD	SHA 3267C	SGU 5180L	26/12/2018	\$ 6,430.12
6	MT/1027231-001	COMFORT TRANSPORTATION PTE LTD	SHC 8082A	SIN 5816M	21/12/2018	\$ 4,226.00
7	MT/1011204-002	SMRT TAXIS PTE LTD	SHB 360E	PC 5013A	11/09/2018	\$ 9,044.20

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5090039049-01		ASK M&E PTE. LTD.	200815981K	GCV	Third Party, Fire & Theft	GQ8343K	GQ8343K	15/05/2018	14/05/2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/11/2018 16:18
Date Of Accident	05/11/2018 14:40
Exact Location Of Accident	WOODLANDS AVE 7 JUNCTION WOODLANDS STREET 83
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB996X
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	KOK MAW CHEONG
NRIC No	S1632338A
Date Of Birth	14/06/1964
Occupation	OUTDOOR
Date Of Driving Pass	19/06/1984
Driving Experience	34 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 148

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG AT THE SECOND LEFT LANE OF WOODLANDS AVE 7 TO GIVE WAY TO THE BUS FROM THE LEFT MOST LANE AS THERE WAS A STATIONARY POLICE CAR IN FRONT OF THE BUS. WHILE STATIONARY, SUDDENLY I FELT AN IMPACT FROM BEHIND. THE VEHICLE GQ8343K FROM BEHIND WHILE TRYING TO SWERVE OUT TO THE RIGHT HAD COLLIDED ONTO MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GQ8343K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 5/11/2010

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



dy

5/11/2018

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB996X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5936008
Chassis No.:	JTDKN36U005720746
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	07 Feb 2014
First Registration Date:	07 Feb 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Feb 2022
PARF Rebate Amount:	\$6,276.00
Intended COE Rebate Details	
COE Expiry Date:	06 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$58,590.00
COE Rebate Amount:	\$22,515.00
Total Rebate Amount:	\$28,791.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Jan 2019

OK



Case Details

Case Reference Number : TAX11/18/2022

Type of Repair : Accident Repair

Vehicle Registration Number : SHB996X

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-4421-10

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 05/11/2018 06:40 AM

Vehicle Age (in Months) : 57

Documents / Photographs

View Documents / Photographs

Total Documents : 1

Estimation Details

Source Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	456.80	456.80	25.00	343.86	Replace	1	343.86	Replace * / CEC
One Time Key In	Main			BUMPER SIDE RETAINER R/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER SIDE RETAINER R/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check * ? X SVC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check * ? X SVC
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give * X SVC
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check * ? X SVC
One Time Key In	Main			BUMPER LIP COVER R/LH	1	72.20	72.20	25.00	54.18	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER LIP COVER R/RH	1	116.10	116.10	25.00	88.57	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give * X SVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give * X SVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace * / NEC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check * ? X SVC
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair * X R
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give * X NV
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give * X NV
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give * X NV
One Time Key In	Main			SEALANT W/SCREEN	3	27.00	111.00	0.00	111.00	Replace	0	0	Not Give * X NV
One Time Key In	Main			NAME PLATE (HYBRID)	1	91.90	91.90	25.00	68.92	Replace	1	38.92	Replace * / NEC
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	506.90	506.90	25.00	379.67	Replace	1	0	Repair * X R
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.90	60.90	25.00	45.68	Replace	1	45.68	Replace * / NEC
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace * / NEC
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace * / NEC

Total Spare Part Cost 7,061.55

Lump Sum Discount (%) 25.00

Final Spare Part Cost 5,341.48

Surveyor Total 2,440.41

Lump Sum Dis (%) 20

Final Sur Total 1,992.33

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Approval		Repair/Replace
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dist(%)				Surveyor Final Price(\$)		
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60		Replace + NBL
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.23	Replace	1	45.23	45.23	Replace + NBL
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0		Not Give + XSVL
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.95	Replace	0	0		Not Give + XSVL
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	575.10		Replace + BFF
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80		Replace + NBL
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60		Replace + NBL
One Time Key In	Main			DUCT ASSY. QUARTER	1	70.40	70.40	0.00	70.40	Replace	0	0		Check + ?XSVL
One Time Key In	Main			QUARTER GLASS RR/RH	1	634.88	634.88	25.00	476.41	Replace	1	476.41		Replace + NBL
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00		Replace + NBL
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0		Not Give + XSVL
One Time Key In	Main			BUMPER SEAL RR RH	1	65.75	65.75	25.00	49.31	Replace	0	0		Not Give + XNN
One Time Key In	Main			SKID MEMBER PLATE RR/RH	1	57.30	57.30	25.00	43.13	Replace	0	0		Not Give + XSVL
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0		Check + ?XSVL
One Time Key In	Main			TAIL LAMP RH	1	502.02	502.02	10.00	451.82	Replace	1	451.82		Replace + CRL
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	35.70	35.70	25.00	26.78	Replace	0	0		Check + ?XSVL
One Time Key In	Main			PANEL ASSY. DECK RH	1	397.00	397.00	25.00	297.75	Replace	0	0		Not Give + XSVL
One Time Key In	Main			BATTERY	1	278.06	278.06	10.00	250.25	Replace	0	0		Not Give + XNN
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0		Not Give + XNN
Total Spare Part Cost												2,840.41		
Lump Sum Discount (%)												20		
Final Spare Part Cost												2,272.33		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION RH	1,014.00	600	
Total:		1,014.00	600.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY REAR BUMPER	378.00	200	
2	TO RESPRAY REAR PANEL	180.00	0	CHECK
3	TO RESPRAY TAIL GATE	378.00	200	
4	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
5	TO RESPRAY SPOILER	180.00	0	NN
Total:		1,896.00	700.00	

S.No.	Job Scope	SMRT Recommendation(S)	Surveyor Adjustment(S)	Remarks
6	TO RESPRAY REAR FENDER RH	378.00	200	
7	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	CHECK
Total:		1,864.00	700.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(S)	Surveyor Adjustment(S)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	60.00	30	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
4	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	NN
5	TO REMOVE / REFIT WINDSCREEN	120.00	0	NN
6	TO REMOVE / REFIT SEAT	120.00	0	NN
7	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	30	
8	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	0	NN
9	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	
10	TO WASH AND VACUUM	60.00	0	NN
11	TO REPLACE SUNDRY PARTS	100.00	0	NN
Total:		1,180.00	150.00	

Summary

	Estimator Assessment(S)	Surveyor Assessment(S)
Total Spare Part Detail	5,541.48	1,902.00
Total Labour Cost	1,014.00	800.00
Total Spray Painting	1,854.00	700.00
Other	1,180.00	150.00
Overall Total	9,589.48	3,402.00
Lump Sum Repair Option		
Lump Sum Total	9,700.00	3,400.00
Surveyor Approved Amount		3,400.00
No of Repair Days*	8	4
Remarks		LUMP SUM REPAIR 4 DAYS CHECK ITEMS PHOTOS AFTER REPAIR PHOTOS
Surveyor Name		Naz
Signature		

Survey Date

07/11/2018

NAZ LKK 7/11/18

LIS

4 DAYS

- CHECK ITEMS PHOTOS

- LUMP SUM REPAIR PHOTOS

https://vacswb.smrt.com.sg/Estimation.aspx

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHB996X
Case Reference Number	TAX/11/18/2022
Registration Date	07/02/14
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	KOK MAW CHEONG
Type of Accident	Head to Rear
Accident Date and Time	05/11/18 2:40 PM
Accident Reported Date and Time	05/11/18 4:22 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098628
Special Instruction to ARC, if any	TP
Prepared Date and Time	05/11/18 8:07 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



SC

Finalized.

Top View

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,464.00	\$800.00
Total Spray Cost	\$2,214.00	\$900.00
Total Spare Part Cost	\$7,206.12	\$2,594.72
Total Other Cost	\$1,180.00	(\$744.72)
TOTAL COST	\$12,064.12	\$3,550.00
Lump Sum Total	\$12,064.12	\$0.00
Number of Repair Days	8.0	6.0
Prepared / Adjusted By	Zhi Yang Phua	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	08/11/2018 8:23 AM	07/11/2018 5:03 PM
Signature		
Remarks	Initial = 6 days Request number of days to extend 2 days	
	LUMP SUM REPAIR. 4 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.	

- Naz

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1901-0093	Invoice Number	
Quotation Date	05.01.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$300.00	\$100.00
TO REPAIR THROUGH BACK DOOR	\$150.00	\$100.00
TO REPAIR REAR PORTION RH	\$1,014.00	\$600.00
Total Labour	\$1,464.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$100.00
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY SPOILER	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,214.00	\$900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO REMOVE / REFIT WINDSCREEN	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$894.72)
Total Other Costs	\$1,180.00	(\$744.72)



SMART Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 83685592
Estimator Telephone Number: 88662623
Accident Reporting Number: 88662672

Data Generated : 07/01/2019

User ID	BobSwar
---------	---------

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		56307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given
		75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given
		75575-47030	MOULDING BACK WINDOW, LOWER NO.1	0.00	\$29.40	0.00	\$0.00	Replace	Not Given
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	100.00	\$0.00	Replace	Repair
		75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace
		75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
			STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace
		75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace
		76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given
		67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Not Given
		61604-47090	FENDER RR/RH	1.00	\$766.80	25.00	\$575.10	Replace	Replace
			STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace
		62940-16060	DUCT ASSY, QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Check
		62710-47130	QUARTER GLASS RR/RH	1.00	\$846.50	25.00	\$634.88	Replace	Replace
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace
		65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given
		65631-47041	SILL MEMBER PLATE RR/RH	0.00	\$57.50	0.00	\$0.00	Replace	Not Given
		61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Check
		81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check
		64730-47031B2	PANEL ASSY, DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Not Given

8674.80

2,440.44

			BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Not Given	
		74481-47050	BATTERY CLAMP	0.00	\$16.10	0.00	\$0.00	Replace	Not Given	X
Total					\$8,908.90		\$2,440.44			X

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace	BT
Total					205.70		154.28			

49980

14032.60

2594.72
+ 800.00
+ 1050.00

4444.72

- 20%

3555.78

4s \$3550/-

CONFIRMED LUMP SUM REPAIR \$3550.00 / 6 DAYS

NAZUKK
H

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	704/11/18/2022	Date of Collection	8/11/18
Vehicle No	S17B 996X	Date of Request	8/11/18
Vehicle Model	70307A PRINS	Number of Days to Extend (If any)	2 DAYS

S/N	Part Number	Part Description	Quantity	Unit Price
	3765,66,69	Bumper Reinforcement Rear		\$205.70
	3767,68	To Repair End Panel		\$300.00 \$100
	3770,71	To Repair LH Tail Lamp Panel		\$150.00 \$100
		To Respray End Panel		\$180.00 \$100
		To Respray RH Tail Lamp Panel		\$180.00 \$100

<<<Please submit photographs for damaged parts>>>

I. (Name)

(Position)

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18020585/Nqbs2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 11-01-2019	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GQ 8343K	Veh. Inspected	SHB 996X	
Policy No.	5090039049-01	Coverage (\$)	0.00	
Claim No.	MT/1018818-003	Excess (\$)	0.00	
Assign From		Assign Date	07/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U005720746	Colour	MAROON	
Odometer	447377	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	ACHILLES	5 mm	
L/H Front Tyre	195/65R15	ACHILLES	5 mm	
R/H Rear Tyre	195/65R15	FALKEN	5 mm	
L/H Rear Tyre	195/65R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/11/2018	Inspection Date	07/11/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 996X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.93
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.23
1	FENDER RR/RH (DISC 25%)	DEFORMED	766.80	575.10
1	QUARTER GLASS RR/RH (DISC 25%)	NECESSARY	846.50	634.88
1	TAIL LAMP RH (DISC 10%)	CRACKED	557.80	502.02
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	BUMPER REINFORCEMENT REAR	REPEATED	205.70	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	AEM SUB-ASSY, RR BUMPER LH	SERVICEABLE	139.60	-
1	AEM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	END PANEL	SERVICEABLE	602.10	-
1	SPOILER REAR	SERVICEABLE	953.70	-
1	TAIL GATE DOOR WEATHER STRIP	SERVICEABLE	353.40	-
1	DUCT ASSY, QUARTER	SERVICEABLE	70.40	-
1	FENDER LINER RR/RH	SERVICEABLE	141.30	-
1	BUMPER SEAL, RR RH	SERVICEABLE	65.70	-
1	SILL MEMBER PLATE RR/RH	SERVICEABLE	57.50	-

Report Ref No. NS/INC18020585/Nqbs2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TROUGH, BACK DOOR	SERVICEABLE	110.90	-
1	TAIL LAMP BRACKET, RH	SERVICEABLE	30.70	-
1	PANEL ASSY, DECK RH	SERVICEABLE	307.00	-
1	BATTERY	SERVICEABLE	278.00	-
1	BATTERY CLAMP	SERVICEABLE	16.10	-
1	TAIL GATE DOOR GLASS MOULDING, LH	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING, RH	NOT NECESSARY	29.40	-
1	MOULDING BACK WINDOW, LOWER NO.1	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	TAILGATE ASY	TO REPAIR SEE LABOUR	1,007.90	-
1	TAILGATE OUTSIDE GARNISH	TO REPAIR SEE LABOUR	504.90	-
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
			9,174.60	2,594.72
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF TAILGATE ASY AND TAILGATE OUTSIDE GARNISH.		1,464.00	800.00
	SPRAY PAINT.		2,214.00	900.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	40.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO TRANSFER REAR TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO REMOVE / REFIT WINDSCREEN.	NOT NECESSARY	120.00	-
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS RH.		120.00	30.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			4,858.00	1,850.00

Report Ref No. NS/INC18020585/Nqbs2

GRAND TOTAL		14,032.60	4,444.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,550.00

Report Ref No. NS/INC18020585/Nqbs2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.