

Surveyor: NAZ

REF: NS/INCL18020597/NSber

TAx/11/18/2037

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SBW 1552Y

Policy No. 5092168785-01 330618-330619

Claims No. MT/1019140-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 1055E Yr Regn: 6 DEC 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS C.G. 1,798

Colour: MAROON A/C: Insured / Std / NI / NA

Sp. Reading: 368,394 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U605711-033

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FAKED

Front 6 mm Rear 5 mm

R/Bal. 6 mm L/Bal. 5 mm

D.O.A. 8/11/18 D.O.I. 12/11/18

Survey held at SMET WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

REAR

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

	REVERSE SEWERS WORKING	INC L/S
	SHB 1055E - C/S/MOI 8144047 / Rnd3m2	DATE: 28/12/18
	SBW 1552Y - C/CU IALG 16032883 / Kuc302	TA: 30/12/18
9/11/19	FINALIZED LUMP SUM REPAIR \$1400.00 / 3 DAYS	
10/01/19	Confirmed L/S \$1,400/- @ 3 days with NAZ	
	(\$1,918.20 Red - 58%)	

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

10/01/19

1) Typist

Date/Time, File Return to?

2) _____

☐ : Prelim Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format:

Lump Sum / I.B.I.: (\$ 1,400/- L/S)

160
160

eBaoTech

Hello, NAC_PAYA_UBI_800601

Change Language

Change Password

Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.

Date of Accident

08/11/2018 13:48

Vehicle No.(For Motor)

SBW1552Y

Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5092168785-01		YU YU CHIU	S2620538G	GPC	Third Party	SBW1552Y	SBW1552Y	23/06/2018	22/06/2019

Continue

TP Claims against NTUC Income: Follow-Through Survey

Date : 10/01/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1019140-002	SMRT TAXIS PTE LTD	SHB 1055E	SBW 1552Y	8/11/2018	17:05	\$ 3,318.20	\$ 1,400.00
2	MT/1027222-001	CITYCAB PTE LTD	SHC 733H	SMD 5434Z	21/12/2018	00.50	\$ 4,836.64	\$ 1,750.00
3								
4								

Claim received from LKK Auto

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
<YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 9 January 2019 11:02 AM
To: Naz (LKKAuto)
Cc: SUR; Shirley Hiew (LKK Auto)
Subject: RE: SHB 1055E Finalization

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Naz (LKKAuto) [mailto:Naz@lkkauto.com]
Sent: Wednesday, 9 January 2019 10:45 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Cc: SUR; Shirley Hiew (LKK Auto)
Subject: Re: SHB 1055E Finalization

Dear Ms Yeo,

Finalized Lump Sum Repair \$1400.00 / 3 Days.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 7 January 2019 4:53 PM
To: Naz (LKKAUTO)
Cc: SUR; CS A Team
Subject: SHB1055E

Hi Naz,

Attached herewith the repair estimate of SHB 1055E having Case No: TAX/11/18/2037.

There is no change to the approved amount of \$1,400 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Sent: Monday, 7 January 2019 4:46 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/11/2018 11:54
Date Of Accident	08/11/2018 17:05
Exact Location Of Accident	TPE SLE (BEFORE LOYANG EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1055E
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	LIM TECK HENG
NRIC No	S6934875J
Date Of Birth	10/10/1969
Occupation	OUTDOOR
Date Of Driving Pass	03/05/1988
Driving Experience	30 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG TPE TOWARDS SLE (BEFORE LOYANG EXIT). WHILST I WAS IN MY LANE I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SBW1552Y HAD COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBW1552Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YU YU CHIU
NRIC/Passport Number	S2620538G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LIM TECK HENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB1055E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

TPE towards SLE (Before Layang Ave Exit)


A-5HB1055E

B- SBW 15529

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

film.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

9/11/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Jim

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
9/11/2016

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number : TAX/11/18/2037

Type of Repair : Accident Repair

Vehicle Registration Number : SHB1055E

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-4462-ID

Assigned By : Kok Wah Wong

Insurance Company Name : NTUC Income Insurance

Co-operative Ltd

Accident Date and Time : 08/11/2018 09:05 AM

Vehicle Age(In Months) : 59

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace * CRK
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace * /NEC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check * ? X ✓ BT
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check * ? X ✓ BT
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give * 180 X ✓ BT
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace * /NEC
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give * X ✓
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give * X ✓
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check * ? X ✓
Total Spare Part Cost									1,246.35	Surveyor Total			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			
Final Spare Part Cost									997.08	Final Sur Total			

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH REAR PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
Total:		558.00	200.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	TO RESPRAY BUMPER BEAM	180.00	0	CHECK 100
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
2	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	20
3	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	NEC ✓
4	TO WASH AND VACUUM	60.00	0	NN X
Total:		556.88	316.88	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	997.08	380.62
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	556.88	316.88
Overall Total	2,449.96	1,097.70
Lump Sum Repair Option		
Lump Sum Total	2,450.00	1,100.00
Surveyor Approved Amount		1,100.00
No of Repair Days*	4	2
Remarks		LUMP SUM REPAIR. 2 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.
Surveyor Name		Naz
Signature		

Survey Date

12/11/2018

NAZ LKK
12/11/18
L/S
2 DAYS
CHECK ITEMS PHOTOS
AFTER REPAIR PHOTOS

[Signature]
16/11/18

Save Clear

3014.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/11/18/2037	Date of Collection	1 / 1
Vehicle No	SHB 1055 E	Date of Request	13/11/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (if any)	1

S/N	Part Number	Part Description	Quantity	Unit Price
		REAR BUMPER REINFORCEMENT Lm	1	BT
		ARM SUB ASSY REAR BUMPER RH Lm	1	BT
		REVERSE SENSOR	1 set	BR
	Labour	to SPRAY REAR BUMPER REINFORCEMENT		\$180

\$100

<<Please submit photographs for damaged parts>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
[to be signed in front of an authorised witness]



I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Section A - Accident Details

Registration Number	SHB1055E
Case Reference Number	TAX/11/18/2037
Registration Date	06/12/13
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LIM TECK HENG
Type of Accident	Head to Rear
Accident Date and Time	08/11/18 5:05 PM
Accident Reported Date and Time	09/11/18 10:27 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098654
Special Instruction to ARC, if any	DROVE IN/NTUC - LKK
Prepared Date and Time	10/11/18 9:58 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Left/Right Side

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$738.00	\$300.00
Total Spare Part Cost	\$1,685.32	\$915.01
Total Other Cost	\$556.88	(\$15.01)
TOTAL COST	\$3,318.20	\$1,400.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	12/11/2018 4:31 PM	12/11/2018 4:11 PM
Signature		
Remarks	REQUEST NUMBER OF DAYS TO EXTEND 1 DAY	LUMP SUM REPAIR. 2 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1901-0092	Invoice Number	
Quotation Date	05.01.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$738.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$331.89)
Total Other Costs	\$556.88	(\$15.01)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52023-12240	BUMPER REINFORCEME	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER	0.00	\$94.80	0.00	\$0.00	Replace	Check
Total					\$1,487.31		\$476.03		

CRK
NEC
SVC
SVC
SVC
NEC
SVC
SVC
SVC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMEN	1.00	\$205.70	25.00	\$154.28	Replace	Replace ✓
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
Total					525.30		438.98		

BT
BT
BR

915.01
+ 200.00
+ 616.88

1731.89
- 20%

1385.51

L/S \$1400/-

CONFIRMED LUMP SUM REPAIR \$1400.00 / 3 DAYS.

NAT LKC
H



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18020592/Nsbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 11-01-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBW 1552Y	Veh. Inspected	SHB 1055E	
Policy No.	5092168785-01	Coverage (\$)	0.00	
Claim No.	MT/1019140-002	Excess (\$)	0.00	
Assign From		Assign Date	12/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTDKN36U605711033	Colour	MAROON	
Odometer	368394	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	5 mm	
L/H Rear Tyre	195/65 R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/11/2018	Inspection Date	12/11/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1055E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	SENSOR REVERSE (SN)	BROKEN	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
			1,561.80	915.01
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK.		338.00	200.00
	SPRAY PAINT.		558.00	300.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.		296.88	296.88
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,452.88	816.88
	GRAND TOTAL		3,014.68	1,731.89
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,400.00

Report Ref No. NS/INC18020592/Nsbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.