

REF: NS/INC18020596/NSb02

REF: NS/INC18020596/NSb02

REF: NS/INC18020596/NSb02

TAX/11/18/2019

Surveyor: N/A 2

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SLV 2131

Policy No. 5096855127 26122017

Claims No. MT/1018594-002

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 46 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 5413 18135

Yr Regn: 2 DEC 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS

C.G. 1798

Colour: MAROON

A/C: Insured / Std / NI / NA

Sp. Reading: BATT FLAT.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKN364305753112

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or N FALKEN

Front

Rear

R/Bal. 6 mm

R/Bal. 5 mm

L/Bal. 6 mm

L/Bal. 5 mm

D.O.A. 5/11/18

D.O.I. 7/11/18

Survey held at S.M.P. WOODLAND

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SLV 2131 - NS/INC11008622 / RJ1

NA: 31032011

INC L/S

1313117 FINALIZED LUMP SUM REPAIR \$2600.00 / 6 DAYS

(\$5,599.75 Red - 69%)

RECEIVED 19 MAR 2019

Date/Time, File Pass to?

19/03/19

1) Typist

Date/Time, File Return to?

2)

☐ : Prelim Report

☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) \$ + RS \$

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ 2,600/- L/S)

160

160

14/3/2019



GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5096855127		HDT SINGAPORE HOLDING PTE LTD	201303684R	GFT	drivo PREMIUM	SLV2131J	SLV2131J	26/12/2017	

TP Claims against NTUC Income: Follow-Through Survey

Date : 14/03/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	Not Income Insured	COMFORT TRANSPORTATION PTE LTD	SHC 3795J	RD 6116B	1/2/2019	15:30	\$ 5,269.18	\$ 2,100.00
2	MT/1018594-002	SMRT TAXIS PTE LTD	SHB 1813J	SLV 2131J	5/11/2018	12:50	\$ 8,299.75	\$ 2,600.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/11/2018 13:32
Date Of Accident	05/11/2018 12:50
Exact Location Of Accident	CAR PARK IN FRONT BLK 26 MARSILING DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1813J
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	NG KIAN LYE
NRIC No	S1539270C
Date Of Birth	12/09/1962
Occupation	OUTDOOR
Date Of Driving Pass	28/07/1982
Driving Experience	36 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	13
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING STRAIGHT ALONG THE CAR PARK DRIVE WAY WHEN THE VEHICLE SLV2131J SUDDENLY DASHED OUT FROM THE PARKING LOT NO.43 AND COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV2131J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	BAY LEE LUNG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


[Signature] 5/11/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 5/11/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX 11/18/2019	Date of Collection	1 / 1
Vehicle No	SHB 1813 J	Date of Request	08/11/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (if any)	3 2

S/N	Part Number	Part Description	Quantity	Unit Price
		FRONT DOOR HINGE LH (upper)	1pc	BT
		FRONT DOOR HINGE LH (lower)	1pc	BT
		REAR DOOR HINGE LH (upper)	1pc	BT
		REAR DOOR HINGE LH (lower)	1pc	BT
	Labour	to REPAIR DOOR center pillar LH	1pc	\$ 200 \$ 100
	Labour	to SPRAY DOOR center pillar LH	1pc	\$ 200 \$ 100

<<<Please submit photographs for damaged parts>>>

I, (Name) _____
 (Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
 Signature of person making this declaration
 [to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



Case Details

Case Reference Number : TAX/11/18/2019
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1813J

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4423-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income
 Insurance Co-operative Ltd
 Accident Date and Time : 05/11/2018 04:50 AM
 Vehicle Age(In Months) : 47

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair * XR
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace * NEC
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	1	128.77	Replace * NEC
One Time Key In	Main			FENDER LINER PAD, FR WHEEL, LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Check * XSVL
One Time Key In	Main			WHEEL DISC, FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair * XR
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	670.80	Replace * DEF
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace * NEC
One Time Key In	Main			HINGE LOWER LHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Check * BT
One Time Key In	Main			HINGE UPPER LHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Check * BT
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check * XSVL
One Time Key In	Main			MOULDING BODY, LH	1	673.60	673.60	25.00	505.20	Replace	0	0	Not Give * XSVL
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair * XR
Total Spare Part Cost									4,564.66	Surveyor 958.49 Total			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20			
Final Spare Part Cost									3,651.73	Final Sur 766.79 Total			

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace * NBL
One Time Key In	Main			DOOR HINGE LOWER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Check * BT
One Time Key In	Main			DOOR HINGE UPPER RR/LH	1	81.70	81.70	25.00	61.28	Replace	0	0	Check * BT
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check * SVL
One Time Key In	Main			PILLAR, CTR BODY LH	1	307.70	307.70	25.00	230.77	Replace	0	0	Check * R
									Total Spare Part Cost		4,564.66	Surveyor Total	958.49
									Lump Sum Discount (%)		20.00	Lump Sum Dis (%)	20
									Final Spare Part Cost		3,651.73	Final Sur Total	766.79

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR LH PORTION	1,014.00	600	
Total:		1,014.00	600.00	

Spray Cost Detail


S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY FRONT FENDER LH	378.00	200	
2	TO RESPRAY RIM	180.00	80	
3	TO REPSRAY REAR DOOR LH	378.00	200	
4	TO RESPRAY CENTRE PILLAR LH	180.00	0	CHECK
5	TO RESPRAY FRONT DOOR LH	378.00	200	
6	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	NN
Total:		1,674.00	680.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
Total:		1,365.32	595.32	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	TO TRANSFER DOOR MECHANISM	240.00	50	
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	NN
6	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	445.32	445.32	NEC
7	TO REPLACE SUNDRY PARTS	100.00	0	NN
8	TO WASH AND VACUUM	60.00	0	NN
Total:		1,365.32	595.32	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,651.73	766.79
Total Labour Cost	1,014.00	600.00
Total Spray Painting	1,674.00	680.00
Other	1,365.32	595.32
Overall Total	7,705.05	2,642.11
Lump Sum Repair Option		✓
Lump Sum Total	7,700.00	2,650.00
Surveyor Approved Amount		2,650.00
No of Repair Days*	6	4
Remarks	-	LUMP SUM REPAIR. 4 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.
Surveyor Name		Naz
Signature		

Save

Clear

Survey Date

07/11/2018

NAZ LCC
 7/11/18
 LIS
 4 DAYS
 - CHECK ITEMS PHOTOS
 - AFTER REPAIR PHOTOS.

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company



Acknowledged by Reparer

Signature: _____

Date: _____



Section A - Accident Details

Registration Number	SHB1813J
Case Reference Number	TAX/11/18/2019
Registration Date	2/12/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	NG KIAN LYE
Type of Accident	Head To Side
Accident Date and Time	5/11/2018 12:50 PM
Accident Reported Date and Time	5/11/2018 1:34 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098622
Special Instruction to ARC, if any	TP
Prepared Date and Time	5/11/2018 8:43 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,214.00	\$700.00
Total Spray Cost	\$1,874.00	\$780.00
Total Spare Part Cost	\$3,846.43	\$1,201.90
Total Other Cost	\$1,365.32	(\$81.90)
TOTAL COST	\$8,299.75	\$2,600.00 (L/S)
Lump Sum Total	\$8,300.00	\$0.00
Number of Repair Days	9.0	6.0
Prepared / Adjusted By	Zhi Yang Phua	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	08/11/2018 8:38 AM	07/11/2018 5:26 PM
Signature		
Remarks	Initial estimates = 6 days Request number of days to extend 3 days LUMP SUM REPAIR. 4 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1903-0071	Invoice Number	
Quotation Date	05.03.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$600.00
TO REPAIR CENTRE PILLAR	\$200.00	\$100.00
Total Labour	\$1,214.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY CENTRE PILLAR LH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO REPSRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$80.00
TO RESPRAY CENTER PILLAR LH	\$200.00	\$100.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,874.00	\$780.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$400.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$445.32	\$445.32
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$50.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,365.32	\$595.32

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		68740-12120	HINGE LOWER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Check
		75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given
		53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace
		68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Check
		68780-52031	DOOR HINGE LOWER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check
		68760-20122	DOOR HINGE UPPER RR/LH	0.00	\$81.70	0.00	\$0.00	Replace	Check



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18020596/Nsbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 20-03-2019



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 2131J	Veh. Inspected	SHB 1813J
Policy No.	5096855127	Coverage (\$)	0.00
Claim No.	MT/1018594-002	Excess (\$)	0.00
Assign From		Assign Date	07/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U305753112	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/11/2018	Inspection Date	07/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1813J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FENDER LINER FRT / LH (DISC 25%)	NECESSARY	171.70	128.78
1	DOOR FRT / LH (DISC 25%)	DEFORMED	894.40	670.80
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	HINGE UPPER LHF, DOOR (DISC 25%)	BENT	80.50	60.38
1	DOOR HINGE LOWER RR / LH (DISC 25%)	BENT	72.20	54.15
1	HINGE LOWER LHF, DOOR (DISC 25%)	BENT	90.10	67.58
1	DOOR HINGE UPPER RR/LH (DISC 25%)	BENT	81.70	61.28
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	HINGE LOWER LHF, DOOR	SERVICEABLE	80.50	-
1	MOULDING BODY, LH	SERVICEABLE	673.60	-
1	HINGE UPPER LHF, DOOR	SERVICEABLE	80.50	-
1	DOOR HINGE LOWER RR / LH	SERVICEABLE	72.20	-
1	DOOR HINGE UPPER RR / LH	SERVICEABLE	81.70	-
1	CHECK ASSY, RR DOOR	SERVICEABLE	150.30	-
1	FENDER LINER PAD, FR WHEEL LH	SERVICEABLE	49.30	-
1	PILLAR, CTR BODY LH	SERVICEABLE	307.70	-
1	CHECK ASSY, FR DOOR	SERVICEABLE	150.30	-
1	FENDER FRT / LH	TO REPAIR SEE LABOUR	723.40	-
1	DOOR RR / LH	TO REPAIR SEE LABOUR	954.50	-
1	WHEEL DISC, FRONT	TO REPAIR SEE LABOUR	1,484.20	-
			6,370.70	1,201.90
<u>LABOUR</u>				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER FRT / LH, DOOR RR / LH AND WHEEL DISC, FRONT.			1,214.00	700.00
SPRAY PAINT.			1,874.00	780.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			200.00	40.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	30.00

Report Ref No. NS/INC18020596/Nsbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.		445.32	445.32
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	30.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO TRANSFER DOOR MECHANISM.		240.00	50.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			4,453.32	2,075.32
GRAND TOTAL			10,824.02	3,277.22

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,600.00
---	--	--	--	----------

Report Ref No. NS/INC18020596/Nsbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.