

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

Due 26/11/2018
Sunny 10/12/2018
Mering



17/12/2018
Merry Sunny

GST REG. NO : M2 - 0020081 - X

14 NOV 2018

ESTIMATE

Estimate No. : b1 49103	Page No. : 1 of 5
Date Estimated : 14/11/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Tay Hui Sing 52B Hume Avenue #02-08 Summerhill Singapore 596230	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKC909H	5F02462	30/09/2016	X1 sDrive18i	0

DESCRIPTION	VALUE
Replace rear bumper and remove attachment etc include knock on accident damage area	<i>1770</i> 2,125.00
Spray painting rear boot lid and rear bumper	<i>1805</i> 2,006.00
To check electrical wiring systems and lightings at the rear section for proper function.	<i>150</i> 177.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	<i>230</i> 271.00
Sundries.	<i>?</i> 150.00

Total Labour 1: **4,729.00**

DESCRIPTION	QTY	PRIC	VALUE
REAR LH BUMPER MOUNT	1	160.55	<i>?</i> 160.55
REAR RH BUMPER MOUNT	1	160.55	<i>?</i> 160.55
RR BUMPER CARRIER	1	468.30	<i>?</i> 468.30
MOUNTING SMART OPENER	1	45.30	<i>?</i> 45.30
REAR TRIM UNDERRIDE PROTECTION (X L	1	102.30	<i>cut</i> 102.30
RR BUMPER LH CORNER MOUNTING	1	141.90	<i>?</i> 141.90
RR BUMPER RH CORNER MOUNTING	1	141.90	<i>?</i> 141.90
Abrasion gua	1	2.55	<i>neu</i> 2.55
Abrasion gua	1	2.55	<i>?</i> 2.55
REAR BUMPER PANEL PRIMED	1	741.55	<i>de</i> 741.55
REAR BUMPER MIDDLE TRIM PANEL (PDC)	1	233.60	<i>cut</i> 233.60
REAR BUMPER TRIM BOTTOM (LINES)	1	222.45	<i>cut</i> 222.45
EMBLEM GROMMET	2	0.80	<i>neu</i> 1.60
BMW PLAQUE WITH ADHESIVE FILM	1	71.25	<i>neu</i> 71.25
LETTERING X1	1	64.10	<i>?</i> 64.10
ULTRASONIC SENSOR BLACK	4	248.70	<i>?</i> 994.80
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	<i>neu</i> 20.20

Total Parts : **3,575.45**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49103**
Date Estimated : **14/11/2018**
Prepared By : **Chua Kee Sin**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKC909H	5F02462	30/09/2016	X1 sDrive18i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 17/12/18 12:00 Excess S\$ _____

Surveyor's Name Taylor Sign [Signature]

Surveyor's Tel 97495229 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail taylor@lkkauto.com

No. of Working Days Recommend 4-5 days

Labour 1	:	4,729.00
Parts	:	3,575.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	581.31
Grand Total	:	8,885.76

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **