

15/02/10

INS. CASE OWNER:

CC /AXA1802

LKK:

IDAC:

ASSIGNMENT

Surveyor:

RASUL

DOI:

21/11/18

Date / Time:

14/11/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SVJ 8979P

Name of Insured:

KIM HANX (Augustine)

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A:

9/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

KIM HANX 30y

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

8801201/81264

Policy No.:

AM85001

Make / Model:

HYUNDAI

Place of Accident:

TPE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

KCC

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

15/11/18
VIC

SVJ 8979P-X

SVJ 8979P-X

STAGE

DATE/ PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

14/11/18 - VIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GLA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

to forum

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

P/P

SS 9,664.19

6 days)

Reduction:

16

%

Confirm by:

Email

Call

FINAL SETTLEMENT

Date/Time:

24/05/19

Confirm with:

AWARD

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

(w/ass)

SS 10,340.68

COW CHANGED LINE

Loss of Rental (LOR):

SS

()

days)

Loss of Use (LOU):

SS

100.00

x 8

days)

Loss of Income (LOI):

SS

(S

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4350.00

Total:

SS

10,812.68

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

10,812.68

Name 1:

CYCLE & CARLISLE INDUSTRIES PTB LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

Signature

Zame

REF:

AXA (ASM)

h

7948 J

ASSIGNMENT

From

Date:

21-11-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SL 7927A

at Workshop m/s

Cyle & Camage
188 Pandan Loop

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

Alan.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL 7927A

Yr Regn:

2017 n442

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz CLA 200

C.C. 1595

Colour:

RED

A/C:

Insured / Std / NI / NA

Sp Reading

33423

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W00 1173432N 430241

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/11/18

D.O.I.

21/11/18

Survey held at

CBC (AL)

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P 9.664.19

CR00: 61,874.15/161.0

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18020600/hb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 14-11-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 8979P	Veh. Inspected	SLL 7927A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/11/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/11/2018	Inspection Date		
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLL7927A

Tan Tse Woon, Alicia

Blk 646 Punggol Central
#16-350
Singapore 820646

Vehicle & Document Information

WIP No **28243**
Reg No/Reg Date **SLL7927A / 10/03/2017**
Date In/Mileage **/ 0**
Chassis No **WDD1173432N430241**
Engine No **27091031104292**
Make/Model **MB/MB CLA 200 COUPE (C117) "FACELIFT"**
Colour/Trim **025 589 Jupiter Re/ 041 151-Leather Twi**

Account No	Terms	Date/Time Printed	CSE	Operator
WCV29181	CRDVCH	13/11/2018/ 08:41	CL	305 / Alan Quek Ai Lun

Description of Goods / Services

Qty Unit Price Disc% Amount

M BPNSUN

POLICY NO/ACC DATE :2100503108 // 09-11-2018
DRIVE IN/:9-11-18 // TP CAR No.SJV8979P (AXA INSURANCE)
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DOOR AND LH/R DOOR

A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT

S BPNSUB

TRANSFER RIM AND BALANCING TYRE. NETT

A BPILAB

REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT

A BPILAB

INSPECT & CONDUCT WHEEL ALIGNMENT.NETT

M LH/ HEADLAMP UNIT

1.00 2813.62 00.00

2813.62

M LH/F DISK WHEEL

1.00 648.96 00.00

648.96

M LEFT REAR DOOR

1.00 1642.61 00.00

1642.61

M LH/R DOOR WEATHERSTRIP

1.00 280.72 00.00

280.72

M ABSORBING DOOR

1.00 62.05 00.00

62.05

Auto Collision Centre notify
Receiver of the following:

Survey before repair

Survey damaged part(s) during resurvey

Prices are subject to confirmation

Survey is on a "Without Prejudice" basis

Legal modification must be surveyed and

to final approval from Insurance Company

Resurvey by paint

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

Tel: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 11,487.96
7% GST on 11487.96 804.16

Total Payable 12,292.12

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLL7927A

Finalization

Ms Tan Tse Woon Alicia

C/O AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
63387288

Rasul

Vehicle & Document Information
WIP No 28243
Reg No/Reg Date SLL7927A / 10/03/2017
Date In/Mileage 21/11/2018 / 33426
Chassis No S WDD1173432N430241 A
Engine No 27091031104292
Make/Model MB/MB CLA 200 COUPE (C117) "FACELIFT"
Colour/Trim 025 589 Jupiter Re/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator				
CSI00001	Cash	28/11/2018/ 18:39	CL	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M. BPNSUN POLICY NO/ACC DATE :2100503108// 09-11-2018 DRIVE IN/ :9-11-18 // LTP CAR No: SJV8979P (AXA INSURANCE) DATE IN/DATE SURVEY:21-11-2018 // LKK RASUL BY/AUTHORIZED ON :LKK VIC ALPEH // 19-11-2018								
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								1440.00
A BPIRES RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DOOR AND LH/R DOOR								2400.00
S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD								60.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.NETT							0.19	400.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								540.00
X LH/ HEADLAMP UNIT					1.00	2813.62	00.00	2813.62
X LH/R DOOR					1.00	1642.61	00.00	1642.61
X LH/R DOOR WEATHERSTRIP					1.00	280.72	00.00	280.72
X ABSORBING DOOR					1.00	62.05	00.00	62.05
X BLIND RIVET WITH PAN HEAD					11.00	2.29	00.00	25.19

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 9,664.19
7% GST on 9664.19 676.49

Authorized signatory and company stamp

Total Payable 10,340.68

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
185 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

SUPPLEMENTARY

ESTIMATE FOR SLL7927A

Ms Tan Tse Woon Alicia

C/O AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
63387288

Vehicle & Document Information
WIP No 28243
Reg No/Reg Date SLL7927A / 10/03/2017
Date In/Mileage 21/11/2018 / 33426
Chassis No **S**WDD1173432N430241
Engine No 27091031104292
Make/Model MB/MB CLA 200 COUPE (C117) "FACELIFT"
Colour/Trim 025 589 Jupiter Re/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator				
CS100001	Cash	28/11/2018/ 18:39	CL	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

M_BPN SUN

POLICY NO/ACC DATE : 2100503108 // 09-11-2018
DRIVE IN : 9-11-18 // TP CAR No: SJV8979P (AXA INSURANCE)
DATE IN/DATE SURVEY: 21-11-2018 // LKK RASUL
BY/AUTHORIZED ON : LKK VIC ALPEH // 19-11-2018

X BLIND RIVET WITH PAN HEAD

11.00 2.29 00.00

25.19

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett** 25.19 25.19
1.76

Authorized signatory and company stamp

Total Payable 26.95

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of removing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383



Service Request Details

Claim

S8M012DI

Reference

None 

Loss Date

November 9, 2018

Request Date

November 13, 2018

Due Date

November 20, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

13-11-2018 @ 1:40pm
Alan veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLL7927A

Make

TPVD MERCEDES-BENZ

Model

CLA200

Service Address

...

Primary Contact/Insured

CHIA HANXI AUGUSTINE (XIE HANXI AUGUSTINE)
BLOCK 987C BUANGKOK GREEN, #13-45, 533987, Singapore
98271716
august_chia@yahoo.com.sg

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: Alan Quek <alan.quek@cyclecarriage.com.sg>
Sent: Tuesday, 13 November, 2018 9:30 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: SLL7927A / SJV8979P Date of accident:09-11-2018
Attachments: img-Y13090505-0001.pdf; SLL7927A.PDF

Categories: Pragati

AXA INSURANCE SINGAPORE PTE LTD

Attn: Motor Claims Dept

RE: Accident involving motor vehicle nos. **SLL 7927 A & SJV 8979 P.**
Along **TAMPINES EXPRESSWAY TWDS CHANGI AIRPORT.**

We have instructs by our client's of motor vehicle no:**SLL 7927 A**, which was involved in the above accident. Our client's vehicle was damaged and we now claiming against you for costs of repair and other consequential loss.

In order that you are the insurer of vehicle no:**SJV 8979 P** are willing to DIRECT SETTLEMENT and other incidental claims. We shall be grateful if you could kindly settle the cost of repair directly with us. On this note we will be much appreciated and looking forward to your Confirmation of settlement.

Your Sincerely

Alan Quek
Service Advisor
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg



Exceptional Journeys



 Please consider the environment before printing this e-mail.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended

recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



Re:<MANDATE IA> S8M012DI

Type

🔗 Question

Message

PLS PROCEED AS PROPOSED

Reply

Our ref:
Your ref:

SLL7927A

Date:

29 NOV 2018

Direct Settlement

To:

AXA Insurance Pte Ltd

Singapore 068811

Attn:

Motor Claims Department

Re: Accident Involving Motor Vehicle Nos. SLL7927A & SJV89792
At/Along Tampines Expressway Tolls Charge On 09/11/18 @ 08:50
Airport

I am the owner of vehicle no. SLL7927A that was involved in an accident with your insured vehicle no. SJV89792 of the above accident.

As the accident was caused by your insured negligent/inconsiderate driving, thus I am claiming from you for the following: -


1. Cost of Repairs	\$ 10,340.68
2. Loss of Use / Rental (8 days @ \$ 100 per day)	\$ 800
3. LTA/GIA Search Fee	\$ 2.00
4. GIA Report Fee	\$
5. Others	\$
Total: \$ 11,142.68	

I hereby give you fourteen (14) days to comply with the above, failing which, I shall instruct my solicitor to commence legal action against you. If you have any queries, please contact the representative of **CYCLE & CARRIAGE INDUSTRIES PTE LTD** at Telephone No: 67714377 (Mr Alan Quek) / 67714304 (Ms Amanda Ang).

I hereby give full authority to **CYCLE & CARRIAGE INDUSTRIES PTE LTD** and their representative to negotiate/comprise settlement of the above claim on my behalf.

Your co-operation and immediate attention to the above is greatly appreciated. I hereby look forward to hearing from you soon.

Yours faithfully



Name & Signature

Address: C/o. 188 Pandan Loop Singapore 128378
Cc: Mr Alan Quek/ Ms Amanda Ang
E-mail: alan.quek@cyclecarriage.com.sg / amanda.ang@cyclecarriage.com.sg
Fax No. 67795383

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJV 8979P (Insd veh)	Model:	MERCEDES BENZ CLA200
	SLL 7927A (TP veh)		
Date of Accident:	09/11/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	12,319.07
Final Repair Cost	:	\$	10,340.68
Loss of Use	:	\$	480.00
Rental (if any)	:	\$	2.00
LTA / GIA Search Fee	:	\$	

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	10,822.68

Is Third Party Workshop GIA Registered?		☒ YES	☐ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____(%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	CYCLE & CARRIAGE INDUSTRIES PTE LTD	:	\$ 10,822.68

NUR SHAQILAH BTE ABDOL
WAHAB

31/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18020600/R1hb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 31-05-2019



ATTN: KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 8979P	Veh. Inspected	SLL 7927A
Policy No.	GA089200/1	Coverage (\$)	0.00
Claim No.	S8M012DI	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	14/11/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA200	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD1173432N430241	Colour	RED
Odometer	33423	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40R18	CONTINENTAL	6 mm
L/H Front Tyre	225/40R18	CONTINENTAL	6 mm
R/H Rear Tyre	225/40R18	CONTINENTAL	6 mm
L/H Rear Tyre	225/40R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/11/2018	Inspection Date	21/11/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7927A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH/ HEADLAMP UNIT (SN) (CONSISTENT)	DAMAGED	2,813.62	2,813.62
1	LH/F DISK WHEEL (SN) (CONSISTENT)	NOT NECESSARY	648.96	-
1	LEFT REAR DOOR (SN) (CONSISTENT)	BENT	1,642.61	1,642.61
1	LH/R DOOR WEATHERSTRIP (SN) (CONSISTENT)	NECESSARY	280.72	280.72
1	ABSORBING DOOR (SN) (CONSISTENT)	NECESSARY	62.05	62.05
11	BLIND RIVET WITH PAN HEAD (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	25.19	25.19
			5,473.15	4,824.19
	<u>LABOUR</u>			
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		1,920.00	1,440.00
	RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DOOR AND LH/R DOOR.		3,000.00	2,400.00
	TO REMOVE, REPLACE HEADLAMP WITH FOCUS.	NOT NECESSARY	120.00	-
	TRANSFER RIM AND BALANCING TYRE.		60.00	60.00
	REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.		400.00	400.00
	INSPECT & CONDUCT WHEEL ALIGNMENT.		540.00	540.00
			6,040.00	4,840.00
	GRAND TOTAL		11,513.15	9,664.19
	RECOMMENDED COST OF REPAIRS			9,664.19

Report Ref No. CC4/ASM18020600/R1hb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.