LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

FWD Singapore Pte. Ltd. 6 Temasek Boulevard To: #18-01 Suntec Tower 4 Singapore 038986

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Clara Li Zi Rong Date: 15 Nov 2018

Preliminary Advice

Insured Vehicle No : SKT9107G

TP Vehicle No **Accident Date** : SJZ3141B : 09/11/2018 Make : MERCEDES-BENZ E220D SE Assignment Date : 14/11/2018 Date of Inspection : 14/11/2018 Est. Duration of Repair : 4/Days

Inspection At : MBM WHEELPOWER PTE LTD

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$:S\$ 10,317.20 :S\$ 4,039.90	
Revised Amount	:S\$		
Check Items (Estimated)	:S\$	2,676.70	
Total	:S\$	6,716.60	

:S\$

Total Loss Consideration

Lump Sum Repair

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(X)	Other comments :We have not authorized repairs.