

15/5/2010

INS. CASE OWNER:

CC 4/III1802 0606, K^{ee} a3

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age : ABDUL KASHIM BIN MANSOR.

Driver Tel No. :

(V/L: YES / NO)

Claim No. :


Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time		STAGE	DATE / PIC
15.11.18	SEEK MANDATE FOR LIABILITY.	Non-Reporting ltr (1st):	
16.11.18	MANDATE APPROVE LIABILITY.	Non-Reporting ltr (2nd):	
20.11.18	EMAIL WSP LIABILITY CLAIM.	Non-Reporting ltr (Final):	
27.11.19	FILE PASS TO TYPIST TO PREPARE REPORT.	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐ ☐
		After call ltr to OI:	☐ ☐
		Authorisation To Act:	☒ ☐
		Release Voucher:	☒ ☐
		Final Repair Bill:	☒ ☐
		Car Rental Invoice:	☒ ☐
		Towing Invoice	☐ ☐
		LTA / GIA :	☐ ☐
		Medical Bill:	☐ ☐
		PIR:	☐ ☐
		Mandate/Reject Instruction:	☒ ☐
		LOD	☒ ☐
		Payment Breakdown Form:	☐ ☐
		Post-Repair Photos:	☐ ☐
		Others:	☐ ☐
PRELIMINARY ADVICE Date/Time: Sent By:		Confirm by: KSL	
FINALIZATION Date/Time: Confirm with:		Confirm by: KSL	
Repair Cost:	PIP SS15,908.45 (14 days) Reduction: 40 %	Email ☒ Call ☐	
FINAL SETTLEMENT Date/Time: 26.03.20 Confirm with: WY		Email ☒ Call ☐	
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 27	If NO or B 28, Ass. Lia :	
Repair Cost:	W/LST SS17,030.04	DID REAR BRIDGE P.	
Loss of Rental (LOR):	W/LST SS 1,936.00 (18 days) x 100		
Loss of Use (LOU):	SS - (S x days)		
Loss of Income (LOI):	SS - (S x days)		
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LO ☐ [Tick only one]		
GIA/LTA Search	SS -		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle	
Legal Cost	SS -	2) Report Format: TP	
		3) Survey fee: *600	
Total:	SS18,948.04 Global Sum SS: 17,500 (PRINCIPAL APPROVED)		
FINAL PAYMENT Date/Time: 26.03.20 Confirm with: WY		Email ☒ Call ☐	
Payee 1:	SS17,500.00	Name 1:	MBM WHEELPOWER PTE LTD
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

REF: III

ASSIGNMENT

From:

Date: 19/11/18

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLL5725D

at Workshop m/s

MBM Wheel Power

of

160 Sin Ming Drive # 06-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 11am
Stephanie

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$79K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

/up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLL5725D

Yr Regn:

03 187

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Signa

C.C.

1496

Colour:

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

27664

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NSP170

7035027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

9/11/18

D.O.I.

19/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/11 File pass to Corina

P/P : +15,908.45 (RED: +10,812.80 40%+)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / L.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

mbm *wheelpower*

Our Ref: SLL5725D

CC

Fax

ESTIMATE FOR VEHICLE NO. : SLL5725D

Date:	19/11/2018
From:	Stephanie
Fax:	64525333
Contact:	86865188
Make / Model:	TOYOTA SIENTA 1.5G CVT
Chassis No.:	NSP1707035027
Engine No.:	2NR8623103
Year of Make:	2016
Accident Date:	9 November 2018

DESCRIPTION	QTY	UNIT	LIST PRICE	REMARKS
REAR WINDSCREEN WITH MOULDING	1	\$	1,462.00	
TAIL GATE	1	\$	1,432.00	
TAIL GATE WEATHERSTRIP	1	\$	483.00	
TAIL GATE INNER TRIM BOARD	1	\$	226.00	
TAIL GATE INNER TRIM BOARD CLIPS @\$ 7 EACH	10	\$	70.00	
TAIL GATE HINGE LH	1	\$	98.00	
TAIL GATE HINGE RH	1	\$	98.00	
TAIL GATE STAY RH	1	\$	305.00	
TAIL GATE STAY LH	1	\$	305.00	
TAIL GATE LOCK	1	\$	580.00	
TAIL GATE STRIKER	1	\$	76.00	
REAR WIPER MOTOR	1	\$	832.00	
REAR WIPER ARM	1	\$	110.00	
REAR WIPER BLADE	1	\$	86.00	
TAIL GATE OUTER CHROME MOULDING	1	\$	305.00	
TAIL GATE"TOYOTA" LOGO	1	\$	116.00	
TAIL GATE LAMP LH	1	\$	535.00	
TAIL GATE LAMP RH	1	\$	535.00	
TAIL LAMP RH	1	\$	442.00	
TAIL LAMP LH	1	\$	442.00	
REAR BUMPER	1	\$	1,282.00	
REAR BUMPER CLIPS @ 6 EACH	10	\$	60.00	
REAR BUMPER LH SIDE SEAL	1	\$	97.00	
REAR BUMPER RH SIDE SEAL	1	\$	97.00	

REAR BUMPER LH SIDE SUPPORT	1	\$	Sh 138.00 X
REAR BUMPER RH SIDE SUPPORT	1	\$	Sh 138.00 X
REAR BUMPER RH SIDE RETAINER	1	\$	Dry 95.00 ✓
REAR BUMPER LH SIDE RETAINER	1	\$	Dry 95.00 ✓
REAR BUMPER SPONGE	1	\$	CM 104.00 Z
REAR BUMPER RH SIDE EXTENSION	1	\$	Bu 195.00 ✓
REAR BUMPER LH SIDE EXTENSION	1	\$	Bu 195.00 Z
REAR BUMPER CTR EXTENSION	1	\$	Dry 283.00 ✓
REAR BUMPER RH REFLECTOR	1	\$	Sh 152.00 X
REAR BUMPER LH REFLECTOR	1	\$	Sh 152.00 X
END PANEL SUB-ASSY	1	\$	Bu 498.20 ✓
END PANEL TOP GARNISH	1	\$	Dry 895.00 ✓
END PANEL TOP GARNISH CLIPS @ 7 EACH	10	\$	Dry 205.00 ✓
REAR FLOOR PANEL	1	\$	MC 224.00 ✓
REAR RH FENDER	1	\$	MC 70.00 ✓
REAR LH FENDER	1	\$	Bu 880.00 Z
EXHUAUST PIPE	1	\$	R 829.00 X
EXHUAUST PIPE HANGER	1	\$	R 1,909.00 X
FRONT BUMPER	1	\$	R 1,980.00 X
FRONT BUMPER SPOILER	1	\$	Sh 180.00 X
FRONT ENGINE UNDERCOVER CENTER	1	\$	Bu/CM 535.10 ✓
			CM 251.00 ✓
			MC 282.00 ✓
			MC 376.00 ✓
Total:		\$	20,266.00
LESS 25%		\$	(4,053.20)
Parts Total:		\$	16,212.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

BODY SEALANT

1

\$

na 60m 80.00

REVERSE SENSOR

1 SET

\$

short 200m 400.00**LABOUR**

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$

1400 1,800.00

TO REMOVE AND REPLACE REAR WINDSCREEN

\$

120 150.00

TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR

\$

60 80.00

TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR

\$

80 100.00

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

\$

150 150.00

TO REMOVE & REPLACE BUMPER SENSORS

\$

140 40.00

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$

20 80.00

TO CONDUCT CHASSIS ALIGNMENT ON (CAR-O-LINER)

\$

✓ 250.00 400.00

TO REMOVE AND REPLACE REAR EXHAUST MUFFLER

\$

60 180.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$

1600 2,100.00

Total: \$ 21,772.80

7% GST: \$ 1,524.10

Grand Total: \$ 23,296.90*20759.50**26721.25**

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t62628888 f64525333

Company Registration Number : 200204110W

MBM WHEELPOWER PTE LTD

Your Ref: SHD3315G

Our Ref: SLL5725D

To: INDIA INTERNATIONAL

CC

Fax

Date: 29/4/2019
 From: Stephanie
 Fax: 64525333
 Contact: 86865188
 Make / Model: TOYOTA SIENTA 1.5G CVT
 Chassis No.: NSP1707035027
 Engine No.: 2NR8623103
 Year of Make: 2016
 Accident Date: 9 November 2018

SUPPLEMENTARY ESTIMATE FOR VEHICLE NO. : SLL5725D

DESCRIPTION

REAR FLOOR PANEL OUTER *659*
 DECKBOARD SUB-ASSY
 DECKBOARD TRIM
 REAR LH FENDER INNER GARNISH TRIM *716*
 REAR RH FENDER INNER GARNISH TRIM *716*
 REAR LH DOOR SLIDE COVER *645-10*
 REAR RH DOOR SLIDE COVER *645-10*
 FRONT BUMPER ENGINE UNDER COVER LH
 FRONT REINFORCEMENT LH SIDE RAIL
 FRONT BUMPER LOWER COVER *282*
 ANTENNA, ELECTRICAL KEY
 REAR PANEL LH
 REAR PANEL RH
 LUGGAGE TRAY COMPARTMENT
 END PANEL OUTER

QTY	List Price	
1	\$ 843.00	<i>BT</i> ✓
1	\$ 810.00	<i>DIG 120</i> ✓
1	\$ 530.00	<i>Del 120</i> ✓
1	\$ 855.00	<i>Bu</i> ✓
1	\$ 855.00	<i>Bu</i> ✓
1	\$ 705.00	<i>mbm</i> ✓
1	\$ 705.00	<i>mylra</i> ✓
1	\$ 290.00	<i>CMT</i> ✓
1	\$ 355.00	<i>DIT B</i> ✓
1	\$ 320.00	<i>CMT</i> ✓
1	\$ 180.00	<i>CMT</i> ✓
1	\$ 232.00	<i>By B B</i> ✓
1	\$ 232.00	<i>By K B</i> ✓
1	\$ 380.00	<i>nd</i> ✓
1	\$ 657.00	<i>Reported By B</i> ✓
Total:	\$ 7,949.00	
LESS 25%	\$ (1,589.80)	
Parts Total:	\$ 6,359.20	