


MBM WHEELPOWER PTE LTD

Your Ref: SHD3315G

Our Ref: SLL5725D



To: INDIA INTERNATIONAL

CC

Fax

Date: 19/11/2018

From: Stephanie

Fax: 64525333

Contact: 86865188

Make / Model: TOYOTA SIENTA 1.5G CVT

Chassis No.: NSP1707035027

Engine No.: 2NR8623103

Year of Make: 2016

Accident Date: 9 November 2018

Not Notarized
1. B. 1. 11 Long @?

ESTIMATE FOR VEHICLE NO. : SLL5725D

DESCRIPTION

QTY

List Price

REAR WINDSCREEN WITH MOULDING <i>P-1</i>	1	\$	<i>M</i> 1,462.00 <i>L</i>
TAIL GATE	1	\$	<i>B</i> 1,432.00 <i>L</i>
TAIL GATE WEATHERSTRIP	1	\$	<i>Butter</i> 483.00 <i>L</i>
TAIL GATE INNER TRIM BOARD	1	\$	226.00 <i>L</i>
TAIL GATE INNER TRIM BOARD CLIPS @\$ 7 EACH	10	\$	70.00 <i>L</i>
TAIL GATE HINGE LH	1	\$	<i>H</i> 98.00 <i>X</i>
TAIL GATE HINGE RH	1	\$	<i>H</i> 98.00 <i>L</i>
TAIL GATE STAY RH	1	\$	305.00 <i>L</i>
TAIL GATE STAY LH	1	\$	305.00 <i>L</i>
TAIL GATE LOCK	1	\$	<i>Tm</i> 580.00 <i>L</i>
TAIL GATE STRIKER	1	\$	76.00 <i>L</i>
REAR WIPER MOTOR	1	\$	832.00 <i>L</i>
REAR WIPER ARM	1	\$	<i>Sh</i> 110.00 <i>X</i>
REAR WIPER BLADE	1	\$	<i>Sh</i> 86.00 <i>L</i>
TAIL GATE OUTER CHROME MOULDING	1	\$	<i>Bu</i> 305.00 <i>L</i>
TAIL GATE "TOYOTA" LOGO	1	\$	<i>M</i> 116.00 <i>L</i>
TAIL GATE LAMP LH	1	\$	535.00 <i>L</i>
TAIL GATE LAMP RH	1	\$	535.00 <i>L</i>
TAIL LAMP RH	1	\$	<i>mg, M</i> 442.00 <i>L</i>
TAIL LAMP LH	1	\$	<i>CM</i> 442.00 <i>L</i>
REAR BUMPER	1	\$	<i>B</i> 1,282.00 <i>L</i>
REAR BUMPER CLIPS @ 6 EACH	1	\$	<i>M</i> 60.00 <i>L</i>
REAR BUMPER LH SIDE SEAL	1	\$	97.00 <i>L</i>
REAR BUMPER RH SIDE SEAL	1	\$	97.00 <i>L</i>

REAR BUMPER LH SIDE SUPPORT	1	\$		138.00	✓
REAR BUMPER RH SIDE SUPPORT	1	\$		138.00	✓
REAR BUMPER RH SIDE RETAINER	1	\$	DRY	95.00	✓
REAR BUMPER LH SIDE RETAINER	1	\$	DRY	95.00	✓
REAR BUMPER SPONGE	1	\$		104.00	✓
REAR BUMPER RH SIDE EXTENSION	1	\$	BR	195.00	✓
REAR BUMPER LH SIDE EXTENSION	1	\$		195.00	✓
REAR BUMPER CTR EXTENSION	1	\$	DRY	283.00	✓
REAR BUMPER RH REFLECTOR	1	\$	SM	152.00	X
REAR BUMPER LH REFLECTOR	1	\$	SM	152.00	✓
END PANEL SUB-ASSY	1	\$	BR	895.00	✓
END PANEL TOP GARNISH	1	\$	DRY	224.00	✓
END PANEL TOP GARNISH CLIPS @ 7 EACH	10	\$	MC	70.00	✓
REAR FLOOR PANEL	1	\$	R	880.00	✓
REAR RH FENDER	1	\$	R	829.00	X
REAR LH FENDER	1	\$	R	1,909.00	X
EXHUAUST PIPE	1	\$	R	1,980.00	X
EXHUAUST PIPE HANGER	1	\$	SM	180.00	X
FRONT BUMPER	1	\$	BUL/CA	1,020.00	✓
FRONT BUMPER SPOILER	1	\$	CMA	282.00	✓
FRONT ENGINE UNDERCOVER CENTER	1	\$	CMA	376.00	✓
Total: \$				20,266.00	
LESS 25% \$				(4,053.20)	
Parts Total: \$				16,212.80	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

BODY SEALANT

1

\$

12 6012 80.00

REVERSE SENSOR

1 SET

\$

short 20012 400.00**LABOUR**TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO
KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$

1401 1,800.00

TO REMOVE AND REPLACE REAR WINDSCREEN

\$

1201 150.00TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW TAILGATE /
FACILITATE REPAIR

\$

601 80.00

TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR

\$

801 100.00

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

\$

1501 150.00

TO REMOVE & REPLACE BUMPER SENSORS

\$

40.00 ✓

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$

201 80.00

TO CONDUCT CHASSIS ALIGNMENT ON (CAR-O-LINER)

\$

400.00 ?

TO REMOVE AND REPLACE REAR EXHAUST MUFFLER

\$

601 180.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$

16001 2,100.00

Total: \$ 21,772.80

7% GST: \$ 1,524.10

Grand Total: \$ 23,296.90

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t62628888 f64525333

Company Registration Number : 200204110W