

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHD 3279C

MAKE :

MODEL : HYUNDAI i40

LKK Auto Consultants hence notify

the Repairer of the following: DATE : 12.11.2018

• To resurvey before/after spray painting TEL : 6542 5119

• To display damaged part(s) during resurvey FAX : 6542 6039

• Parts prices are subject to confirmation

INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet NA <i>NA</i>			\$ 2,265.90 <i>✓</i>
	Bonnet Hinge (LH/RH) <i>NA</i>		\$ 41.00	\$ 82.00 <i>X</i>
	Bonnet Lock <i>NA</i>			\$ 36.90 <i>✓</i>
	Radiator Grille <i>broken</i>			\$ 1,110.10 <i>✓</i>
	Radiator Grille H Emblem <i>dislodged</i>			\$ 39.50 <i>✓</i>
	Front Bumper Cover <i>NA</i>			\$ 1,052.20 <i>✓</i>
	Front Bumper Sponge <i>NA</i>			\$ 99.20 <i>✓</i>
	Front Bumper Reinforcement <i>NA</i>			\$ 402.10 <i>✓</i>
	Front Bumper Lip <i>NA</i>			\$ 54.90 <i>X</i>
	Front Bumper Bracket Top (LH/RH) <i>NA</i>		\$ 22.40	\$ 44.80 <i>X</i>
	Front Bumper Bracket (LH/RH) <i>NA</i>		\$ 24.60	\$ 49.20 <i>X</i>
	Headlamp Support Top Cover <i>NA</i>			\$ 222.60 <i>X</i>
	Headlamp Support Panel Assy <i>NA</i>			\$ 907.40 <i>✓</i>
	Headlamp (LH/RH) <i>mounting crack</i>		\$ 1,388.00	\$ 2,776.00 <i>✓</i>
	Radiator <i>NA</i>			\$ 698.30 <i>✓</i>
	Radiator Fan Blade, Cowling, Motor Assy <i>NA</i>			\$ 792.95 <i>✓</i>
	Radiator Bracket (RH/LH) <i>NA</i>		\$ 6.50	\$ 13.00 <i>X</i>
	Radiator Guard <i>NA</i>		\$ 20.00	\$ 40.00 <i>X</i>
	Horn Unit (LH/RH) <i>NA</i>		\$ 73.80	\$ 147.60 <i>✓</i>
	Aircon Condenser <i>NA</i>			\$ 927.50 <i>✓</i>
	Inter Cooler <i>NA</i>			\$ 1,032.50 <i>X</i>
	Inter Cooler Mounting (2 PCS) <i>NA</i>			\$ 25.90 <i>X</i>
	SUB TOTAL			\$ 12,820.55
	LESS 20%			\$ 2,564.11
	DISCOUNTED TOTAL			\$ 10,256.44
	Front Number Plate <i>dislodged</i>			\$ 25.00 <i>Nett ✓</i>
	Front No Plate Trim Cover <i>dislodged</i>			\$ 30.00 <i>Nett ✓</i>
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 <i>500/-</i>
	Spray Painting Charge			\$ 500.00 <i>200/- 400/-</i>
	Wiring Charge			\$ 50.00 <i>30/-</i>
	Tuff Kote			\$ 50.00 <i>NA</i>
	Towing Charge			\$ 50.00 <i>NA</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00 <i>80/-</i>
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 <i>NA</i>
	TOTAL LABOUR			\$ 2,280.00
	ESTIMATE TOTAL			\$ 12,591.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.