

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1254/2018/JT 22-Nov-18 Jeffery Tan 1 SLT 2066 A Audi Q5 Sport 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
Parts			
1	Bumper tail light - LHS <i>cracked</i>	\$ 619.00	<i>494.80</i>
TOTAL		\$ 619.00	

For Premium Automobiles Pte Ltd

Adrian Ling
sls

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1254/2018/JT
Date	:	8-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 days - ok - jb - 17 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Munich Management Pte Ltd
Address	:	20 Qollier Quay
	:	#13-01
	:	Singapore 049319
Telephone	:	HP + 65 9785 6311
Type of Claim	:	Own Damage Claims
Policy No.	:	1700063197-01
Vehicle No	:	SLT 2066 A
Model Code	:	Audi Q5 Sport 2.0 TFSI qu
Model / Year	:	Oct-17
Engine No	:	DAX 014344
Chassis No	:	WAUZZZF8H2052312
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	4-Nov-18
Place of Accident	:	Braddell road towards Lornie Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 2066 A

S/n	Nature of Jobs	Estimated Charges	
1	To remove and transfer rear parking aid & rear lid kick sensor. Check function.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper assy. To repair rear lid. Re-organize crash management components. Reinstall all parts removed.	\$ 1,400.00	\$ 750.00
3	To respray rear bumper, rear lower spoiler, rear lid and both wheel arch trim.	\$ 2,800.00	\$ 1,860.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,752.00	\$ 3,162.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 2066 A.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
1	REAR BUMPER	\$ 1,970.00	\$ 1,576.00
2	REAR BUMPER SPOILER	\$ 862.00	\$ 689.20
3	REAR BUMPER LOWER TRIM	\$ 354.00	\$ 282.80
4	LOWER SPOILER TRIM - LHS/RHS	\$ 486.00	
5	ALUMINIUM TRIM	\$ 1,566.00	\$ 1,252.80
6	REAR BUMPER TAIL LIGHT - RHS	\$ 619.00	\$ 494.80
7	BOOT LID CONTROL UNIT	\$ 375.00	
8	BOOT LID CTRL UNIT BRACKET	\$ 40.00	
9	REAR PARKING AID SENSOR	2 \$ 421.00	
10	REAR REINFORCEMENT BEAM	\$ 786.00	
11	REAR BUMPER FOAM FILLER	\$ 53.00	
12	REAR LID SENSOR HOLDER	\$ 142.00	
13	REAR BUMPER GUIDE - RHS	\$ 71.00	
14	REAR NUMBER PLATE PACKING PIECE	\$ 15.00	\$ 11.60
15	AUDI EMBLEM	\$ 108.00	\$ 86.00
16	"Q5" EMBLEM	\$ 83.00	\$ 66.16
17	"TFSI" EMBLEM	\$ 83.00	\$ 66.16
18	"quattro" EMBLEM	\$ 83.00	\$ 66.16
19	REAR WHEEL ARCH TRIM - LHS/RHS	\$ 910.00	\$ 727.20
20	WHEEL ARCH TRIM CLIPS	16 \$ 34.00	\$ 26.88
21	REAR NUMBER PLATE	S/N \$ 25.00	
22	<i>Added parts - see attached</i>	\$ 619.00	\$ 494.80
23	SUNDRIES	\$ 400.00	
	TOTAL SPARE PARTS CHARGES	\$ 10,105.00	\$ 5,840.56
	TOTAL LABOUR CHARGES	\$ 4,752.00	\$ 3,162.00
	GRAND TOTAL	\$ 14,857.00	\$ 9,002.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/1254/2018/JT
22-Nov-18
Jeffery Tan
1
SLT 2066 A
Audi Q5 Sport 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Bumper tail light - LHS	\$ 619.00	\$ 494.80
		\$ 619.00	\$ 494.80
	TOTAL	\$ 619.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLT 2066 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1254/2018/MAS

2 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLT 2066 A, Audi Q5 Sport 2.0 TFSI Qu S-Tro

With reference to the above-mentioned vehicle, no. **SLT 2066 A**, claimant, **Munich Management Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85013305 – S\$8,562.74
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLT 2066 A

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Page 1 17:48

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408879
Telephone 6388 7773
Telefax 6388 7773

Customer Service

Service Appointment 6366 2323
Hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013305
Date : 20/12/2018
Order : SLT2066A
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLT2066A (V 35614) Regn Date: 20/10/2017 Mileage: 4328 WIP No.: 31025
Model: Q5 SPORT 2.0 TFSI qu 5 tronic Chassis: WAUZZZF0H2052312 Engine: DAX 014344 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (B7)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR,CHECK FUNCTION	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER ASSY.TO REPAIR REAR LID,REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,REAR LOWER SPOILER, REAR LID AND BOTH WHEEL ARCH TRIM	1860.00	1.00	1,860.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A80A8538178 GRU	COVER Less 020%	1.00	454.50	363.60
X	A80A8538188 GRU	COVER Less 020%	1.00	454.50	363.60
X	A80A8074340 GRU	SPOILER Less 020%	1.00	861.50	689.20
X	A80A807578 307	(A)(SK)MOLDING Less 020%	1.00	1566.00	1,252.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road

Singapore 159938

Main Telephone 6836 2223

Main Telefax 6471 3733

Page 2 17:40

Alexandra Service Centre

281 Alexandra Road

Singapore 159938

Telephone 6388 2223

Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1

Singapore 408601

Telephone 6388 3333

Telefax 6841 1183

Customer Service

Service Appointment

Hour Breakdown Service

Email

customer.care@premiumauto.com.sg

6366 2323

6828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013305
Date : 20/12/2018
Order : SLT2066A
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLT2066A (V 35614) Regn Date: 20/10/2017 Mileage: 4328 WIP No.: 31025
Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF8Y8H2052312 Engine: DAX 014344 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (87)

		Details		Qty	Unit Price	Amount
X	A00A007067E GRU	(A) (SK) COVER	Less 020%	1.00	1970.00	1,576.00
X	A0R0053741 22Z	INSCRIPTION 'Q5'	Less 020%	1.00	82.70	66.16
X	A4H0053737D 22Z	INSCRIPTION 'TFSI'	Less 020%	1.00	82.70	66.16
X	A4G5053742 22Z	AUDI SIGN	Less 020%	1.00	107.50	86.00
X	A0D0053419F	PACKING	Less 020%	1.00	14.50	11.60
X	A0U0053909	CLIP	Less 020%	16.00	2.10	26.88
X	A0W9053737 22Z	NAME PLATE 'QUATTRO'	Less 020%	1.00	82.70	66.16
X	A00A945070	(A) (SK) TAILLIGHT	Less 020%	1.00	618.50	494.80
X	A00A945069	TAILLIGHT	Less 020%	1.00	618.50	494.80
X	A00A007023	(A) (SK) TRIM	Less 020%	1.00	353.50	282.80
Sub-Total						8,002.56
7% GST						560.18
Grand Total						8,562.74

Parts 5,840.56
Labour 0.00
Sublet 3,162.00
Menus 0.00
Lubricant 0.00

Signature

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLT 2066 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1254/2018/JT
November 2018

from:
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 Sport 2.0 TFSI qu
Vehicle Chassis No. : WAUZZZF8H2052312
Vehicle Regn No. : SLT 2066 A
Vehicle Mileage : 11308 km
Vehicle Owner : Munich Management Pte Ltd
Certificate No. : 1700063197-01
Own Damage Excess : \$1070.00
Accident Date : 04th November 2018
Place : Braddell Road towards Lornie Road
Repair Cost : \$ 8,562.74
WIP No. : 31025
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kei Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres:
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :

23/11/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Nov 2018		14 Nov 2018 15:19 Edit Adj Rpt	S\$9,002.56 Edit Estimates	S\$9,002.56 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MUNICH MANAGEMENT PTE LTD , Co. Reg. No.: 197501746E, Tel: +6597856311		
Vehicle Reg. No.:	SLT2066A	Date of Loss:	04/11/2018 18:00 - :59 [12 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 5763145513SG	Policy/Cover Note No.:	1700063197-01 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/11/2018]		
Driver/Custodian:	ECKL ROLAND (49 / Male), NRIC: G3371683X, Tel: +6581817600		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (28/11/2018): Alert - Adj Mandate Approved (S\$9495.00) - SLT2066A - Claim Handler: Dally Amri,...
- AIG_SG (28/11/2018): SLT2066A / OD / 04/11/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLT2066A (5763145513SG)**
OD
Nov 4 2018 6:10PM
[MUNICH MANAGEMENT PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

1 per page

Thumbnail

Print

Assessment Reports

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/11/18 13:54	Adjuster Immediate Advice	1	Load HTM	
2	23/11/18 11:41	Adjuster Immediate Advice	1	Load HTM	

3 per page

Thumbnail

Print

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/11/18 13:56	General View	1	Load JPG	
2	15/11/18 13:56	Chassis Number	1	Load JPG	
3	15/11/18 13:56	General View	1	Load JPG	
4	15/11/18 13:56	General View	1	Load JPG	
5	15/11/18 13:56	General View	1	Load JPG	
6	15/11/18 13:56	General View	1	Load JPG	
7	15/11/18 13:56	General View	1	Load JPG	
8	15/11/18 13:56	General View	1	Load JPG	
9	15/11/18 13:56	General View	1	Load JPG	
10	15/11/18 13:56	General View	1	Load JPG	
11	15/11/18 13:56	General View	1	Load JPG	
12	15/11/18 13:56	General View	1	Load JPG	
13	15/11/18 13:56	General View	1	Load JPG	
14	15/11/18 13:56	General View	1	Load JPG	
15	15/11/18 13:56	General View	1	Load JPG	
16	15/11/18 13:56	General View	1	Load JPG	
17	15/11/18 13:56	General View	1	Load JPG	
18	15/11/18 13:56	General View	1	Load JPG	
19	15/11/18 13:56	General View	1	Load JPG	
20	17/12/18 11:09	Reinspection Photo	1	Load JPG	
21	17/12/18 11:09	Reinspection Photo	1	Load JPG	
22	17/12/18 11:09	Reinspection Photo	1	Load JPG	
23	17/12/18 11:09	Reinspection Photo	1	Load JPG	
24	17/12/18 11:09	Reinspection Photo	1	Load JPG	
25	17/12/18 11:09	Reinspection Photo	1	Load JPG	
26	17/12/18 11:09	Reinspection Photo	1	Load JPG	
27	17/12/18 11:09	Reinspection Photo	1	Load JPG	
28	17/12/18 11:09	Reinspection Photo	1	Load JPG	

1 per page

Thumbnail

Print

Documentation

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	28/11/18 08:36	undertaking letter, interview form and copy of passport	1	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/11/18 13:55	Singapore Accident Statement	1	Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	15/11/18 13:55	Police Report	Load PDF	
3	15/11/18 13:55	Certificate of Insurance	Load PDF	
4	15/11/18 13:55	Driver's Driving License	Load PDF	
5	15/11/18 13:55	ESTIMATE	Load PDF	
6	10/01/19 11:45	SUPPLEMENTARY	Load PDF	
7	10/01/19 11:45	DISCHARGE VOUCHER	Load PDF	
8	10/01/19 11:45	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/11/18 15:25	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/11/18 15:15	Police Report	Load JPG	☒
2	05/11/18 15:15	Police Report	Load JPG	☒
3	05/11/18 15:15	Police Report	Load JPG	☒
4	05/11/18 15:22	Accident Photo	Load JPG	☒
5	05/11/18 15:22	Accident Photo	Load JPG	☒
6	05/11/18 15:22	Driving License	Load JPG	☒
7	05/11/18 15:22	Accident Photo	Load JPG	☒
8	05/11/18 15:22	Accident Photo	Load JPG	☒
9	05/11/18 15:22	Accident Photo	Load JPG	☒
10	05/11/18 15:22	Accident Photo	Load JPG	☒
11	05/11/18 15:22	Accident Photo	Load JPG	☒
12	05/11/18 15:22	Accident Photo	Load JPG	☒
13	05/11/18 15:22	Accident Photo	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/11/18 15:15	Sketch Plan	Load JPG	☒
2	05/11/18 15:15	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18020608/AQBS2

Date: 10/01/2019

REFERENCE

Insured/Claimant: MUNICH MANAGEMENT PTE LTD Policy No: 1700063197-01
Date of Loss: 04/11/2018 Nature of Claim: OD Claim No: 5763145513SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT2066A** Engine No: DAX014344
Make & Model: AUDI Q5, 2.0 (A) Chassis No: WAUZZZF8H2052312
Reg. Date: 20/10/2017 (Man. Year: 2017) Odometer: 4202 km
Colour: White
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$182,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,980.80	5,840.56	4,140.24	41.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	3,162.00	1,590.00	33.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,732.80	9,002.56	5,730.24	38.89
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	13,732.80	8,002.56	5,730.24	41.73
+ GST 7.00/7.00% (S\$)	961.30	560.18	401.12	41.73
Nett Amount (S\$)	14,694.10	8,562.74	6,131.36	41.73

INSPECTION

Date of Assignment: 14/11/2018 Premium Automobiles Pte Ltd (UBI)
Date Inspected: 14/11/2018 Inspected At: 55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,970.00 FS	*1,576.00 FS
2	1		*REAR BUMPER SPOILER	Deformed	862.00 FS	*689.20 FS
3	1		*REAR BUMPER LOWER TRIM	Deformed	354.00 FS	*282.80 FS
4	1		*LOWER SPOILER TRIM - LHS / RHS	Not Necessary	486.00 FS	*- FS
5	1		*ALUMINIUM TRIM	Cut	1,566.00 FS	*1,252.80 FS
6	1		*REAR BUMPER TAIL LIGHT - RHS	Cut	619.00 FS	*494.80 FS
7	1		*BOOT LID CONTROL UNIT	Not Necessary	375.00 FS	*- FS
8	1		*BOOT LID CTRL UNIT BRACKET	Not Necessary	40.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR	Not Necessary	421.00 FS	*- FS
10	1		*REAR REINFORCEMENT BEAM	Not Necessary	786.00 FS	*- FS
11	1		*REAR BUMPER FOAM FILLER	Not Necessary	53.00 FS	*- FS
12	1		*REAR LID SENSOR HOLDER	Not Necessary	142.00 FS	*- FS
13	1		*REAR BUMPER GUIDE - RHS	Not Necessary	71.00 FS	*- FS
14	1		*REAR NUMBER PLATE PACKING PIECE	Necessary	15.00 FS	*11.60 FS
15	1		*AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
16	1		*QS EMBLEM	Necessary	83.00 FS	*66.16 FS
17	1		*TFSI EMBLEM	Necessary	83.00 FS	*66.16 FS
18	1		*QUATTRO EMBLEM	Necessary	83.00 FS	*66.16 FS
19	1		*REAR WHEEL ARCH TRIM - LHS / RHS	Necessary	910.00 FS	*727.20 FS
20	16		*WHEEL ARCH TRIM CLIPS	Necessary	34.00 FS	*26.88 FS
21	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
22	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
23	1		*BUMPER TAIL LIGHT - LHS	Cracked	494.80 FS	*494.80 FS
Total Parts (S\$)					9,980.80	5,840.56

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID & REAR LID KICK SENSOR. CHECK FUNCTION.	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER ASSY. TO REPAIR REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,400.00	750.00
3	TO RESPRAY REAR BUMPER, REAR LOWER SPOILER, REAR LID AND BOTH WHEEL ARCH TRIM.	New	2,800.00	1,860.00
4	TO CARRY DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			4,752.00	3,162.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >