

ASS. REC. BY:

REF:

A/G/1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1.9.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S140 389m

Yr Regn:

06/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Renault Latitude

c.c

1895

Colour:

m. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

408338

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF/ABL/5AUC 28.2697

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

11/4/18

D.O.I.

13/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/11

File pass to Catherine

P/P - \$7289.41 (Red \$35102.11 / 83%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18020612/Kfb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 14-11-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGZ 1118T	Veh. Inspected	SHD 389M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/11/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/11/2018	Inspection Date	13/11/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 389M**AAD1811-090***Not Authored
Resony B4 paint*

Vehicle No.:	SHD 389M
Chassis No.:	VF1ABL15AUC282697
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	11.11.2018
Third Party Insurer :	AIG

PART		LIST	
1	DOOR PANEL REAR LH	\$	<i>B</i> 2,844.66
1	DOOR GUIDE REAR LH	\$	<i>SL</i> 176.82
1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
1	DOOR CHECK REAR LH	\$	<i>SL</i> 203.06
1	DOOR LOCK REAR LH	\$	<i>R</i> 908.75
1	DOOR HANDLE OUTER REAR LH	\$	<i>SL</i> 126.49
1	DOOR HANDLE CAP REAR LH	\$	<i>SL</i> 35.52
1	DOOR HANDLE SEAL REAR LH	\$	<i>SL</i> 7.89
1	DOOR HANDLE COVER REAR LH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE REAR LH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR REAR LH	\$	<i>R</i> 1,135.10
1	DOOR REGUALTOR MOTOR REAR LH	\$	<i>SL</i> 893.75
1	DOOR REGULATOR NUT REAR LH	\$	<i>SL</i> 12.43
1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	<i>SL</i> 6.31
1	DOOR FINISHER REAR LH	\$	<i>SL</i> 423.10
1	DOOR MOULDING REAR LH	\$	<i>SL</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>~</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>~</i> 6.91
1	DOOR CASING REAR LH	\$	<i>SL</i> 1,509.06
1	DOOR WATER SHIELD REAR LH	\$	<i>SL</i> 30.39
1	DOOR CASING CLIP	\$	<i>~</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>SL</i> 48.74
1	DOOR FINISHER INNER REAR LH	\$	<i>SL</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i> 20.33
1	DOOR GRAB HANDLE REAR LH	\$	<i>SL</i> 210.96

Trans-cab Auto Services Pte Ltd

AAD1811-090

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 389M

1	DOOR BLIND REAR LH	\$	Sn	741.80	X
1	DOOR WHEATHESTRIIP REAR LH	\$	Sn	410.66	X
1	DOOR SEAL REAR LH	\$	Sn	162.02	X
1	DOOR GLASS RUNNER SEAL REAR LH	\$	Sn	229.31	X
1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn	334.69	X
1	DOOR WAIST SEAL INNER REAR LH	\$	Sn	115.64	X
1	FENDER PANEL REAR LH	\$	B7	3,299.13	✓
1	FENDER PANEL INNER TRIM REAR	\$	Sn	671.45	} X
1	WHEELARCH REAR LH	\$	Sn	543.47	
1	ROCKER PANEL INNER GARNISH LH	\$	Sn	466.51	
1	ROCKER PANEL INNER LH	\$	n	1,024.79	
1	ROCKER PANEL CENTER LH	\$	n	990.25	
1	WHEEL HOUSING PANEL REAR LH	\$	n	4,682.09	
1	CHASSIS PANEL REAR LH L70Y	\$	n	3,766.43	
1	HEADLAMP LH	\$	Sn	1,184.43	
1	BUMPER COVER REAR	\$	Sn	1,108.46	
1	BUMPER LOWER REAR	\$	Sn	768.84	
1	BUMPER BRACKET CTR REAR	\$	Sn	113.47	
1	BUMPER BRACKET SIDE LH REAR	\$	Sn	135.97	
1	BUMPER RETAINER LH REAR	\$	Sn	44.99	
1	FUEL FLAP L70Y	\$	Sn	343.57	

\$	31,066.54
----	------------------

10% \$	3,106.65
--------	-----------------

\$	27,959.89
----	------------------

Special Nett

1	REAR DOOR STICKER '6555 3333'	\$	n	80.00	605n
1	DOOR CHECK BOLT	\$	n	22.69	} X
1	DOOR GUIDE SCREW	\$	n	10.85	
1	DOOR HINGE BOLT	\$	n	10.85	
1	DOOR HINGE NUT RH	\$	n	14.60	
1	DOOR CHECK BOLT	\$	n	22.69	
1	DOOR CHECK NUT	\$	n	3.75	
1	DOOR LOCK SCREW L70Y	\$	n	6.12	
1	DOOR CATCH SCREW L70Y	\$	n	10.06	

TOTAL \$	181.63
-----------------	---------------

Trans-cab Auto Services Pte Ltd

AAD1811-090

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 389M

TOTAL PARTS	\$	28,141.52
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	800
Putty and spray painting of the affected portion.	\$	6,000.00	660
To rust-proofing of the affected areas.	\$	170.00	60
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	100
To check steering geometry and computer wheel alignment	\$	220.00	~ ~ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ ~ X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	~ ~ X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	380.00	~ ~ X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60

TOTAL	\$	14,250.00
--------------	-----------	------------------

Over All Total	\$	42,391.52
-----------------------	-----------	------------------

PART-BY-PART (REPAIR DAY)**20 DAYS**

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Not damaged by Repairer

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD389M

Vehicle to be Exported: Yes

Intended Deregistration Date: 12 Nov 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C003061

Chassis No.: VF1ABL15AUC282697

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 10 Jun 2016

First Registration Date: 10 Jun 2016

Transfer Count: 0

Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 09 Jun 2024

PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date: 09 Jun 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$37,164.00

COE Rebate Amount: \$25,903.00

Total Rebate Amount: \$40,901.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Nov 2018

OK

View Received Message

This mail is associated with :

***SHD389M (3951852797SG)
[SGZ1118T]**

TP

TRANS-CAB SERVICES PTE LTD

Nov 11 2018 9:00PM

[CHEW YI]

Trans-cab Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/12/2019 16:17 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8221.56) - SHD389M - Claim Handler: Lee, Ming-Yao

Approved:8221.56.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Nov 2018 Edit Reg		13 Nov 2018 00:00 Edit Adj Rpt	S\$7,289.41 Edit Estimates	S\$7,289.41 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	CHEW YI, ID: S7040641A		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD389M	Date of Loss:	11/11/2018 21:00 - :59 [29 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3951852797SG	Policy/Cover Note No.:	2100463207 (Comprehensive) Coverage: 05/05/2018 - 04/05/2019
Vehicle Reg. No. (Insured):	SGZ1118T	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (02/12/2019): Alert - Adj Mandate Approved (S\$8221.56) - SHD389M - Claim Handler: Lee, Ming-Ya...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SHD389M (3951852797SG)**
[SGZ1118T]
TP
TRANS-CAB SERVICES PTE LTD
Nov 11 2018 9:00PM
[CHEW YI]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 11:29	General View	 Load JPG	☒
2	17/06/19 11:29	General View	 Load JPG	☒
3	17/06/19 11:29	General View	 Load JPG	☒
4	17/06/19 11:29	General View	 Load JPG	☒
5	17/06/19 11:29	General View	 Load JPG	☒
6	17/06/19 11:29	General View	 Load JPG	☒
7	17/06/19 11:29	General View	 Load JPG	☒
8	17/06/19 11:29	General View	 Load JPG	☒
9	17/06/19 11:29	General View	 Load JPG	☒
10	17/06/19 11:29	General View	 Load JPG	☒
11	17/06/19 11:29	General View	 Load JPG	☒
12	17/06/19 11:29	General View	 Load JPG	☒
13	17/06/19 11:29	General View	 Load JPG	☒
14	17/06/19 11:29	General View	 Load JPG	☒
15	17/06/19 11:29	General View	 Load JPG	☒
16	17/06/19 11:29	General View	 Load JPG	☒
17	17/06/19 11:29	General View	 Load JPG	☒
18	17/06/19 11:53	Reinspection Photo	 Load JPG	☒
19	17/06/19 11:53	Reinspection Photo	 Load JPG	☒
20	17/06/19 11:53	Reinspection Photo	 Load JPG	☒
21	17/06/19 11:53	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/11/18 16:22	TP ESTIMATE- MARKED	 Load PDF	
2	14/11/18 16:22	TP GIA REPORT	 Load PDF	
3	23/10/19 10:29	LETTER TO OI	 Load PDF	
4	23/10/19 10:29	LOD	 Load PDF	
5	23/10/19 10:29	LTA SEARCH	 Load PDF	
6	23/10/19 10:29	RENTAL MILEAGE	 Load PDF	
7	23/10/19 10:29	RENTAL RECEIPT	 Load PDF	
8	11/12/19 08:53	AUTHORISATION TO ACT	 Load PDF	
9	11/12/19 08:53	RELEASE VOUCHER	 Load PDF	
10	11/12/19 08:53	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/11/18 16:00	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST**Reset** **Save** **Print**

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGZ1118T (Insd veh)	Model:	RENAULT LATITUDE 2.0 L (A)
	SHD389M (TP veh)		
Date of Accident:	11/11/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$		45,358.91
Final Repair Cost	:	\$		7,799.67
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		414.40
LTA / GIA Search Fee	:	\$		7.49
Others:	:	\$		
	:	\$		
Final Settlement Sum	:	\$		8,221.56

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown				
1)	Trans-Cab Auto Services Pte Ltd	:	\$	8,221.56
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

11 Dec
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18020612/KDB3S2

Date: 11/12/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100463207
Claimant Vehicle No :	SHD389M	Insured Vehicle No :	SGZ1118T
Date of Loss:	11/11/2018	Nature of Claim:	TP
		Claim No:	3951852797SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD389M		
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Engine No:	M9R8839C003061
Reg. Date:	10/06/2016 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC282697
Colour:	Metallic White/Red	Odometer:	408338 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,141.50	5,589.41	22,552.09	80.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,250.00	1,700.00	12,550.00	88.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	42,391.50	7,289.41	35,102.09	82.80
+ GST 7.00/7.00% (S\$)	2,967.41	510.26	2,457.15	82.80
Nett Amount (S\$)	45,358.91	7,799.67	37,559.24	82.80
+ Car Rental (4.0 x S\$103.60/day) (S\$)		414.40		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		8,221.56		

INSPECTION

Date of Assignment:	13/11/2018	
Date Inspected:	13/11/2018	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR LH	Bent	2,844.66 FL	*2,844.66 FL
2	1		*DOOR GUIDE REAR LH	Serviceable	176.82 FL	*- FL
3	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
4	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
5	1		*DOOR CHECK REAR LH	Serviceable	203.06 FL	*- FL
6	1		*DOOR LOCK REAR LH	Repair	908.75 FL	*- FL
7	1		*DOOR HANDLE OUTER REAR LH	Serviceable	126.49 FL	*- FL
8	1		*DOOR HANDLE CAP REAR LH	Serviceable	35.52 FL	*- FL
9	1		*DOOR HANDLE SEAL REAR LH	Serviceable	7.89 FL	*- FL
10	1		*DOOR HANDLE COVER REAR LH	Serviceable	13.22 FL	*- FL
11	1		*DOOR HANDLE MODULE REAR LH	Serviceable	133.60 FL	*- FL
12	1		*DOOR REGULATOR REAR LH	Repair	1,135.10 FL	*- FL
13	1		*DOOR REGULATOR MOTOR REAR LH	Serviceable	893.75 FL	*- FL
14	1		*DOOR REGULATOR NUT REAR LH	Serviceable	12.43 FL	*- FL
15	1		*DOOR REGULATOR MOTOR SCREW REAR L70Y	Serviceable	6.31 FL	*- FL
16	1		*DOOR FINISHER REAR LH	Serviceable	423.10 FL	*- FL
17	1		*DOOR MOULDING REAR LH	Serviceable	176.82 FL	*- FL
18	1		*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*- FL
19	1		*DOOR MOULDING SCREW L70Y	Not Necessary	6.91 FL	*- FL
20	1		*DOOR CASING REAR LH	Serviceable	1,509.06 FL	*- FL
21	1		*DOOR WATER SHIELD REAR LH	Serviceable	30.39 FL	*- FL
22	1		*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
23	1		*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*- FL
24	1		*DOOR FINISHER INNER REAR LH	Serviceable	323.44 FL	*- FL
25	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	46.97 FL	*- FL
26	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
27	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
28	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
29	1		*DOOR GRAB HANDLE REAR LH	Serviceable	210.96 FL	*- FL
30	1		*DOOR BLIND REAR LH	Serviceable	741.80 FL	*- FL
31	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	410.66 FL	*- FL
32	1		*DOOR SEAL REAR LH	Serviceable	162.02 FL	*- FL
33	1		*DOOR GLASS RUNNER SEAL REAR LH	Serviceable	229.31 FL	*- FL
34	1		*DOOR WAIST SEAL OUTER REAR LH	Serviceable	334.69 FL	*- FL
35	1		*DOOR WAIST SEAL INNER REAR LH	Serviceable	115.64 FL	*- FL
36	1		*FENDER PANEL REAR LH	Bent	3,299.13 FL	*3,299.13 FL
37	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
38	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
39	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
40	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
41	1		*ROCKER PANEL CENTER LH	Repair	990.25 FL	*- FL
42	1		*WHEEL HOUSING PANEL REAR LH	Repair	4,682.09 FL	*- FL
43	1		*CHASSIS PANEL REAR LH L70Y	Repair	3,766.43 FL	*- FL
44	1		*HEADLAMP LH	Serviceable	1,184.43 FL	*- FL
45	1		*BUMPER COVER REAR	Serviceable	1,108.46 FL	*- FL
46	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
47	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
48	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
49	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
50	1		*FUEL FLAP L70Y	Serviceable	343.57 FL	*- FL
51	1		*REAR DOOR STICKER 6555 3333	Necessary	80.00 FS	*60.00 FS
52	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
53	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
54	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
55	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
57	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
58	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS
59	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	31,248.16	6,203.79
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,106.66	614.38
Total Parts (\$\$)	28,141.50	5,589.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	6,000.00	800.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	660.00
3	TO RUST-PROOFING OD THE AFFECTED AREAS.	New	170.00	60.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	100.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
8	TO TRANSFER REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
9	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
10	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	60.00
Gross Labour Cost (\$\$)			14,250.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >