

Transcab Auto Services Pte Ltd

Nò. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 389M**AAD1811-090***Not Authored
Resony B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 389M

VF1ABL15AUC282697

RENAULT

LATITUDE

11.11.2018

AIG

PART		LIST	
1	DOOR PANEL REAR LH	\$	<i>B</i> 2,844.66
1	DOOR GUIDE REAR LH	\$	<i>SL</i> 176.82
1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
1	DOOR CHECK REAR LH	\$	<i>SL</i> 203.06
1	DOOR LOCK REAR LH	\$	<i>R</i> 908.75
1	DOOR HANDLE OUTER REAR LH	\$	<i>SL</i> 126.49
1	DOOR HANDLE CAP REAR LH	\$	<i>SL</i> 35.52
1	DOOR HANDLE SEAL REAR LH	\$	<i>SL</i> 7.89
1	DOOR HANDLE COVER REAR LH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE REAR LH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR REAR LH	\$	<i>R</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>SL</i> 893.75
1	DOOR REGULATOR NUT REAR LH	\$	<i>SL</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>SL</i> 6.31
1	DOOR FINISHER REAR LH	\$	<i>SL</i> 423.10
1	DOOR MOULDING REAR LH	\$	<i>SL</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>nn</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>nn</i> 6.91
1	DOOR CASING REAR LH	\$	<i>SL</i> 1,509.06
1	DOOR WATER SHIELD REAR LH	\$	<i>SL</i> 30.39
1	DOOR CASING CLIP	\$	<i>nn</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>SL</i> 48.74
1	DOOR FINISHER INNER REAR LH	\$	<i>SL</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>R</i> 20.33
1	DOOR GRAB HANDLE REAR LH	\$	<i>SL</i> 210.96

Transcab Auto Services Pte Ltd**AAD1811-090**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 389M

1	DOOR BLIND REAR LH	\$	<i>SL</i> 741.80	X
1	DOOR WHEATHESTRIIP REAR LH	\$	<i>SL</i> 410.66	X
1	DOOR SEAL REAR LH	\$	<i>SL</i> 162.02	X
1	DOOR GLASS RUNNER SEAL REAR LH	\$	<i>SL</i> 229.31	X
1	DOOR WAIST SEAL OUTER REAR LH	\$	<i>SL</i> 334.69	X
1	DOOR WAIST SEAL INNER REAR LH	\$	<i>SL</i> 115.64	X
1	FENDER PANEL REAR LH	\$	<i>SL</i> 3,299.13	✓
1	FENDER PANEL INNER TRIM REAR	\$	<i>SL</i> 671.45	}
1	WHEELARCH REAR LH	\$	<i>SL</i> 543.47	
1	ROCKER PANEL INNER GARNISH LH	\$	<i>SL</i> 466.51	
1	ROCKER PANEL INNER LH	\$	<i>SL</i> 1,024.79	
1	ROCKER PANEL CENTER LH	\$	<i>SL</i> 990.25	
1	WHEEL HOUSING PANEL REAR LH	\$	<i>SL</i> 4,682.09	
1	CHASSIS PANEL REAR LH L70Y	\$	<i>SL</i> 3,766.43	
1	HEADLAMP LH	\$	<i>SL</i> 1,184.43	
1	BUMPER COVER REAR	\$	<i>SL</i> 1,108.46	
1	BUMPER LOWER REAR	\$	<i>SL</i> 768.84	
1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	}
1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	
1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	
1	FUEL FLAP L70Y	\$	<i>SL</i> 343.57	

\$ 31,066.5410% **\$ 3,106.65****\$ 27,959.89****Specical Nett**

1	REAR DOOR STICKER '6555 3333'	\$	<i>na</i> 80.00	<i>base</i>
1	DOOR CHECK BOLT	\$	<i>na</i> 22.69	}
1	DOOR GUIDE SCREW	\$	<i>na</i> 10.85	
1	DOOR HINGE BOLT	\$	<i>na</i> 10.85	
1	DOOR HINGE NUT RH	\$	<i>na</i> 14.60	
1	DOOR CHECK BOLT	\$	<i>na</i> 22.69	
1	DOOR CHECK NUT	\$	<i>na</i> 3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>na</i> 6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>na</i> 10.06	

TOTAL \$ 181.63

Transcab Auto Services Pte Ltd

AAD1811-090

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 389M

TOTAL PARTS	\$	28,141.52
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	8001
Putty and spray painting of the affected portion.	\$	6,000.00	6601
To rust-proofing of the affected areas.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
To check steering geometry and computer wheel alignment	\$	220.00	~ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	~ X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	380.00	~ X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	601

TOTAL	\$	14,250.00
--------------	-----------	------------------

Over All Total	\$	42,391.52
-----------------------	-----------	------------------

PART-BY-PART (REPAIR DAY)**20 DAYS**

6 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date: