

15/02/10

INS. CASE OWNER:

CC

AIG1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age: HUA TONG TEK MANJERRY

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass, Lia:

Repair Cost:

\$

Loss of Rental (LOR):

\$

(\$

days)

Loss of Use (LOU):

\$

(\$

x days)

Loss of Income (LOI):

\$

(\$

x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LO ☐

(Tick only one)

GIA/LTA Search

\$

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 320 w

CRP SENT

11/6/19

Reject Case

By (staff): Hsiao Tong

Approved by: Yur

Date: 11-03-19

01 ✓ video.

01 video, old made left turn

with green light turn arrow,

TP was making U-turn

04-03-19 NO U TURN SIGN IS LOCATED AT THE JUNCTION FOR TP TO MAKE A U TURN. TP IS TO BE BLAMED FOR MAKING ILLEGAL U TURN. SO TO REJECT TP CLAIM.

11/4/19 File - Schupritula

ASS. REC. BY:

REF:

AIG

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1. B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 653A

Yr Regn:

0717

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Pencut Lorry

c.c.

1.995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

408338

T/Radio:

Insured / Std / NI / NA

Eng/No:

176840

C/No:

VIFIABL15AUC

783503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

11/11/18

D.O.I.

13/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/11

File pass to Catherine

PIP \$ 3211.95 (Reel \$ 14654.05 / 839)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fuels

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18020613/Kpb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 14-11-2018



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 8901T	Veh. Inspected	SHD 653A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/11/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	11/11/2018	Inspection Date	13/11/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**Trans-cab Auto Services Pte Ltd**

AAD1811-081

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 653A***Not Notation**Reserve B4 paint*

Vehicle No.:

**SHD 653A**

Chassis No.:

VF1ABL15AUC283503

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

11.11.2018

Third Party Insurer :

**AIG****PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>CM</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	<i>wm</i> 394.68 X
4	1	BUMPER RETAINER FRT LH	\$	<i>h</i> 151.41X
5	1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Sm</i> 150.77 X
7	1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>CM</i> 207.21 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	<i>se</i> 914.08 X
13	1	TOW COVER FRT	\$	<i>Sm</i> 28.61 X
14	1	RADIATOR GRILLE	\$	<i>Sm</i> 1,707.78 X
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>wm</i> 225.36 X
16	1	RADIATOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75 X
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sm</i> 615.90 X
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>n</i> 89.79 X
19	1	HEADLAMP LH	\$	<i>mgcm</i> 1,184.43 ✓
20	1	HEADLAMP PANEL FRT LH	\$	<i>n</i> 152.15 X
21	1	FENDER PANEL FRT LH	\$	<i>n</i> 783.83 X

<b>TOTAL</b>	<b>\$</b>	<b>10,595.53</b> ✓
<b>10%</b>	<b>\$</b>	<b>1,059.56</b>
	<b>\$</b>	<b>9,536.00</b>

*9535.97*

**Trans-cab Auto Services Pte Ltd****AAD1811-081**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 653A****Specical Nett**

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
2	1SET	BUMPER CLIP FRT	\$	na	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
7	1	TOW COVER FRT	\$	sm	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	} X
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
21	1	Windscreen moulding	\$	na	100.00	} X
22	1SET	Front licence plate with holder	\$	sm	80.00	

<b>TOTAL</b>	<b>\$</b>	<b>540.00</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>10,076.00</b>

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,450.00 *3001*

To apply paint protection system (PPS) maintain and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 2,200.00 *4401*

To rust-proofing of the affected areas.

\$ na 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

To check steering geometry and computer wheel alignment

\$ na 220.00 X

**Trans-cab Auto Services Pte Ltd**

AAD1811-081

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 653A

To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2d/
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↷ 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	↷ 380.00	X
To replace, refix and top up coolant for radiator	\$	↷ 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	↷ 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	↷ 170.00	X

<b>TOTAL</b>	<b>\$</b>	<b>7,790.00</b>
--------------	-----------	-----------------

<b>Over All Total</b>	<b>\$</b>	<b>17,866.00</b>
-----------------------	-----------	------------------

**(PART-BY-PART) Repair Days**

7 DAYS

17865.97

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Hsiao Tong (LKKAUTO)

---

**From:** Ng, Hai-Chuan <Hai-Chuan.Ng@aig.com>  
**Sent:** Thursday, 7 March 2019 2:39 PM  
**To:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: CLaim No: 8675806437SG \*LKK REF: CC3/LCR18020613/Kpb3

Please proceed to reject the claim.

Regards,

**Ng Hai Chuan**  
**AIG**  
Senior Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +(65)6419 1994

[Hai-Chuan.Ng@aig.com](mailto:Hai-Chuan.Ng@aig.com) | [www.aig.sg](http://www.aig.sg)

**AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.**  
**[Click here to find out more.](#)**

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** Hsiao Tong (LKKAUTO) [mailto:[chewht@lkkauto.com](mailto:chewht@lkkauto.com)]  
**Sent:** Thursday, March 07, 2019 2:34 PM  
**To:** Ng, Hai-Chuan  
**Subject:** RE: CLaim No: 8675806437SG \*LKK REF: CC3/LCR18020613/Kpb3

Hi Mr Ng,

We refer to the above matter.

We have reviewed the matter and we are of the view that our driver is not liable for the accident. The traffic light was green with green arrow which means OID has the right of way. In addition, there was no U-turn sign is located at the junction for third party to make a U-turn. Third party is to be blamed for making illegal U-turn.

In view of this, we are intending to reject third party claim.

Kindly let us have your comments/ instruction.



Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng, Hai-Chuan <Hai-Chuan.Ng@aig.com>

**Sent:** Wednesday, 21 November 2018 9:59 AM

**To:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

**Subject:** CLaim No: 8675806437SG

Dear all,

OI video footage in Merimen.

Please establish liability before settlement.

Regards,

**Ng Hai Chuan**

**AIG**

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +(65)6419 1994| Fax +68357416

[Hai-Chuan.Ng@aig.com](mailto:Hai-Chuan.Ng@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Sunday, 10 March 2019 3:14 PM  
**To:** 'jasminetan@transcab.com.sg'; claims@transcab.com.sg; 'Ng Wai Yin'  
**Cc:** Admin A; Kenneth Kong (LKKAuto)  
**Subject:** <REJECTION> Your Ref: AAD1811-081 (SHD653A) \*Our Ref: CC3/LCR18020613/Kpb3 [ACCIDENT INVOLVING SLG 8901T(AIG) & SHD 653A ON 11/11/2018]  
**Attachments:** SHD 653A vs SLG 8901T - OI VIDEO.MP4; Statement of SLG8901T.pdf

Your Ref: **AAD1811-081 (SHD653A)**  
Our Ref: CC3/LCR18020613/Kpb3

Without Prejudice

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SLG 8901T(AIG) & SHD 653A ON 11/11/2018**

We refer to the above matter.

Attached is a copy of our insured car video footage and accident statement for your easy reference. We have reviewed the matter and we are of the view that our driver is not liable for the accident. The traffic light was green with green arrow which means our driver has the right of way. In addition, there was no U-turn sign is located at the junction for your client to make a U-turn. Your client is to be blamed for making illegal U-turn.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

*Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.*

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2018 <a href="#">Edit Reg</a>		13 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,211.95</b> <a href="#">Edit Estimates</a>	<b>S\$3,211.95</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD653A	Date of Loss:	11/11/2018 15:00 - :59 [16 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8675806437SG	Policy/Cover Note No.:	0999994766 (Comprehensive)
Vehicle Reg. No. (Insured):	SLG8901T	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Ng, Hai-Chuan</b> ] Hai-Chuan.Ng@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 23/11/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SHD653A (8675806437SG)**  
**[SLG8901T]**  
**TP**  
**TRANS-CAB SERVICES PTE LTD**  
**Nov 11 2018 3:00PM**  
**[LCRF PTE LTD]**  
**Trans-cab Auto Services Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View** [View in Browser](#)





Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/11/18 09:58	<b>Video - Accident</b> From: SC - Reg. No: SLG8901T, Claimant: LCRF PTE LTD	Load MP4	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	28/11/18 15:05	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	28/11/18 15:05	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
13	28/11/18 15:05	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
14	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
15	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
16	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
17	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
18	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
19	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
20	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
21	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
22	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
23	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
24	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
25	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
26	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
27	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
28	10/03/19 15:09	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/11/18 16:20	<b>TP ESTIMATE- MARKED</b>	Load PDF	

Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
2	14/11/18 16:20	TP GIA REPORT		Load PDF
3	10/03/19 15:06	Email from AIG dd 070319		Load PDF
4	10/03/19 15:15	Email to TP_rejection dd 100319		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	15/11/18 15:51	OI GIA REPORT		Load PDF

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18020613/KPB3S2

Date: 23/05/2019

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994766
Claimant Vehicle No :	SHD653A	Insured Vehicle No :	SLG8901T
Date of Loss:	11/11/2018	Nature of Claim:	TP
		Claim No:	8675806437SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD653A	Engine No:	M9R8839C003205
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC283503
Reg. Date:	03/07/2017 (Man. Year: 2016)	Odometer:	176840 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,075.97	2,451.95	7,624.02	75.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,790.00	760.00	7,030.00	90.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>17,865.97</b>	<b>3,211.95</b>	<b>14,654.02</b>	<b>82.02</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,250.62</b>	<b>224.84</b>	<b>1,025.78</b>	<b>82.02</b>
<b>Nett Amount (\$\$)</b>	<b>19,116.59</b>	<b>3,436.79</b>	<b>15,679.80</b>	<b>82.02</b>

## INSPECTION

Date of Assignment:	13/11/2018	
Date Inspected:	13/11/2018	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Cracked	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Not Necessary	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*- FL
7	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
10	1		*BUMPER FOG LAMP GRILLE LH	Cracked	207.21 FL	*207.21 FL
11	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
12	1		*BUMPER BEAM FRT	Serviceable	914.08 FL	*- FL
13	1		*TOW COVER FRT	Serviceable	28.61 FL	*- FL
14	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
15	1		*RADIATOR GRILLE BADGE RENAULT	Not Necessary	225.36 FL	*- FL
16	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
17	1		*FAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
18	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
19	1		*HEADLAMP LH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
20	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
21	1		*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
22	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
23	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
24	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
25	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
26	1		*TOW COVER FRT	Serviceable	14.50 FS	*- FS
27	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
28	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
29	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
30	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
31	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
32	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
33	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>11,135.52</b>	<b>2,717.06</b>
- List Item Discount on L Items 10.00/10.00% (S\$)	1,059.55	265.11

<b>Total Parts (S\$)</b>	<b>10,075.97</b>	<b>2,451.95</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	2,450.00	300.00
2	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	2,200.00	440.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
9	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	New	380.00	0.00
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
11	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	New	380.00	0.00
12	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	New	170.00	0.00
13	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	New	170.00	0.00
14	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>7,790.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >