

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 653A**AAD1811-081***Not Notarised*
Reserve B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 653A

VF1ABL15AUC283503

RENAULT

LATITUDE

11.11.2018

AIG

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>CM</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	394.68 ?
4	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 151.41 X
5	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77 X
7	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>CM</i> 207.21 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	914.08 ?
13	1	TOW COVER FRT	\$	<i>Sn</i> 28.61 X
14	1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78 X
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36 X
16	1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75 X
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90 X
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>n</i> 89.79 X
19	1	HEADLAMP LH	\$	<i>mgcm</i> 1,184.43 ✓
20	1	HEADLAMP PANEL FRT LH	\$	<i>n</i> 152.15 X
21	1	FENDER PANEL FRT LH	\$	<i>n</i> 783.83 X

TOTAL	\$	10,595.55
10%	\$	1,059.56
	\$	9,536.00

Trans-cab Auto Services Pte Ltd**AAD1811-081**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 653A**Specical Nett**

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
2	1SET	BUMPER CLIP FRT	\$	na	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
7	1	TOW COVER FRT	\$	na	14.50	
8	1SET	RADIATOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	} X
21	1	Windscreen moulding	\$	na	100.00	
22	1SET	Front licence plate with holder	\$	na	80.00	

TOTAL	\$	540.00
TOTAL PARTS	\$	10,076.00

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,450.00	3001
To apply paint protection system (PPS) maintain and enhancement	\$	na	380.00 X
Putty and spray painting of the affected portion.	\$	2,200.00	4401
To rust-proofing of the affected areas.	\$	na	170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X

Trans-cab Auto Services Pte Ltd

AAD1811-081

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 653A

To transfer of tire, rim and on wheel balancing.	\$	<i>un</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>2d</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>un</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	<i>7</i> 380.00	X
To replace, refix and top up coolant for radiator	\$	<i>4</i> 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>4</i> 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>4</i> 170.00	X

TOTAL	\$	7,790.00
--------------	-----------	-----------------

Over All Total	\$	17,866.00
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days*7 DAYS**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: