

ASS. REC. BY:

REF: CS/SMO18020617/ Uvd3/n2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

Meimen

From (Person): Ngo Sau Wei shawn

of

SMO

Date/Time: 14/11/18 @ 3:13pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 9549A

Insured:

PC 4973K

at Workshop m/s

Yew Tee Automobile

Tel:

97471475

of

39 Woodlands close # 01-12

Policy No:

D18MTSCBU000015

Claim No:

CMTD1804981

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/11/2018

CA / REV / REP. / REV 24 HRS

(up)

15/11/2018

H.O.D. Endorsement:

Date/Time:

3:27pm 14/11/18

Person Contacted:

sky

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMD 9549A-X

PC 4973K-X

REF: SMO

## ASSIGNMENT

From: Date: 15/11/2018

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMD 9549A  
at Workshop m/s Yew Tee Automobile  
of 39 woodlands close # 01-12

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 30k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up) 5/11/2013  
Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMD 9549A Yr Regn: 6/11/08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Honda stream C.C. 1799

Colour: s. blue A/C: Insured / Std / NI / NA

Sp. Reading: 177374 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RN 6-1084356

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 225/45R17

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 15/11/08 D.O.I. 15/11/08

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4 yrs. 11/11/07 HA 15967

16/11/08 4/5 &amp; 4100 confirmed with Sharm. (Red 5935.32, 5913)

16/11/08 Send preli revised via merimen

RECEIVED 16 NOV 2010

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 16/11 - typist

Report Format: merimen

Lump Sum / I.B.I.: (\$ 4100/2)

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others:

TOTAL

350

10

360

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 16 Nov 2018

**Preliminary Advice**

Insured Vehicle No	: PC4973K		
TP Vehicle No	: SMD9549A	Accident Date	: 12/11/2018
Make	: HONDA STREAM	Assignment Date	: 14/11/2018
Date of Inspection	: 15/11/2018	Est. Duration of Repair	: 5.00
Inspection At	: YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS) 39 WOODLANDS CLOSE #01-12, MEGA@WOODLANDS SINGAPORE 737856		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,035.32
Revised Amount	:S\$	4,100.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,100.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Vehicle survey on "Without Prejudice" basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Nov 2018		14 Nov 2018 15:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	QUAN FENG MOTORS (SINGAPORE) PTE. LTD., Co. Reg. No.: 201715821C		
Vehicle Reg. No.:	SMD9549A	Date of Loss:	12/11/2018 07:00 - :59
Claim Type:	TP / CMTD1804981	Policy/Cover Note No.:	D18MTSCBU000015 (Third Party Only)
Vehicle Reg. No. (Insured):	PC4973K	Policy No. (Claimant):	
		Excess:	
Repairer:	Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands, 737856 Woodlands - Tel: 62562533		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 23/11/2018]</b>		
Driver/Custodian (Insured):	ABDUL RAOF BIN MOHAMED MAGAD (), NRIC: S1251192B, Tel: +6597392049		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Teo, Grace**

---

**From:** Henry, Irene James  
**Sent:** Wednesday, November 14, 2018 1:34 PM  
**To:** Teo, Grace  
**Subject:** FW: SOMPO REF: CMTD1804981/RE: Accident involving SMD9549A & PC4973K on 12.11.18 PRI

---

**From:** YT(HQ) <[info@yewteegroup.com](mailto:info@yewteegroup.com)>  
**Sent:** Wednesday, 14 November, 2018 1:10 PM  
**To:** Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Cc:** YT(HQ) <[info@yewteegroup.com](mailto:info@yewteegroup.com)>  
**Subject:** RE: SOMPO REF: CMTD1804981/RE: Accident involving SMD9549A & PC4973K on 12.11.18 PRI

Hi Henry,

We would like to choose Number 2 Marcus Chua to conduct the pre-repair survey.

Thank you

Best Regards

*Vinnie Lim*



**Yew Tee Automobile Tech Pte Ltd**

HQ:  
Blk 6 Woodlands Road 399F  
Yew Tee Ind. Est  
Singapore 678006  
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895  
Email: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch Office:  
Synergy@KB, 25 Kaki Bukit Road  
Unit No #01-60/61  
Singapore 417800  
DID: 6702 3113  
Email: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

Branch Office:  
39 Woodlands Close,  
#01-12 Mega@Woodlands  
Singapore 737856  
DID: 62562081  
Email: [info@yewteegroup.com](mailto:info@yewteegroup.com)



*please consider the environment before printing this email*

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

**From:** Henry, Irene James [mailto:irene.henry@sompo.com.sg]

**Sent:** Wednesday, 14 November, 2018 10:12 AM

**To:** YT(HQ)

**Cc:** Ngo, Sau Wei Shawn; Teo, Grace

**Subject:** SOMPO REF: CMTD1804981/RE: Accident involving SMD9549A & PC4973K on 12.11.18 PRI

Our Reference : CMTD1804981

Your Reference: SMA 9549A

**Without Prejudice**

Date: 14<sup>TH</sup> November 2018

**Attention:**

**M/S YEW TEE AUTOMOBILE TECH PTE LTD**

Dear Sirs,

**ACCIDENT INVOLVING PC 4973K & SMB 9549A ON 12.11.2018**

We refer to your Notice of Accident via email dated 13.11.2018.

Please be informed that Shawn Ngo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	

		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards  
**Irene Henry**  
 Claims Division

---

**From:** YT(HQ) <[info@yewteegroup.com](mailto:info@yewteegroup.com)>  
**Sent:** Tuesday, 13 November, 2018 3:03 PM  
**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>  
**Cc:** YT(HQ) <[info@yewteegroup.com](mailto:info@yewteegroup.com)>  
**Subject:** Accident involving SMD9549A & PC4973K on 12.11.18 PRI

Hi ,

Kindly arrange PRI at Yew Tee HQ.

Kindly lets us have the surveyor list and the officer-in-charge too.

Thank you

Best Regards

*Vinnie Lim*



**Yew Tee Automobile Tech Pte Ltd**

HQ:  
 Blk 6 Woodlands Road 399F  
 Yew Tee Ind. Est  
 Singapore 678006  
 DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895  
 Email: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch Office:  
 Synergy@KB, 25 Kaki Bukit Road  
 Unit No #01-60/61  
 Singapore 417800  
 DID: 6702 3113  
 Email: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

Branch Office:  
 39 Woodlands Close,  
 #01-12 Mega@Woodlands

Singapore 737856

DID:62562081

Email: [info@yewteegroup.com](mailto:info@yewteegroup.com)



*please consider the environment before printing this email*

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5821C

### Vehicle Details

Vehicle No.:	SMD9549A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	R18A1793608
Chassis No.:	RN61084356
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,683.00
Original Registration Date:	06 Nov 2008
First Registration Date:	06 Nov 2008
Transfer Count:	3
Actual ARF Paid:	\$15,386.00

### Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	05 Nov 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$16,061.00
COE Rebate Amount:	\$15,967.00
<b>Total Rebate Amount:</b>	<b>\$15,967.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Nov 2018

OK

**Inchcape**  
The Chained  
**6303 6303**

**FREE SERVICE & TYRE CREDITS**  
WHEN YOU PURCHASE A CAR FROM INCHCAPE-PREOWNED

**PIT & GO**  
FREE SERVICE & TYRE CREDITS

**VALUE \$1,500**  
FOR PURCHASES BELOW \$10K

**PIT & GO**  
FREE SERVICE & TYRE CREDITS

**VALUE \$3,000**  
FOR PURCHASES ABOVE \$10K



**LEARN MORE**

**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88% p.a. Lowest Interest@GV Cars Financing \$2000 Downpayment Monthly From \$638  
GV Credit Pte Ltd StarAd



Browse by Category

« Back ( 1 2 3 4 5 6 7 ) Next »

Sort by Date Posted

20 results/page

133 vehicles

Honda Stream

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Stream	Any	Any	2008	Any	Any	Any	Available
	Honda Stream 1.8A RSZ (COE till 10/2023)	\$32,800	\$6,650 /yr	23-Oct-2008	1,799 cc	-	MPV	Available
2.88% Per Annum By GV Cars Financing At \$2000 Down Payment From \$638 Lowest Monthly With 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New \$2k Metallic Paint/6 Months Road Tax. Extra A... 2.88% p.a. Lowest Interest@GV Cars Financing \$2000 Downpayment Monthly From \$638 GV Credit Pte Ltd Posted: 16-Nov-2018 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	Honda Stream 1.8A Sunroof (COE till 10/2023)	\$31,800	\$6,440 /yr	25-Oct-2008	1,799 cc	-	MPV	Available
2.88% Per Annum By GV Cars Financing At \$2000 Down Payment From \$638 Lowest Monthly With 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New \$2k Metallic Paint/6 Months Road Tax. Extra A... 2.88% p.a. Lowest Interest@GV Cars Financing \$2000 Downpayment Monthly From \$638 GV Credit Pte Ltd Posted: 16-Nov-2018 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	Honda Stream 1.8A (New 5-yr COE)	\$31,800	\$6,360 /yr	20-Dec-2008	1,799 cc	-	MPV	Available
2.88% Per Annum By GV Cars Financing At \$2000 Down Payment From \$638 Lowest Monthly With 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New \$2k Metallic Paint/6 Months Road Tax. Extra A... 2.88% p.a. Lowest Interest@GV Cars Financing \$2000 Downpayment Monthly From \$638 GV Credit Pte Ltd Posted: 16-Nov-2018 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	Honda Stream 1.8A Sunroof (New 5-yr COE)	\$31,800	\$6,360 /yr	01-Dec-2008	1,799 cc	-	MPV	Available
2.88% Per Annum By GV Cars Financing At \$2000 Down Payment From \$638 Lowest Monthly With 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New \$2k Metallic Paint/6 Months Road Tax. Extra A... GV Credit Pte Ltd Posted: 16-Nov-2018 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
<b>GET YOUR COE RENEWAL LOAN</b> Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Honda Stream 1.8A (New 5-yr COE)	\$31,800	\$6,360 /yr	14-Oct-2008	1,799 cc	-	MPV	Available
2.88% P.a. Nett By GV Cars Financing At \$2000 Down Payment From \$638 Lowest Monthly With 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New \$2k Metallic Paint/6 Months Road Tax. Extra Ad... GV Credit Pte Ltd Posted: 16-Nov-2018 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	Honda Stream 1.8A (COE till 09/2028)	\$52,500	\$5,320 /yr	30-Sep-2008	1,799 cc	120,000 km	MPV	Available
wn Payment! \$800 Plus Monthly! 7 Seater Sporty White Honda Stream For Sale! Smooth Engine, Easy To Maintain Unit, Immaculate Condition, ation Is Even Cheaper, Bank And In House Loan Avail...								

Compare

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

ON BEHALF OF OWNER :

Fax: 62562533

## Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SMD9549A	Excess.	NIL
Policy No.	5102664992	Coverage.	Comprehensive
Claiming Against.	PC4973K	SOMPO	
Insured Under.	NTUC		

## Vehicle Particulars & Condition

Make & Model	Honda Stream
Engine No.	R18A1793608
Chassis No.	RN61084356
Odometer	
Engine CC.	1799
Year Of Reg.	2008
Colour.	SILVER
Parf/COE Rebate.	

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

## Description Of Damages

Rear portion damaged.

## General Information

Accident Date. 12/11/2018  
Survey held at

Yew Tee Automobile Tech Pte Ltd  
Blk 6, #01-399F Woodlands Road, Singapore 678006

## Remarks

KINDLY LET US HAVE THE APPROVAL SOON.

## Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR:

Days

Not Allowed  
Lien  
2/5 # 4100 / 2 confirmed  
15/11/18  
The 2nd After repair  
5 day.  
Tel. 62563561

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

Qty.	Description Of Parts	Pricing
1	Rear bumper 665.40	DS \$ 1,185.00 ✓
1	Rear bumper side retainer LH	11/15 \$ 48.50 ✓
1	Rear bumper side retainer RH 30.90	34 \$ 48.50 ✓
1	Rear bumper bracket LH	11 \$ 20.70 ✓
1	Rear bumper bracket RH	11 \$ 20.70 ✓
1	Rear tailgate 903.20	3.50 \$ 1,160.00 ✓
1	Rear tailgate damper LH	11 \$ 297.00 ✓
1	Rear tailgate damper RH	11 \$ 297.00 ✓
1	Rear tailgate rubber 112.30	3.1 \$ 186.60 ✓
1	Rear tailgate lock 145.50	11/15 \$ 303.80 ✓
1	Rear tailgate lock catch	11 \$ 55.00 ✓
1	Rear tailgate inner board 248.50	20/15 \$ 489.50 ✓
1	Rear windscreen glass moulding	22 \$ 118.50 ✓
1	Rear tailgate stream emblem 36.50	22 \$ 58.00 ✓
1	Rear taillamp RH 338.80	11 \$ 454.30 ✓
1	Rear taillamp panel RH	11 \$ 325.00 ✓
1	Rear fender RH	11 Rpr ✓
1	Rear end panel 316.40	11/15 \$ 685.00 ✓
1	Rear end panel inner garnish	11 \$ 189.50 ✓
1	Rear fender inner trim board RH 435.10	20/15 \$ 628.50 ✓
1	Rear spare tyre board	11 \$ 220.00 ✓
1	Rear exhaust pipe	11 \$ 638.30 ✓
1	Rear exhaust silencer	11 \$ 689.50 ✓
1	Rear exhaust heat shield	11 \$ 80.00 ✓
1	Rear tailgate outer handle	11 \$ 189.00 ✓
		List items \$ 8,387.90
		Less 20% \$ 1,677.58
		Sub Total \$ 6,710.32
1	Rear bumper clips (1 set)	11 \$ 45.00 ✓
1	Rear bumper reverse sensors (1 set)	11 \$ 260.00 200
1	Rear number plate	11 \$ 45.00 ✓
1	Rear tailgate inner board clips (1 set)	11 \$ 40.00 ✓
1	Rear windscreen sealant	11 \$ 60.00 40
1	Rear end panel inner garnish clips (1 set)	11 \$ 35.00 ✓
2	Rear exhaust mountings	11 \$ 60.00 ✓
		S/N \$ 545.00

325

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

Qty.	Description Of Parts	Pricing
<b>LABOUR</b>		
	To apply undercoating on the repaired and replaced panel for rust protection.	\$ 60.00 ✓
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 50.00 30
	To Carry-Out Body Cavity Preservation.	repld \$ 60.00 X
	To remove and refit rear bumper sensors.	\$ 80.00 50
	To dismantle and refit rear windscreen glass.	\$ 100.00 ✓
	To transfer rear tailgate.	\$ 150.00 60
	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	\$ 180.00 60
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 1,100.00 700
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 1,000.00 900
	LABOUR	\$ 2,780.00 1950
	Sub Total.	\$ 10,035.32
	7% GST	\$ 702.47
	Grand Total	\$ 10,737.79

P-3561.30  
20%  
2849.04  
S.N + 325.00  
labour 1957.00  
5725.04

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

4100

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18020617/UVD3N2

Date: 19/11/2018

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTSCBU000015	
Claimant Vehicle No :	SMD9549A	Insured Vehicle No :	PC4973K	
Date of Loss:	12/11/2018	Nature of Claim:	TP	Claim No: CMTD1804981

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SMD9549A	Engine No:	R18A1793608
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61084356
Reg. Date:	06/11/2008 (Man. Year: 2008)	Odometer:	177374 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,255.32	3,174.04	4,081.28	56.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,960.00	820.00	29.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,035.32</b>	<b>5,134.04</b>	<b>4,901.28</b>	<b>48.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
(S\$)	10,035.32	4,100.00	5,935.32	59.14
<b>+ GST 7.00/7.00% (S\$)</b>	<b>702.47</b>	<b>287.00</b>	<b>415.47</b>	<b>59.14</b>
<b>Nett Amount (S\$)</b>	<b>10,737.79</b>	<b>4,387.00</b>	<b>6,350.79</b>	<b>59.14</b>

## INSPECTION

Date of Assignment:	14/11/2018
Date Inspected:	15/11/2018 Inspected At:

Yew Tee Automobile Tech Pte Ltd  
(Woodlands)  
39 Woodlands Close #01-12,  
Mega@Woodlands  
Singapore 737856

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2018)
<b>Parts:</b> M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMD9549A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Distorted	1,185.00 FL	*665.40 FL
2	1	*REAR BUMPER SIDE RETAINER LH	Not Necessary	48.50 FL	*- FL
3	1	*REAR BUMPER SIDE RETAINER RH	Bent	48.50 FL	*30.90 FL
4	1	*REAR BUMPER BRACKET LH	Not Necessary	20.70 FL	*- FL
5	1	*REAR BUMPER BRACKET RH	Bent	20.70 FL	*20.70 FL
6	1	*REAR TAILGATE	Badly Dented	1,160.00 FL	*903.20 FL
7	1	*REAR TAILGATE DAMPER LH	Not Necessary	297.00 FL	*- FL
8	1	*REAR TAILGATE DAMPER RH	Not Necessary	297.00 FL	*- FL
9	1	*REAR TAILGATE RUBBER	Twisted	186.60 FL	*112.30 FL
10	1	*REAR TAILGATE LOCK	Dented/Jammed	303.80 FL	*145.50 FL
11	1	*REAR TAILGATE LOCK CATCH	Not Necessary	55.00 FL	*- FL
12	1	*REAR TAILGATE INNER BOARD	Deformed/Cracked	489.50 FL	*248.50 FL
13	1	*REAR WINDSCREEN GLASS MOULDING	Necessary	118.50 FL	*118.50 FL
14	1	*REAR TAILGATE STREAM EMBLEM	Necessary	58.00 FL	*36.50 FL
15	1	*REAR TAILLAMP RH	Cracked	454.30 FL	*338.80 FL
16	1	*REAR TAILLAMP PANEL RH	Repair	325.00 FL	*- FL
17	1	*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
18	1	*REAR END PANEL	Badly Dented	685.00 FL	*316.40 FL
19	1	*REAR END PANEL INNER GARNISH	Twisted	189.50 FL	*189.50 FL
20	1	*REAR FENDER INNER TRIM BOARD RH	Deformed/Cracked	628.50 FL	*435.10 FL
21	1	*REAR SPARE TYRE BOARD	Not Necessary	220.00 FL	*- FL
22	1	*REAR EXHAUST PIPE	Repair	638.30 FL	*- FL
23	1	*REAR EXHAUST SILENCER	Repair	689.50 FL	*- FL
24	1	*REAR EXHAUST HEAT SHIELD	Not Necessary	80.00 FL	*- FL
25	1	*REAR TAILGATE OUTER HANDLE	Not Necessary	189.00 FL	*- FL
26	1	*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
27	1	*SET REAR BUMPER REVERSE SENSORS	Shorted	260.00 FS	*200.00 FS
28	1	*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
29	1	*SET REAR TAILGATE INNER BOARD CLIPS	Necessary	40.00 FS	*40.00 FS
30	1	*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
31	1	*SET REAR END PANEL INNER GARNISH CLIPS	Not Necessary	35.00 FS	*- FS
32	2	*REAR EXHAUST MOUNTINGS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,932.90</b>	<b>3,886.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,677.58</b>	<b>712.26</b>
<b>Total Parts (\$\$)</b>	<b>7,255.32</b>	<b>3,174.04</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANEL FOR RUST PROTECTION	New	60.00	60.00
2	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS	New	50.00	30.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	60.00	-
4	TO REMOVE AND REFIT REAR BUMPER SENSORS	New	80.00	50.00
5	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
6	TO TRANSFER REAR TAILGATE	New	150.00	60.00
7	TO REMOVE AND REFIT,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	180.00	60.00
8	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,100.00	700.00
9	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS,CLEANING AND SANDING OF SURFACES,FINAL POLISHING & WAXING ARE ALSO AVAILABLE	New	1,000.00	900.00
Gross Labour Cost (\$\$)			<b>2,780.00</b>	<b>1,960.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;