

ASS. REC. BY:

REF:

CS/CTU8020610 / Uthb

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Catherine Trica

of

CTL

Date/Time:

14-11-2018 3:23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBC 2901Y

Insured:

SLJ 7352C

at Workshop m/s

Sun Hook Hin

Tel:

6281 6520 X 220

of

No. 6 Defu Lane 4

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS W/P

15-11-2018

H.O.D. Endorsement:

Date/Time:

14-11-2018 3:40pm

Person Contacted:

Raymond

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FBC 2901Y - NSA / DAL5014036/d

DLA 23192015

SLJ 7352C - X

REF: CTI

ASSIGNMENT

From: Date: 15/11/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: FBC 2901 Y

at Workshop m/s Bon Hock Hin

of No. 6 Defu Lane 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 46.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp' 21/1/2023

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBC 2901 Y Yr Regn: 1 / 08

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SYM GTS200 CC 172

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 89289 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RFGLM18WX75000568

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/90-13

R: 100/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: mm

L/Bal: mm

D.O.A: 13/10/18

D.O.I: 15/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 21/1/2023

No collision 21/1/2023 4y15 34L.

21/4/19 check with repairer vehicle has not send in for repair.

RECEIVED 26 APR 2019

Date/Time, File Pass to?

26/4/2019 Typist

Date/Time, File Return to?

21

Report Format:

Lump Sum / I.B.I. (\$)

☒ : Preli. Report☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee

Transportation

\$ + RS \$

Photos

Other

TOTAL

Catherine Chong (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Wednesday, 14 November, 2018 3:23 PM
To: assignments
Cc: Raymond
Subject: FW: Accident Involving FBC2901Y & SLJ7392C on 18/10/2018
Attachments: 11203_Claim File.pdf

Dear LKK personnel

Kindly send surveyor down to workshop to do the PRI inspection.

We will create in Merimen shortly

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Raymond [mailto:raymond@bhh.com.sg]
Sent: Thursday, 8 November, 2018 12:54 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: FW: Accident Involving FBC2901Y & SLJ7392C on 18/10/2018

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 9051Z

Vehicle Details

Vehicle No.: FBC2901Y

Vehicle to be Exported: No

Intended Deregistration Date: 15 Nov 2018

Vehicle Make: SYM

Vehicle Model: GTS200

Primary Colour: Black

Secondary Colour: Green

Manufacturing Year: 2007

Engine No.: KB600616

Chassis No.: RFGLM18WX75000568

Maximum Power Output: -

Open Market Value: \$2,582.00

Original Registration Date: 22 Jan 2008

First Registration Date: 22 Jan 2008

Transfer Count: 8

Actual ARF Paid: \$388.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 21 Jan 2023

COE Category: D - Motorcycle

COE Period(Years): 5

PQP Paid: \$2,955.00

COE Rebate Amount: \$2,472.00

Total Rebate Amount: \$2,472.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Nov 2018

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBC2901Y		
Vehicle Type :	P01 - Passenger Scooter		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	SYM		
Vehicle Model :	GTS200		
Chassis No. :	RFGLM18WX7S000568		
Propellant :	Petrol		
Engine No. :	KB600616		
Engine Capacity :	172 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	319 kg		
Unladen Weight :	151 kg		
Year Of Manufacture :	2007		
Original Registration Date :	22 Jan 2008		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
PQP Paid :	\$2,955.00		
COE Expiry Date :	21 Jan 2023		
Road Tax Expiry Date :	21 Jan 2019		
Inspection Due Date :	21 Jul 2019		
Intended Transfer Date :	05 Nov 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 21 Jan 2019. You may renew the road tax from 22 Oct 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 21 Jan 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 22 Jan 2019 to 21 Jul 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	39.00	-	39.00
Total Amount Payable :			64.00
Amount Payable (From 22 Jan 2019 to 21 Jan 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	77.00	-	77.00
Total Amount Payable :			102.00
Message			
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33190

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534

DATE : 23/10/2018
CLAIM NO. : 11203
POLICY NO. :
FROM : RAYMOND

VEHICLE NO. : FBC2901Y
MAKE/MODEL : SYM / GTS200

*not attached
dbr
4/5 B
3 dy.
15/11/18
Wm pho Ather kepo*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 29008	REPLACE	1.00	\$38.00	38.00
2	BAR HANDLE P/N: 52791	REPLACE	1.00	\$112.00	112.00
3	BOX REAR SHAD -SH-45L	REPLACE	1.00	\$255.00	255.00
4	COVER P/N: 52816	REPLACE	1.00	\$133.00	133.00
5	COVER BODY RH	REPLACE	1.00	\$110.00	110.00
6	COVER BODY STRIPR	REPLACE	1.00	\$5.00	5.00
7	COVER SIDE LOWER RH (BLACK) P/N: 52811	REPLACE	1.00	\$68.00	68.00
8	COWLING FRONT (BLACK)	REPLACE	1.00	\$175.00	175.00
9	EXHAUSE. MUFFLER ASSY.	REPLACE	1.00	\$858.00	858.00
10	FENDER REAR P/N: 37527	REPLACE	1.00	\$72.00	72.00
11	FLOOR PANEL P/N: 52821	REPLACE	1.00	\$105.00	105.00
12	FOOTBOARD UPPER P/N: 40150	REPLACE	1.00	\$145.00	145.00
13	LABOUR P/N: 06766 - DISMANTLING AND ASSEMBLING OF PARTS	Supply/Install	1.00	\$350.00	350.00



S/N	Description	Action	Qty	Unit Price	Amount
14	LEVER BRAKE RH P/N: 52805	REPLACE	1.00	\$21.00	21.00
15	MIRROR RH P/N: 59118	REPLACE	1.00	\$178.00	178.00
16	MUDGUARD FRONT	REPLACE	1.00	\$84.00	84.00
17	PILLION STEP PIN	REPLACE	1.00	\$15.00	15.00
18	PILLION STEP RH	REPLACE	1.00	\$35.00	35.00
19	SPOILER UNDER FRONT	REPLACE	1.00	\$95.00	95.00
20	SPRAY PAINT COVER BODY RH	Spray	1.00	\$120.00	120.00
21	SPRAY PAINT MUDGUARD FRONT	Spray	1.00	\$65.00	65.00
22	SPRAY PAINT SPOILER UNDER FRONT	Spray	1.00	\$45.00	45.00
23	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	\$35.00	35.00

SUB TOTAL

\$3,119.00

GST @ 7 %

\$218.33

GRAND TOTAL

\$3,337.33

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CERT NO: 2002-1-0383
ISO 9001:2015

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Nov 2018		23 Nov 2018 17:06 Edit Adj Rpt	S\$1,831.00 Edit Estimates	S\$1,831.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	- ID: -								
Main Claimant:	ABDUL HALIM BIN AHMAD								
Vehicle Reg. No.:	FBC2901Y	Date of Loss:	18/10/2018 00:00 - :59 [128 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04989C02	Policy/Cover Note No.:	DMHCSN1691821701						
Vehicle Reg. No. (Insured):	SLJ7392C	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Chia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/12/2018]								
Adj Asg. Remarks:	ASSIGNED VIA EMAIL ON 13/11/2018								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

1/1

Claim Documents

***FBC2901Y (SNM18D04989C02)**
[SLJ7392C]

TP
ABDUL HALIM BIN AHMAD
Oct 18 2018 12:00AM
[-]
Ban Hock Hin Co. Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/05/19 11:25	General View		Load JPG	☒
2	06/05/19 11:25	General View		Load JPG	☒
3	06/05/19 11:25	General View		Load JPG	☒
4	06/05/19 11:25	General View		Load JPG	☒
5	06/05/19 11:25	General View		Load JPG	☒
6	06/05/19 11:25	General View		Load JPG	☒
7	06/05/19 11:25	General View		Load JPG	☒
8	06/05/19 11:25	General View		Load JPG	☒
9	06/05/19 11:25	General View		Load JPG	☒
10	06/05/19 11:25	General View		Load JPG	☒
11	06/05/19 11:25	General View		Load JPG	☒
12	06/05/19 11:25	General View		Load JPG	☒
13	06/05/19 11:25	General View		Load JPG	☒
14	06/05/19 11:25	General View		Load JPG	☒
15	06/05/19 11:25	General View		Load JPG	☒
16	06/05/19 11:25	General View		Load JPG	☒
17	06/05/19 11:25	General View		Load JPG	☒
18	06/05/19 11:25	General View		Load JPG	☒
19	06/05/19 11:25	General View		Load JPG	☒
20	06/05/19 11:25	General View		Load JPG	☒
21	06/05/19 11:25	General View		Load JPG	☒
22	06/05/19 11:25	General View		Load JPG	☒
23	06/05/19 11:25	General View		Load JPG	☒
24	06/05/19 11:25	General View		Load JPG	☒
25	06/05/19 11:25	General View		Load JPG	☒
26	06/05/19 11:25	General View		Load JPG	☒
27	06/05/19 11:25	General View		Load JPG	☒
28	06/05/19 11:25	General View		Load JPG	☒
29	06/05/19 11:25	General View		Load JPG	☒
30	06/05/19 11:25	General View		Load JPG	☒
31	06/05/19 11:25	General View		Load JPG	☒
32	06/05/19 11:25	General View		Load JPG	☒
33	06/05/19 11:25	General View		Load JPG	☒
34	06/05/19 11:25	General View		Load JPG	☒
35	06/05/19 11:25	General View		Load JPG	☒
36	06/05/19 11:25	General View		Load JPG	☒
37	06/05/19 11:25	General View		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/05/19 11:25	General View	 Load JPG	☒
39	06/05/19 11:25	General View	 Load JPG	☒
40	06/05/19 11:25	General View	 Load JPG	☒
41	06/05/19 11:25	General View	 Load JPG	☒
42	06/05/19 11:25	General View	 Load JPG	☒
43	06/05/19 11:25	General View	 Load JPG	☒
44	06/05/19 11:25	General View	 Load JPG	☒
45	06/05/19 11:25	General View	 Load JPG	☒
46	06/05/19 11:25	General View	 Load JPG	☒
47	06/05/19 11:25	General View	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118020620/UTBQ2

Date: 06/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1691821701

Claimant Vehicle
No: FBC2901YInsured Vehicle
No: SLJ7392C

Date of Loss: 18/10/2018

Nature of Claim: TP

Claim
No: SNM18D04989C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBC2901Y

Make & Model: SYM GTS 200, 172cc

Reg. Date: 22/01/2008 (Man. Year: 2007)

Colour: Grey

Engine Capacity: 172 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: KB600616

Chassis No: RFGLM18WX7S000568

Odometer: 89287 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/90-13

Rear Tyre Size:

100/70-12

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,504.00	1,341.00	1,163.00	46.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	615.00	490.00	125.00	20.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,119.00	1,831.00	1,288.00	41.30
+ GST 7.00/7.00% (S\$)	218.33	128.17	90.16	41.30
Nett Amount (S\$)	3,337.33	1,959.17	1,378.16	41.30

INSPECTION

Date of Assignment: 23/11/2018

Date Inspected: 15/11/2018 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 May 2019)	
Parts:	N/A	SYM GTS 200 172cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBC2901Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER HANDLE	Scratched	38.00 F	*38.00 FL
2	1		*BAR HANDLE	Bent	112.00 F	*112.00 FL
3	1		*BOX REAR SHAD -SH-45L	Cut	255.00 F	*255.00 FL
4	1		*COVER	Cracked	133.00 F	*133.00 FL
5	1		*COVER BODY RH	Cut	110.00 F	*110.00 FL
6	1		*COVER BODY STRIPR	Cut	5.00 F	*5.00 FL
7	1		*COVER SIDE LOWER RH (BLACK)	Cut	68.00 F	*68.00 FL
8	1		*COWLING FRONT (BLACK)	Cut	175.00 F	*175.00 FL
9	1		*EXHAUSE,MUFFLER ASSY	Repair	858.00 F	*- FL
10	1		*FENDER REAR	*Check	72.00 F	*- FL
11	1		*FLOOR PANEL	Cut	105.00 F	*105.00 FL
12	1		*FOOTBOARD UPPER	Cut	145.00 F	*145.00 FL
13	1		*LEVER BRAKE RH	Scratched	21.00 F	*21.00 FL
14	1		*MIRROR RH	Cut	178.00 F	*178.00 FL
15	1		*MUDGUARD FRONT	Repair	84.00 F	*- FL
16	1		*PILLION STEP PIN	Cut	15.00 F	*15.00 FL
17	1		*PILLION STEP RH	Cut	35.00 F	*35.00 FL
18	1		*SPOILER UNDER FRONT	Cut	95.00 F	*95.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,504.00	1,490.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	149.00
Total Parts (\$\$)	2,504.00	1,341.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR-DISMANTLING AND ASSEMBLING OF PARTS	New	350.00	250.00
2	SPRAY PAINT COVER BODY RH	New	120.00	100.00
3	SPRAY PAINT MUDGUARD FRONT	New	65.00	60.00
4	SPRAY PAINT SPOILER UNDER FRONT	New	45.00	45.00
5	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD	New	35.00	35.00
Gross Labour Cost (\$\$)			615.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >