

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2931/11/18 Your Ref: Date: 14th NOV 2018

MR KWEEK SIEW CHUAN JASON
83, YISHUN AVE 11, #02-28
SINGAPORE 768864

Estimate cost of repair to BMW 528i (A) 2.0 Saloon - SKV 7108 G

1 pc front bumper		\$ 1,718.00	X
1 pc front bumper n/s side bracket		34.00	X
8 pcs front bumper clips	@ \$ 9.00	72.00	X
1 pc front n/s fender		874.00	X
1 pc front n/s fender chrome moulding		138.00	X
1 pc front n/s fender inner shield garnish		294.00	X
8 pcs front n/s fender shield garnish clips	@ \$ 9.00	72.00	X
1 pc front n/s sport rim	1000S	1,980.00	✓
1 pc front n/s wheel tyre		1,250.00	X
1 pc front n/s door side mirror comp		2,076.00	✓
12 pcs front n/s door inner trim board clips	@ \$ 11.00	132.00	X
		\$ 8,240.00	
	Less 20%	\$ 1,640.00	
		\$ 6,592.00	

To wiring check up for door wiring system.

60.00 30

To check & adjust front wheel alignment & balancing, using computerised.

200.00 80

To diagnose & reset front wheel tyre pressure sensor, front n/s door air-bag sensor.

450.00 X

Labour charge to remove & refix n/s rocker panel garnish, front n/s door inner trim board cover, front n/s door pillar garnish & necessary parts.

250.00 X

To respray Tuff-Kote on all affected accident parts.

100.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front n/s door panel, door pillar panel, front n/s wheel house panel & necessary parts, to weld, renew & align above parts.

1,300.00 400

To putty & respray painting (Pearl colour) on all affected accident parts.

1,700.00 800

\$ 10,652.00

Dollars : Ten Thousand Six Hundred And Fifty Two Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2148

1718-4

40284