

萬 汽 車 服 務

MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782
 Website: <http://www.millionauto.com> Email: wendy@millionauto.com
 Tel: 6567 0817, 6264 9091 Fax: 6791 4716
 Reg No: 317413/00-K GST Reg No: M90363176A

30-Jan-20

EQ Insurance Company Ltd
 22 Gemmill lane
 Singapore 069257

Attention: Motor Claim Department

ESTIMATE COST FOR REPAIR GZ396M TOYOTA DYNA-3.0 D (M)

Tailgate assy	1,218.60
Tailgate "TOYOTA" sticker	138.00
Tailgate stopper bracket LH	100.30
Tailgate lower lock assy	168.20
LH taillamp assy	222.70
LH taillamp bracket	51.60
Rear number plate holding plate	157.60
Subtotal of the above	2,057.00
Discount 25%	514.25
	1,542.75
Tailgate "70 km/h" sticker	15.00
Tailgate aluminium backplate rivet	6.00
Rear number plate	35.00
To check wiring at the affected areas for condition and repair where needed.	40.00
Panel beating charges to dismantle and remove all damaged parts, renew and install the same, to cut out the damaged body, renew and weld the same, to knock and reshape surrounding panels back to shape and alignment.	900.00
Spray paint all affected parts and repaired areas - tailgate, rear deck end panel, rear deck LH side panel, tailgate stopper bracket, step bracket and necessary areas.	1,000.00
To remove and replace reverse sensors and check sensing distance	80.00
Sub total :	3,618.75
GST 7% :	253.31
Total:	\$ 3,872.06