

22/03/2001

ASS. REC. BY:

REF: CS/FCI18020626/Tisd34

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Suren Ler

of

FCI

Date/Time: 14/11/18 3:55pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

SLL 3055S

Insured:

SHA 3919E

at Workshop m/s

Kah Motor

Tel:

82886309

of

255 Alexandra Road

Policy No:

Claim No: D18008047 MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/11/2018

CA / REV / REP. / REV 24 HRS

(DS)

19/11/18 10am @ 10:30am

H.O.D. Endorsement:

Date/Time:

4:10pm @ 14/11/18

Person Contacted:

Juek

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 3055S - X
	SHA 3919E - CS/FCI17019568 / Rlvbn2
21/11/18	@ 16:30 p.m. revised PA to Suren Ler via email.
12/12/18	Confirmed P/P \$15,230.67 @ 14 days with Taufik
	(\$3,555.24 Red - 19%)

MOTOR SURVEY ASSIGNMENT

Date	12-11-2018	Our Ref No.	D18008047MFSH
Accident Date	09-11-2018	Claim Type.	Third Party
Insured Vehicle	SHA3919E	Third Party Vehicle.	SLL3055S
Survey Location	BODY REPAIR & PAINT CENTRE 255 ALEXANDRA ROAD		
Contact Person.	JACK NG		
Contact No.	65145481/ 82886309	Fax No.	63625015
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR - \$19,550.23)		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO. SDN. BHD.	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SERENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



PRI Header Details

Claim No	D18008047MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & KAH MOTOR
Workshop Name	KAH MOTOR CO. SDN. BHD. (Contact Person : JACK NG)	Survey Location & Contact Details	BODY REPAIR & PAINT CENTRE 255 ALEXANDRA ROAD Mobile: 82886309 , Phone: 65145481 , Fax: 63625011 EmailId: JACKNG@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. C		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3919E	TP Vehicle No	SLL3055S
PRI Recieved Date	12-11-2018 05:24:04 PM	Surveyor Appointed Date	14-11-2018 03:54:41 PM	Surveyor Accept Date	14-11-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	14-11-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Date	Job Remarks	Action
------	-------------	--------

FINAL SUMMARY

Surveyor Final Adjusted Amount		Surveyor Fees		Remarks	
---	--	------------------	--	---------	--

Submit Assessment

Shirley Hiew (LKK Auto)

From: Jack Ng <jackng@honda.com.sg>
Sent: Thursday, 13 December 2018 10:35 AM
To: Shirley Hiew (LKK Auto)
Cc: Admin-D (LKKAuto); SUR
Subject: RE: FINALIZATION FOR SLL 3055 S

Dear Shirley,

Ok 14 days of repair.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, December 13, 2018 10:30 AM
To: Jack Ng <jackng@honda.com.sg>
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZATION FOR SLL 3055 S

Hi Jack,

Please re-confirm final fig of \$15,230.67 (part by part) @ 14 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

From: Jack Ng [<mailto:jackng@honda.com.sg>]

Sent: Monday, 10 December 2018 5:36 PM

To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: FINALIZATION FOR SLL 3055 S

Dear all,

We enclosed the total final repair costs for,

Vehicle No.	SLL 3055 S
Final Repair Costs (exclude GST)	S\$15,230.67
Repair Period* (Days)	15 WORKING DAYS

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, 'P' items and supplementary parts (if any) for your records.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



SMILE WIVES FOR
OUR CHILDREN




Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 21 November 2018 4:30 PM
To: 'Serene Ler'; 'CWS Motor Claims'
Cc: 'SUR'; 'Admin-D (LKKAuto)'; 'assignments'
Subject: RE: SURVEY ASSESSMENT - D18008047MFSH/1
Attachments: SLL 3055S - Preli Advise .pdf

Dear Serene,

Enclosed preliminary revised of vehicle SLL 3055S.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 14 November 2018 4:14 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008047MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 19/11/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 14 November 2018 3:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008047MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

✪ **Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008047MFSH

Date: 21 November 2018

Our Ref: CS/FCI18020626/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLL 3055S .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/11/2018 at the premises of M/s Kah Motor Co. Sdn. Bhd. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>18,271.22</u> .
Revised Estimate Amount	: S\$ <u>14,689.19</u> .
"Check" Items Amount	: S\$ <u>1,431.10</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 14 - 15 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/11/2018 16:04
Date Of Accident	09/11/2018 18:40
Exact Location Of Accident	ALONG BENDEMEER ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLL3055S
Insured/Policyholder	
Name Of Registered Owner	KAAN SHEUNG KIN
NRIC No	S1435428Z
Email Address	DRSHEUNG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96884746
Alternative Phone No	OTHERS-96884746
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ 1.5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10729792
Cover Note Number	N.A
Driver	
Name of Driver	KAAN SHEUNG KIN
NRIC No	S1435428Z
Date Of Birth	09/11/1960
Occupation	INDOOR
Date Of Driving Pass	16/04/1979
Driving Experience	39 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96884746
Fax Number	
Contact Number	OTHERS-96884746
EMail Address	DRSHEUNG@GMAIL.COM

Address	HDB TELOK BLANGAH RISE, 43 TELOK BLANGAH RISE #05-628
Postcode	090043
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ANBUMANI GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I (SLL3055S) was stationary along Bendemeer road on the first lane, just before the yellow box when suddenly a taxi (SHA3919E) hit me from the back. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA3919E
Vehicle Make/Model/Colour	HYUNDAI I40 1.7L CRDI / BLU
Details Of Properties	NIL
Vehicle Category	TAXI
Name of Driver	STANLEY OW KUM CHEONG
NRIC/Passport Number	S8620037F
Contact Number	96862213
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Insurer.
3. Information provided must be as truthful and accurate as possible. Any wilful misstatement or omission may be considered as fraud.
4. The issue and acceptance of this form by insurance companies is not an admission of liability.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the Government of Singapore (GIA) for archiving and that copies of this report will for a fee be made available to the Insurers.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the GIA.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, process my personal data/personal information set out in this form and any other personal information provided by me or my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) as the vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANDI BIN
MOHD AFFANDI

Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I (SLL3055S) was stationary along Bendemeer road on the first lane, just before the yellow box when suddenly a taxi (SHA3919E) hit me from the back. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

10 November 2018 at 11:26 AM

Date/Time:

10 November 2018 at 11:26 AM

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLL3055S

Chassis No : JHMGK5850HX201136

Model : JAZZ 1.5VTIR CVT 17YM

Owner's Name : KAAH SHEUNG KIN

Ins Policy No. :

Date of Accident : 9/11/2018

Document No. : SQT18004877 Page 1

Date : 13. Nov 2018

Customer No. : WZF002

Svc Advisor :

Engine No : L15B31190813

Date | Time : 13. Nov 2018 5:20:02 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:KAAH SHEUNG KIN OWNER INSURER:AVIVA LTD ACC DATE:09/11/2018 SURVEYED BY: DATE: REF NO: TP INSURER:MS FIRST CAPITAL TP VEH:SHA 3919 E						
04715-T5A-J50ZZ	FACE,RR.BUMPER	1 de	492.70	25	369.52	25.87	395.39
71505-T5A-J50	GARNISH,RR.BUMPER	1 de	38.30/4.30	25	10.72	28.72	30.73
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1 ne	16.90/11.50	25	8.62	12.67	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1 ne	16.90/11.50	25	8.62	12.67	13.56
71502-T5A-J60	COVER,R.RR.BUMPER	1 ne	20.70 X un	25	15.52	1.09	16.61
71507-T5A-J60	COVER,L.RR.BUMPER	1 X	20.70 un	25	15.52	1.09	16.61
91505-TM8-003	CLIP,BUMPER	7 ne	2.30	25	12.07	0.84	12.91
68100-TAS-Z50ZZ	TAILGATE COMP	1 ht	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1 ?	92.30 ne	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY,TAILGATE	1 ?	78.90 X un	25	59.17	4.14	63.31
74813-T5A-003	STRIKER ASSYTAILGATE	1 ?	24.70 X un	25	18.52	1.30	19.82
74890-T5B-911	GARNISH ASSYRR.LICENSE	1 ?	200.60 X un	25	150.45	10.53	160.98
75701-T5A-000	EMBLEMH	1 ne	10.70 X un	25	8.02	0.56	8.58
33500-T5A-J02	TAILLIGHT ASSY,R.	1 cr	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL.	1 X	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID	1 ?	81.70 X un	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID	1 X	81.70 un	25	61.27	4.29	65.56
04655-TAS-300ZZ	PANEL SET,RR.FLOOR - photo	1 ?	683.30 X un	25	512.47	35.87	548.34
04636-TAS-300ZZ	PANEL SET,R.RR.OUTSIDE - photo	1 ht	548.30	25	411.22	28.79	440.01
66100-TAR-T10ZZ	PANEL COMPRR.	1 ht	320.40	25	240.30	16.82	257.12
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1 ne	11.40	25	8.55	0.60	9.15

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLL3055S

Chassis No : JHMGK5850HX201136

Model : JAZZ 1.5VTIR CVT 17YM

Owner's Name : KAAH SHEUNG KIN

Ins Policy No. :

Date of Accident : 9/11/2018

Document No. : SQT18004877

Date : 13. Nov 2018

Customer No. : WZF002

Svc Advisor :

Engine No : L15B31190813

Date | Time : 13. Nov 2018 5:20:02 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2 <i>rel</i>	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1 <i>rel</i>	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2 <i>rel</i>	60.00		120.00	8.40	128.40
73501-TF0-Y01	GLASS R QUARTER	1 <i>rel</i>	148.30	25	111.22	7.79	119.01
73525-TF0-000	RUBBER A WSHIELD DAM	1 <i>rel</i>	9.90	25	7.42	0.52	7.94
73526-TF0-000	RUBBER B WSHIELD DAM	1 <i>rel</i>	12.40	25	9.30	0.65	9.95
91501-SMA-003	CLIP AQTR.	3.40 <i>rel</i>	3.00	25	2.25	0.16	2.41
91503-TF0-000	CLIP QTR WSHIELD	1 <i>rel</i>	2.90 <i>Xun</i>	25	2.17	0.15	2.32
91506-S47-003	CLIP CQTR WINDOW	2.40 <i>rel</i>	2.40	25	1.80	0.13	1.93
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1 <i>rel</i>	60.00 <i>Xun</i>		60.00	4.20	64.20
Sum Item					3281.22	229.71	3,510.93

BOSUN	SUNDRIES	1	100.00	40	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	120.00	100	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	120.00	100	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	120.00	100	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT REAR RHS FENDER	1	120.00	100	120.00	8.40	128.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00	280	380.00	26.60	406.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00	✓	280.00	19.60	299.60
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA(N)	1	380.00	✓	380.00	26.60	406.60
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM(N)	1	450.00	✓	450.00	31.50	481.50
BODAMKIT	WINDSCREEN DAM KIT.	1	180.00	150	180.00	12.60	192.60
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00	✓	560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00	✓	560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	✓	560.00	39.20	599.20
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00	? photo Xun	560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.	1	7000.00	5600	7000.00	490.00	7490.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00	3375	3500.00	245.00	3745.00

Printed on 13/11/2018 5:43:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLL3055S

Chassis No : JHMGK5850HX201136

Model : JAZZ 1.5VTIR CVT 17YM

Owner's Name : KAAH SHEUNG KIN

Ins Policy No. :

Date of Accident : 9/11/2018

Document No. : SQT18004877 Page 3

Date : 13. Nov 2018

Customer No. : WZF002

Svc Advisor :

Engine No : L15B31190813

Date | Time : 13. Nov 2018 5:20:02 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Labor					14990.00	1,049.30	16,039.30

Survey By Tan Jiah 97495749

Date & Time 19/11/18 1025

Excess wp

Status

Signature [Signature]

Total Amount 18,271.22 1,279.01 19,550.23

Total (Inclusive of GST) 19,550.23

18812.01

surellhanto.com

14 days. - 15 days.

Resurvey before paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 13/11/2018 5:43:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: ****5428Z / KAN SHEUNG KIN

Chassis No: JHMGK5850HX201136

License No: SLL3055S

Mileage: 19297

Engine No: L15B31190813

Document No: SVO18068585

Printed By: JACKNG

Order Date: 19. November 2018

Order Time: 10:52:48 AM

Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
75722-T5L-T01	EMBLEMRR,	1	10.90	25	8.17	0.57	8.74 A
91502-T5A-901	CLIP B ,QUARTER WINDSHIELD	1	3.70	25	2.77	0.19	2.96 A
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	25	45.30	3.17	48.47 A
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40 A
84521-T5A-901ZA	LID ASSYSAPARE TIRE	1	189.80	25	142.35	9.96	152.31 A
SUM PARTS:					518.59	36.29	554.88
TOTAL SGD					518.59	36.29	554.88

Total Payable (SGD)

554.88

GST Amount is calculated from individual line(s)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK5850HX201136
License No: SLL3055S
Mileage: 19297
Engine No: L15B31190813

Document No: SVO18068585
Printed By: JACKNG
Order Date: 19. November 2018
Order Time: 10:52:48 AM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:KAAN SHEUNG KIN OWNER INSURER:AVIVA LTD ACC DATE:09/11/2018 SURVEYED BY: DATE: REF NO: TP INSURER:MS FIRST CAPITAL TP VEH:SHA 3919 E ADDITIONAL PART						
04715-T5B-000ZZ	FACERR.BUMPER	1	502.50	25	376.87	26.38	403.25
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71502-T5A-000	GARNISHR.RR.BUMPER	1	14.30	25	10.72	0.75	11.47
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
68100-TAS-Z50ZZ	TAILGATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
33500-T5A-J02	TAILLIGHT ASSY,R.	1	223.90	25	167.92	11.75	179.67
04636-TAS-300ZZ	PANEL SET,R.RR.OUTSIDE	1	548.30	25	411.22	28.79	440.01
66100-TAR-T10ZZ	PANEL COMPR.	1	320.40	25	240.30	16.82	257.12
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
73525-SYY-000	RUBBERRR QTR W/SHIELD	2 A	9.70	25	14.55	1.02	15.57
91501-T5A-901	CLIP A ,QUARTER WINDSHIELD	1	3.40	25	2.55	0.18	2.73
91503-TD4-003	CLIP C,QUARTER WINDSHIELD	1	2.40	25	1.80	0.13	1.93
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
75722-T5L-T01	EMBLEMRR. S	1 A	10.90	25	8.17	0.57	8.74
91502-T5A-901	CLIP B ,QUARTER WINDSHIELD S	1 A	3.70	25	2.77	0.19	2.96
74940-TZ5-A01	BUZZER ASSYSMART S	1 A	60.40	25	45.30	3.17	48.47
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR S	1 A	320.00		320.00	22.40	342.40
84521-T5A-901ZA	LID ASSYSAPARE TIRE S	1 A	189.80	25	142.35	9.96	152.31
	SUM PARTS:				2,595.67	181.69	2,777.36
BOSUN		1	40.00		40.00	2.80	42.80
	SUNDRIES						
BOJSE	1610	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT FOR TAILGATE						
BOJSE	1610	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT FOR END PANEL						
BOJSE	1610	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT FOR FLOOR PANEL						
BOJSE	1610	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT REAR RHS FENDER						
BML02I		1	280.00		280.00	19.60	299.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK5850HX201136
License No: SLL3055S
Mileage: 19297
Engine No: L15B31190813

Document No: SVO18068585
Printed By: JACKNG
Order Date: 19. November 2018
Order Time: 10:52:48 AM
Service Advisor: JACK NG

BA02R	0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00	280.00	19.60	299.60
BOMISC1	0671 REMOVE & INSTALL REAR VIEW CAMERA(N)	1	380.00	380.00	26.60	406.60
BOMISC1	0671 RESET & CALLIBRATE SMART ENTRY SYSTEM(N)	1	450.00	450.00	31.50	481.50
BODAMKIT	WINDSCREEN DAM KIT.	1	150.00	150.00	10.50	160.50
BG02R	1757 REPLACE RR. WINDSCREEN.(N)	1	560.00	560.00	39.20	599.20
BMI03D	1757 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00	560.00	39.20	599.20
BMI02D	1757 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	560.00	560.00	39.20	599.20
BKRP02M	0671 CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS. ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	5,600.00	5,600.00	392.00	5,992.00
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3,375.00	3,375.00	236.25	3,611.25
			SUM LABOUR:	12,635.00	884.45	13,519.45
			TOTAL SGD	15,230.67	1,066.14	16,296.81
Total Payable (SGD)						16,296.81

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020626/T1sd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3919E	Veh. Inspected	SLL 3055S	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18008047MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	14/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMGK5850HX201136	Colour	RED	
Odometer	19297	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	DUNLOP	6 mm	
L/H Front Tyre	185/55 R16	DUNLOP	6 mm	
R/H Rear Tyre	185/55 R16	DUNLOP	6 mm	
L/H Rear Tyre	185/55 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/11/2018	Inspection Date	19/11/2018	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 3055S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FACE,RR.BUMPER (SN)	DEFORMED	376.87	376.87
1	GARNISH,RR.BUMPER (SN)	DEFORMED	28.72	10.72
1	SPACER,R.RR.BUMPER SIDE (SN)	NECESSARY	12.67	8.62
1	SPACER,L.RR.BUMPER SIDE (SN)	NECESSARY	12.67	8.62
1	COVER,R.RR.BUMPER (SN)	NOT NECESSARY	15.52	-
1	COVER,L.RR.BUMPER (SN)	NOT NECESSARY	15.52	-
7	CLIP, BUMPER (SN)	NECESSARY	12.07	12.07
1	TAILGATE COMP (SN)	BENT	547.95	547.95
1	WEATHERSTRIPTAILGATE (SN)	NECESSARY	69.22	69.22
1	LOCK ASSY, TAILGATE (SN)	NOT NECESSARY	59.17	-
1	STRIKER ASSYTAILGATE (SN)	NOT NECESSARY	18.52	-
1	GARNISH ASSYRR.LICENSE (SN)	NOT NECESSARY	150.45	-
1	EMBLEMH (SN)	NOT NECESSARY	8.02	-
1	TAILLIGHT ASSY,R. (SN)	CRACKED	167.92	167.92
1	TAILLIGHT ASSYL (SN)	NOT NECESSARY	167.92	-
1	LIGHT ASSYR.LID (SN)	NOT NECESSARY	61.27	-
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	61.27	-
1	PANEL SET,RR.FLOOR (SN)	NOT NECESSARY	512.47	-
1	PANEL SET,R.RR.OUTSIDE (SN)	BENT	411.22	411.22
1	PANEL COMPRR. (SN)	BENT	240.30	240.30
1	RUBBER CWINDOWSHIELD DAMPER (SN)	NECESSARY	8.55	8.55
2	RUBBERWINDOWSHIELD DAMPER (SN)	NECESSARY	9.75	9.75
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.37	6.37
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
1	GLASS R QUARTER (SN)	NOT NECESSARY	111.22	-
1	RUBBER A WSHIELD DAM (SN)	NOT NECESSARY	7.42	-
1	RUBBER B WSHIELD DAM (SN)	NOT NECESSARY	9.30	-
1	CLIP AQTR (SN)	NECESSARY	2.55	2.55
1	CLIP QTR WSHIELD (SN)	NOT NECESSARY	2.17	-
1	CLIP CQTR WINDOW (SN)	NECESSARY	1.80	1.80
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00

Report Ref No. CS/FCI18020626/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	100.00	40.00
2	RUBBERRR QTR W/SHIELD (SN) (ADDITIONAL)	NECESSARY	14.55	14.55
1	EMBLEMRR. (SN) (ADDITIONAL)	NECESSARY	8.17	8.17
1	CLIP B, QUARTER WINDSHIELD (SN) (ADDITIONAL)	NECESSARY	2.77	2.77
1	BUZZER ASSYSMART (SN) (ADDITIONAL)	CRACKED	45.30	45.30
4	ACT RR.SENSOR (SN) (ADDITIONAL)	NOT WORKING	320.00	320.00
1	LID ASSYSPIARE TIRE (SN) (ADDITIONAL)	DEFORMED	142.35	142.35
			3,922.01	2,635.67
	LABOUR			
	BODY JOINT SEALANT FOR TAILGATE.		120.00	100.00
	BODY JOINT SEALANT FOR END PANEL.		120.00	100.00
	BODY JOINT SEALANT FOR FLOOR PANEL.		120.00	100.00
	BODY JOINT SEALANT REAR RHS FENDER.		120.00	100.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		380.00	280.00
	REMOVE & RENEW REVERSE SENSORS - 4PCS.		280.00	280.00
	REMOVE & INSTALL REAR VIEW CAMERA.		380.00	380.00
	RESET & CALIBRATE SMART ENTRY SYSTEM.		450.00	450.00
	WINDSCREEN DAM KIT.		180.00	150.00
	REPLACE RR.WINDSCREEN.		560.00	- 560.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		560.00	560.00
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.		560.00	560.00
	REMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	560.00	-
	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.		7,000.00	5,600.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P).		3,500.00	3,375.00
			-	-
			-	-
			14,890.00	12,595.00
	GRAND TOTAL		18,812.01	15,230.67
	RECOMMENDED COST OF REPAIRS			15,230.67

Report Ref No. CS/FCI18020626/T1sd3e2



Report Ref No. CS/FCI18020626/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.