

ASS. REC. BY:

REF: cs/MSG18020635/Ksd3 ⁿ² Special Instruction:

Surveyor:

Menmen

ASSIGNMENT (Office)

From (Person):

Jawyn Tay

of

MSIG

Date/Time:

14/11/18 @ 4:07pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

BHY 1133

Insured:

FBJ 6091X

at Workshop m/s

Guin Motor

Tel:

6453 6111

of

176 Sin Ming Drive # 02-03

Policy No:

MSD/VMT/18-991576-WT1

Claim No:

MSC/V/18-001421

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/10/2018

15/11/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

1up

Date/Time:

4:56pm @ 14/11/18

Person Contacted:

Ms. Teo

Vehicle:

OUT

Date/Time	Action/Instruction (✓) Estimate
	BHY 1133X
	FBJ 6091X - X
16/11/18	@ 13:49 p.m. revised IA to Jawyn Tay me Ling via memo.
	11 Dp @ 310a email & confirm

ASSIGNMENT

From: _____ Date: 15/11/2018

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: BMY 1133

at Workshop m/s Guan Motor

of 176 Sin Ming Drive # 02-03

Insured: _____


Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: BMY 1133 Yr Regn: 03 07

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: M E280 C.C. 2996

Colour: M. D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 281854 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W00-21105462 001905

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm R/Bal. 6 mm

L/Bal. 5 mm L/Bal. 6 mm

D.O.A. 20/10/18 D.O.I. 15/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Pres o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/11 176 Road to Catharina

16/01/19 Confirmed HS \$3,100/- @ 3 days with Kenneth -
(\$3,113.90 - Red - 50%)

16/1/2019

RECEIVED 18 JAN 2019

Date/Time, File Pass to?

18/01/19

1) Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 3,100/- L/S)

150
10
160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 16 Nov 2018

Preliminary Advice

Insured Vehicle No	: FBJ6091X	Accident Date	: 20/10/2018
TP Vehicle No	: BHY1133	Assignment Date	: 14/11/2018
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 3 days
Date of Inspection	: 15/11/2018		
Inspection At	: Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,213.90
Revised Amount	:S\$	3,693.00
Check Items (Estimated)	:S\$	788.40
Total	:S\$	4,481.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2018		14 Nov 2018 16:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MASSOT GILLES JEAN YVES, ID: S2712252C, Tel: +6581826438, Email: GILLESMASSOT@GMAIL.COM		
Main Claimant:	WONG GUAN TECK, ID: 560107085063		
Vehicle Reg. No.:	BHY1133	Date of Loss:	20/10/2018 13:00 - :59 [45 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001421	Policy/Cover Note No.:	MSD/VMT/18-991576-WTT (Third Party Only) Coverage: 07/11/2017 - 06/11/2018
Vehicle Reg. No. (Insured):	FBJ6091X	Policy No. (Claimant):	
		Excess:	
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/11/2018]		
Driver/Custodian (Insured):	MASSOT GILLES JEAN YVES (63 / Male), NRIC: S2712252C, Tel: +6581826438		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (KENNETH KONG). LIABILITY: IN DISPUTE. CONTACT: AH HENG 6453 6111		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



**SINGAPORE
POLICE FORCE**



T/20181021/2031

1 of 3

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

Report No. T/20181021/2031

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/10/2018 12:41	Vide Report No.:	Station Diary No.: 7
--	------------------	-------------------------

Informant's Particulars

Name of Informant: WONG GUAN TECK			Address: APT BLK 155 Hougang street 11 #03-176 SINGAPORE 530115		
ID Type / ID No.: NEW MALAYSIAN IC / 560107085063			Contact No.: Home/Office: Mobile: 81592910		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 62	Date of Birth: 07/01/1956	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: RETIRES			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 20/10/2018 13:15	Type of Location: Straight Road
Location: Along Road 1 BALESTIER ROAD traffic junction near Balestier Point				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
BHY1133	Car				Slightly Damaged	0
FBJ6091X	Motorcycle				No Damage	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

Report No. T/20181021/2031

CONTINUATION OF REPORT

Driver				
Name	WONG GUAN TECK		ID No.	560107085063
Related Vehicle	BHY1133 (Car)		Contact No.	81592910
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Rider				
Name	Massot Gilles Jean Yves		ID No.	S2712252C
Related Vehicle	FBJ6091X (Motorcycle)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 20/10/2018 at about 1318hrs, I was driving my car vehicle no: BHY1133 along Balestier Road near Balestier Point. I stopped my car at the traffic Junction and while waiting for the traffic light to turn green, I suddenly felt a collision at the rear of my car.

After the collision, I came down from my vehicle to make a check. This was when I discovered a motorbike vehicle no FBJ6091X collided to the right rear of my car. My right rear bumper suffered scratches and dent in a result.

Both me and the motorcyclist was not injured, no police was called also. I exchanged particulars with the motorcyclist and we agreed to do insurance claims on our own and we left the scene.

Particular of the said motorcyclist is as such,

Name: Massot Gilles Jean Yves
NRIC: S2712252C



**SINGAPORE
POLICE FORCE**



T/20181021/2031

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

3 of 3

Report No. T/20181021/2031

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 KOH PEI QI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI 2 YEO GEAK ENG CECILIA

Contact No.: 65476404

Signature Of Informant:

Date/Time:

21/10/2018 12:41

Classification Of Case:

Authentication Stamp

NP168

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN: **011Y 1133**

No. Siri A **4908419**

Nama Pemunya Berdaftar : **YINPOLIN AGRICULTURE SDN. BHD.**

064091-X
(OKT)

Alamat : **48A JALAN 3 KAWASAN 10 TAMAN INTAN
41300 KLANG SELANGOR D.L.**

No. Enjin : **27284330613-112**
No. Casis : **W002110546L001905**
Buatan : **ALPHEDES BERZ**
Name Model : **C280 W211**
Keupayaan Enjin : **2996 C.P**
Bahan Bakar : **PETROL**
Warna : **KELABU**
Kelas Kegunaan : **PERKULIAHAN MOTORAN SYARIKAT**
Jenis Badan : **MOTORAN**
Tahun Dibuat : **2007**
Tarikh Pendaftaran : **16/02/2007**
Status Pemunya : **SYARIKAT/PERUSAHAAN**
Muatan Tempak :
Duduk : **5**
Kadar Lesen :
Kenderaan Motor : **6 bulan 12 bulan**

B.D.M/B.G.K
B.T.T.
Berat Kerb
B.T.M.
B.G.1
B.G.2
B.G.3
B.G.4
B.G.5
B.G.6
B.G.7
B.G.8
B.G.9
B.G.10
B.G.11
B.G.12

RM2,950.00

RM3,500.00

YINPOLIN AGRICULTURE SDN. BHD.
No. Syarikat: **064091X**

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan

oleh Pengerah JPJ Negeri **JPJ PETALING JAYA**

UNTUK KEGUNAAN PEJABAT

PENASANGAN TEMPATAN

HAKMILIK DITONTOT OLEH : **Pembatalan Melalui Sistem**
FIS (JPJ Selangor) NO SIRI SURAT **10531754**

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).
2. Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membarui lesen 60 hari sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berlesen.
5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR BHY1133

No.	Qty	List Items		
1	1	Rear bumper <i>1834</i>	\$ <i>CM</i> 1,823.00	✓
2	1	Rear bumper centre chrome moulding	\$ <i>MC</i> 204.00	✓
3	2	Rear bumper side chrome moulding	\$ <i>MC</i> 288.00	✓
4	1 <i>2</i>	Rear bumper reverse sensors	\$ <i>MC</i> 392.00	✓
5	2	Rear bumper side retainer	\$ <i>0.1</i> 90.00	✓
6	1	Rear bumper inner reinforcement	\$ <i>MC</i> 634.00	✓
7	1	Rear bumper inner parts	\$ <i>CM</i> 242.00	✓
8	1	RH taillamp <i>701</i>	\$ <i>CM</i> 669.00	✓
9	1	RH taillamp lower bracket	\$ <i>MC</i> 14.00	✓
10	1	Rear end panel	\$ <i>MC</i> 815.00	✓
			\$ 5,171.00	
			Less 10%	\$ 517.10
			Total :	\$ 4,653.90

		Labour		
1		Labour Charges for remove/refit, panel beating and replacement of damages.	\$ 700.00	<i>3001</i>
2		To putty and spray Spray Paintings charges.	\$ 700.00	<i>4001</i>
3		To check wirings, lightings including remove, reset and replace reverse sensors.	\$ 80.00	<i>301</i>
4		To apply anti rust treatment	\$ <i>MC</i> 80.00	✓
			Total :	\$ 1,560.00

Total Parts and Labour : \$ 6,213.90

Not Notified
21 Sep 83100h
Repair After Paint
3 days

[Signature]
16/11/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18020635/KSD3N2

Date: 21/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-991576-WTT	Claim No:	MSC/V/18-001421
Claimant Vehicle No :	BHY1133	Insured Vehicle No :	FBJ6091X		
Date of Loss:	20/10/2018	Nature of Claim:	TP		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	BHY1133	Engine No:	27294330413112
Make & Model:	MERCEDES-BENZ E280, 3.0 W211 (A)	Chassis No:	WDD2110546L001905
Reg. Date:	14/03/2007 (Man. Year: 2007)	Odometer:	281854 km
Colour:	Metallic Dark Blue		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,653.90	3,160.80	1,493.10	32.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	750.00	810.00	51.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,213.90	3,910.80	2,303.10	37.06
Approved Total (Overridden) (\$\$)		3,100.00		
Nett Amount (\$\$)	6,213.90	3,100.00	3,113.90	50.11

INSPECTION

Date of Assignment:	14/11/2018	
Date Inspected:	15/11/2018 Inspected At:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2019)
Parts: 143	MERCEDES-BENZ E280 3.0 W211 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for BHY1133)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Cracked	1,823.00 FL	*1,823.00 FL
2	1	*REAR BUMPER CENTRE CHROME MOULDING	Necessary	204.00 FL	*204.00 FL
3	2	*REAR BUMPER SIDE CHROME MOULDING	Necessary	288.00 FL	*288.00 FL
4	1	*REAR BUMPER REVERSE SENSOR (2 Pcs)	Dented (1 Pc only)	392.00 FL	*196.00 FL
5	2	*REAR BUMPER SIDE RETAINER	Distorted	90.00 FL	*90.00 FL
6	1	*REAR BUMPER INNER REINFORCEMENT	Repair	634.00 FL	*- FL
7	1	*REAR BUMPER INNER PARTS	Cracked	242.00 FL	*242.00 FL
8	1	*RH TAILLAMP	Cracked	669.00 FL	*669.00 FL
9	1	*RH TAILLAMP LOWER BRACKET	Serviceable	14.00 FL	*- FL
10	1	*REAR END PANEL	Repair	815.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,171.00	3,512.00
- List Item Discount on L Items 10.00/10.00% (S\$)	517.10	351.20
Total Parts (S\$)	4,653.90	3,160.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE/REFIT,PANEL BEATING AND REPLACEMENT OF DAMAGES	New	700.00	300.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	700.00	400.00
3	TO CHECK WIRINGS,LIGHTINGS INCLUDING REMOVE,RESET AND REPLACE REVERSE SENSORS	New	80.00	50.00
4	TO APPLY ANTI RUST TREATMENT	New	80.00	-
Gross Labour Cost (\$\$)			1,560.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >