

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1306/2018/PH
Date : 16-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SLE 991 X

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Chee Hong Peter
Address : 370E Alexandra Road
#13-04
Singapore 159958
Telephone : HP +65 97554504
Type of Claim : Third Party Claims
Policy No. : 2018-V0097464-VDP-R002
Vehicle No : **SGU 9998 T**
Model Code : Audi A6 1.8 TFSI
Model / Year : Mar-16
Engine No : CYG 008295
Chassis No : WAUZZZ4G6GN051456
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Nov-18
Place of Accident : Along Aliwal Street

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGU 9998 T.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front and rear door's multi-lock system and power window devices .	S/N \$ 560.00	280
2	To dismantle and renew rhs front and rear doors , align to position . Reinstall all parts removed .	\$ 2,100.00	500
3	To respray rhs front and rear doors .	\$ 1,800.00	1100
4	To carry out diagnostic check .	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ <u>4,652.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 9998 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	DOOR SEAL , OUTER - RH LOWER <i>me n</i>	\$ 165.00	<i>+</i>
2	REAR DOOR - RH <i>Regis</i>	\$ 3,211.00	<i>+</i>
3	ATTACHMENT PARTS FOR DOOR <i>?</i>	\$ 72.00	<i>+</i>
4	OUTER DOOR SEAL	\$ 202.00	<i>+</i>
5	BONDING AGENT	\$ 43.00	<i>+</i>
6	CLEANING SOLUTION	\$ 64.00	<i>+</i>
7	DOOR CATCH	\$ 105.00	<i>+</i>
8	DOOR SEAL , OUTER - RH <i>me n</i>	\$ 162.00	<i>+</i>
9	FRONT DOOR - RH <i>Dented</i>	\$ 3,211.00	<i>+</i>
10	STONE GUARD FILM FOR FRONT FENDER - RH <i>me n</i>	\$ 105.00	<i>+</i>
11	ATTACHMENT PARTS FOR DOOR <i>?</i>	\$ 164.00	<i>?</i>
12	OUTER DOOR SEAL <i>Abol me n</i>	\$ 202.00	<i>+</i>
13	BONDING AGENT <i>?</i>	\$ 43.00	<i>?</i>
14	CLEANING SOLUTION <i>?</i>	\$ 64.00	<i>?</i>
15	DOOR CATCH <i>me n</i>	\$ 105.00	<i>+</i>
TOTAL SPARE PARTS		\$ 7,918.00	
TOTAL LABOUR CHARGES		\$ 4,652.00	
GRAND TOTAL		\$ 12,570.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 20/11/12
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant