

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05883

Date : 13-Nov-2018

PAGE : 1

Vehicle Insured : SLB6911D
Accident Date : 09-Nov-2018

Our Ref : 218189 (AIG) / CHAN

QUAH TUANG KIT @ LEE TUANG KIT
BLK 234 HOUGANG AVENUE 1
#04-262
Singapore 530234

*Not Authorise
Resurvey B4 paint
2 day,*

ESTIMATED COST OF REPAIR FOR AUDI A4 1.4 TFSI SKQ3666P

=====

1 pc Rear bumper fascia
1 pc Rear bumper lower spoiler
1 pc Rear o/s bumper reflector
1 pc Rear bumper reinforcement

Av 1 cm 885.00 ✓
154.00 ?
46.00 ?
380.00 ?

1,465.00

Less 10% : 146.50

1,318.50

To putty and spray replaced parts

500.00 *250*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

550.00 *250*

Total : S\$ 2,368.50

=====

Singapore Dollars Two Thousand Three Hundred
and Sixty Eight and Cents Fifty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: