

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8703 Y

1 pc	Front bumper	DE	\$	531.00
		Less 10%	\$	53.10
			\$	477.90
S/NETT				
1 set	Front bumper clips	NEC	\$	48.00
	Sundry		\$	50.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s fender		\$	550.00 ²⁰⁰
	To putty and spray painting on front bumper, front o/s fender		\$	400.00 ²¹⁸⁰
	To apply rustproofing on the repaired and replaced panels.		\$	80.00 X
			\$	<u>1,785.90</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalin 10/11/18
14/11/18 1305hrs.
2 Days
4/5
After Repair photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "What is it?" basis
- No illegal modifications are allowed
- Supplementary damages must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: