

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SJV2566L	Excess.	NIL
Policy No.	5102022092	Coverage.	Comprehensive
Claiming Against.	GR5408Y	AXA	
Insured Under.	NTUC		

Vehicle Particulars & Condition

Make & Model	Nissan Teana
Engine No.	VQ25486330A
Chassis No.	JN1BBUJ32Z0002266
Odometer	
Engine CC.	2496
Year Of Reg.	2010
Colour.	BLACK
Parf/COE Rebate.	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Rear portion and front portion damaged

General Information

Accident Date. 12/11/2018
Survey held at

Yew Tee Automobile Tech Pte Ltd

MEGA@Woodlands, 39 Woodlands Close #01-12, Singapore 737856

Remarks

KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR:

Days

VIC
Not Authorised
Lah
mercus
W. 62563561
~~W. 62563561~~
15/11/18
MV \$25,000
LTA \$18927
4/5 \$6000/-
15 day.

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts		Pricing	
1	Rear bumper	Dis	\$ 395.00	✓
1	Rear bumper side retainer LH	Ref	\$ 38.00	✓
1	Rear bumper side retainer RH	CN	\$ 38.00	✓
1	Rear bumper bracket LH	11	\$ 23.00	X
1	Rear bumper bracket RH	Ref	\$ 23.00	✓
1	Rear bumper inner sponge	Pin	\$ 75.00	✓
1	Rear bumper reinforcement	Ref	\$ 193.00	✓
2	Rear bumper chrome moulding	015 B10	\$ 140.00	1PC
1	Boot lid	Ref	\$ 495.00	✓
2	Boot lid hinges	Ref	\$ 230.00	✓
1	Boot lid rubber	Ref	\$ 95.00	✓
1	Boot lid inner trim board	Dis	\$ 160.00	✓
1	Boot lid logo	Ref	\$ 55.00	✓
1	Boot lid TEANA emblem	Ref	\$ 52.00	✓
1	Boot lid 250XV emblem	Ref	\$ 53.00	✓
1	Boot lid V6 emblem	Ref	\$ 58.00	✓
1	Boot lid outer chrome moulding top	11	\$ 145.00	X
1	Boot lid outer chrome moulding bottom	11	\$ 95.00	X
1	Boot lid lock	Ref	\$ 90.00	✓
1	Boot lid lock catch	Ref	\$ 33.00	✓
2	Boot lid damper	Ref	\$ 260.00	✓
2	Rear taillamp	n/sa 015 B10	\$ 480.00	1PC
2	Rear taillamp lower bracket	015 CN	\$ 60.00	1PC
2	Rear taillamp panel	015 B10	\$ 340.00	1PC
2	Rear fender	n/sa 015 Dis	\$ 1,310.00	1PC
2	Rear fender inner shield	015 Pin	\$ 298.00	1PC
1	Rear fender glass chrome moulding RH	Ref	\$ 537.00	✓
1	Rear fender glass chrome moulding LH	11	\$ 537.00	X
1	Rear fender inner trim board RH	Dis	\$ 185.00	✓
1	Rear fender inner panel RH	Dis	\$ 883.00	✓
1	Rear fender wheelhouse panel RH	Dis	\$ 787.00	✓
2	Rear fender inner garnish	015 Pin	\$ 286.00	1PC
1	Rear chassis side member RH	Ref	\$ 980.00	X
1	Rear windscreen glass	B10	\$ 500.00	✓
1	Rear door RH	Ref	\$ 395.00	X
1	Rear door lock RH	Ref	\$ 205.00	X
1	Rear door lock catch RH	11	\$ 25.00	X

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts		Pricing	
1	Rear end panel	Body	\$ 190.00	✓
1	Rear end panel inner garnish	111	\$ 68.00	✓
1	Rear spare tyre panel	11	\$ 514.00	✓
1	Rear spare tyre board	11	\$ 210.00	✓
1	Rear spare tyre compartment top panel	11	\$ 987.00	✓
1	Rear spare tyre compartment top inner panel	11	\$ 996.00	✓
1	Rear exhaust silencer RH	11	\$ 353.00	✓
1	Rear exhaust pipe	11	\$ 643.00	✓
1	Rear exhaust heat shield RH	11	\$ 85.00	✓
1	Front bumper	11	Rpr	✓
1	Front bumper fog lamp cover RH	11	\$ 55.00	✓
1	Front bumper chrome moulding RH	11	\$ 75.00	✓
1	Front bumper nozzle cover RH	11	\$ 45.00	✓
1	Front bumper nozzle spray RH	11	\$ 185.00	✓
1	Front bumper side retainer RH	11	\$ 20.00	✓
1	Front headlamp HID RH	11	\$ 605.00	✓
	Subtotal		\$ 15,585.00	
	Add 10%		\$ 1,558.50	
			\$ 17,143.50	
1	Rear bumper clips (set)	11	\$ 35.00	✓
1	Rear bumper sensors (set)	11	\$ 240.00	200
1	Boot lid inner trim board clips (set)	11	\$ 35.00	✓
1	Rear fender inner shield clips (set)	11	\$ 35.00	✓
1	Rear windscreen sealant	11	\$ 60.00	40
1	Rear door black tape RH	11	\$ 70.00	✓
1	Private Hire sticker	11	\$ 20.00	✓
2	Rear exhaust mountings RH	11	\$ 60.00	✓
			\$ 555.00	

365

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 120.00 100
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 80.00 30
	To remove and refit rear bumper sensors.	\$ 80.00 50
	Towing fees	\$ 120.00 ✓
	To dismantle and refit rear windscreen glass.	\$ 100.00 ✓
	To dismantle and refit rear fender glass x 2	\$ 120.00 60
	To remove and refit carpet and trims on the rear section to give way to the repair on the rear section.	\$ 100.00 80
	To supply spray terostat sealant on the cutting areas.	\$ 80.00 ✓
	To do up interior cleaning and chemical wash.	11 \$ 120.00 x
	To remove and refit, straighten and re-adjust exhaust pipe and rear exhaust silencer and mountings.	11 \$ 180.00 x
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 2,400.00 2000
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 1,500.00 ✓
	LABOUR	\$ 5,000.00
	Sub Total.	\$ 22,698.50 4120
	7% GST	\$ 1,588.90
	Grand Total	\$ 24,287.40

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.