

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1280/2018/GW
Date	:	10-Nov-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no: SKX 5508 M

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Lim Siew Hwa
Address	:	80 Jellicoe Road #11-02 Singapore 208766
Telephone	:	HP +65 91397695
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	SKX 5508 M
Model Code	:	Audi A3 SB 1.4 TFSI
Model / Year	:	Dec-15
Engine No	:	CZC 501632
Chassis No	:	WAUZZZ8V7GA067472
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	09-Nov-18
Place of Accident	:	SPH News Centre

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 5508 M

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To renew lhs 1/4 glass to facillitate fender renewal.	S/N \$ 300.00 ✓
3	To remove and transfer lhs front and rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00 280
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓
5	To remove and reinstall rear seat, back rest, hat try, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓
6	To dismantle rear bumper, rear lid, lhs front door and lhs rear door. Cut out and weld lhs rear fender, lhs rear inner side panel and lhs rear wheel housing. Renew lhs front door and lhs rear door. Re-organize crash management components. Reinstall all parts removed.	\$ 9,000.00 3500
SUB- TOTAL LABOUR CHARGES		: \$ 12,940.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 5508 M

S/n	Nature of Jobs	Estimated Charges
7	To respray lhs front fender, lhs rear fender, lhs front door, door handle, lhs rear door, lhs sill panel, door entrances, roof channel, drain panel, end panelling, lhs side inner panel and lhs wheel housing. To carry out stone chip treatment and joint sealer works.	\$ 6,600.00
8	To renew rear rim and carry out wheel alignment.	S/N \$ 280.00
9	To carry out diagnostic check.	S/N \$ 384.00
TOTAL LABOUR CHARGES		\$ 20,204.00

550x6 = 3300
Handle = 80

3380

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 5508 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-LH <i>Repair</i>	\$ 1,991.00	X
2	FRONT OUTER DOOR SEAL-LH } <i>see</i>	\$ 139.00	X
3	BONDING AGENT	\$ 43.00	X
4	CLEANING SOLUTION	\$ 64.00	X
5	APPLICATOR	\$ 7.00	X
6	FRONT DOOR ATTACHMENT PARTS-LH } <i>see</i>	\$ 206.00	X
7	FRONT DOOR CATCH-LH	\$ 92.00	X
8	FRONT DOOR CATCH COVER-LH	\$ 13.00	X
9	FRONT DOOR HANDLE EXTERIOIR-LH } <i>Repair</i>	\$ 207.00	X
10	FRONT DOOR HANDLE HOUSING-LH	\$ 26.00	X
11	FRONT DOOR MOUNTING BAR-LH <i>see</i>	\$ 143.00	X
12	REAR DOOR-LH <i>Dented</i>	TBC	C
13	REAR OUTER DOOR SEAL-LH <i>see</i>	\$ 139.00	✓
14	BONDING AGENT ?	\$ 43.00	?
15	CLEANING SOLUTION ?	\$ 64.00	?
16	APPLICATOR ?	\$ 7.00	?
17	REAR DOOR ATTACHEMENT PARTS ?	\$ 110.00	?
18	REAR DOOR CATCH-LH <i>see</i>	\$ 82.00	X
19	REAR DOOR CATCH COVER-LH <i>see</i>	\$ 14.00	X
20	REAR SECTIONAL PART- SIDE PANEL-LH <i>Dented</i>	\$ 1,938.00	✓
SUB- SPARE PARTS CHARGES		\$ 5,328.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 5508 M

S/N	Parts Description		Damaged Par S/Nett
21	REAR SIDE WINDOW-LH <i>new</i>	\$	225.00 ✓
22	REAR SIDE WINDOW TRIM STRIPS-LH <i>new</i>	\$	226.00 ✗
23	MOLDING ROOF <i>new</i>	\$	509.00 ✗
24	C-PILLAR REINFORCEMENT-LH <i>new Rys</i>	\$	172.00 ✗
25	REAR WHEEL HOUSING INNER PARTS-LH <i>new Rys</i>	\$	532.00 ✗
26	REAR ALUMINIUM RI-LH <i>OK</i>	\$	603.00 ✓
27	RUBBER VALVE <i>NOT NEC</i>	4 \$	12.00 ✗
28	ACRYLIC SEALANT <i>2</i>	S/N \$	180.00 ✓
29	CAVITY WAX	S/N \$	140.00 ✓
30	STONE CHIP	S/N \$	180.00 ✓
31	METAL FILLER POWDER <i>NEC</i>	S/N \$	280.00 ✓
32	1/4 GLASS SEALANT	S/N \$	100.00 ✓
33	SUNDRIES <i>?</i>	\$	800.00 ?
TOTAL SPARE PARTS CHARGES		:	\$ 9,287.00
TOTAL LABOUR CHARGES		:	\$ 20,204.00
GRAND TOTAL		:	\$ 29,491.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Adrian King -
15/11/18

Not Authorised, 14 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant