

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 518Y**

**AAD1811-103**

*Not Authorized  
1 Sing @ 3650/*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHF 518Y**  
VF1ABL15AUC278263  
RENAULT  
LATITUDE  
7.11.2018  
**III**

PART			LIST
1	BUMPER COVER FRT	\$	R 1,259.42
1	BUMPER SPOILER FRT	\$	Sm 181.75
1	BUMPER ABSORBER FRT	\$	Sm 394.68
1	BUMPER RETAINER FRT LH	\$	Sm 151.41
1	BUMPER SUPPORT FRT	\$	Sm 123.88
1	BUMPER RETAINER FRT RH	\$	Sm 150.77
1	BUMPER SUPPORT FRT	\$	Sm 123.88
1	BUMPER UNDERTRAY FRT	\$	Sm 472.83
1	BUMPER GRILLE LOWER FRT	\$	Sm 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	Sm 207.21
1	BUMPER FOG LAMP GRILLE RH	\$	Sm 207.21
1	BUMPER BEAM FRT	\$	R 914.08
1	FENDER PANEL FRT RH	\$	Sm 783.83
1	WHEELARCH FRT RH	\$	Sm 278.84 X
1	FENDER BRACKET LOWER RH	\$	Sm 15.79 X
1	FENDER INSULATOR RH	\$	Sm 130.84 X
1	DOOR PANEL FRT RH	\$	Sm 2,844.66
1	DOOR HINGE UPPER RH	\$	R 261.28
1	DOOR HINGE LOWER RH	\$	R 300.55
1	DOOR CHECK FRT RH	\$	Sm 194.77
1	DOOR LOCK FRT RH	\$	R 908.75
1	DOOR CATCH FRT RH	\$	Sm 131.23
1	DOOR HANDLE OUTER FRT RH	\$	Sm 477.76
1	DOOR HANDLE COVER FRT RH	\$	Sm 13.22
1	DOOR HANDLE MODULE FRT RH	\$	Sm 133.60
1	DOOR REGULATOR FRT RH	\$	R 505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	Sm 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	Sm 120.97
1	DOOR PANEL REAR RH	\$	R 2,844.66

*X*

*X*

*X*

**Trans-cab Auto Services Pte Ltd**

AAD1811-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 518Y**

1	DOOR GUIDE REAR RH	\$	Su	176.82
1	DOOR HINGE UPPER RH	\$	R	274.50
1	DOOR HINGE LOWER RH	\$	R	300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	Su	203.06
1	DOOR LOCK REAR RH	\$	R	908.75
1	DOOR HANDLE OUTER REAR RH	\$	Su	126.49
1	DOOR HANDLE CAP REAR RH	\$	Su	35.52
1	DOOR HANDLE SEAL REAR RH	\$	Su	7.89
1	DOOR HANDLE COVER REAR RH	\$	Su	13.22
1	DOOR HANDLE MODULE REAR RH	\$	Su	133.60
1	DOOR REGULATOR REAR RH	\$	Su	1,135.10
1	DOOR REGUALTOR MOTOR REAR RH	\$	Su	893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	Su	12.43
1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	Su	6.31
1	DOOR FINISHER REAR RH	\$	Su	423.10
1	DOOR MOULDING REAR RH	\$	Su	176.82
1	DOOR MOULDING CLIP L70Y	\$	Su	5.92
1	DOOR MOULDING SCREW L70Y	\$	Su	6.91
1	DOOR CASING REAR RH	\$	Su	1,509.06
1	DOOR WATER SHIELD REAR RH	\$	Su	30.39
1	DOOR CASING CLIP	\$	su	12.63
1	DOOR CASING LIGHT L70Y	\$	Su	48.74
1	DOOR FINISHER INNER REAR RH	\$	Su	323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	R	46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	R	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	R	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	R	20.33
1	DOOR GRAB HANDLE REAR RH	\$	Su	210.96
1	DOOR BLIND REAR RH	\$	Su	741.80
1	DOOR WHEATHESTRIP REAR RH	\$	Su	410.66
1	DOOR SEAL REAR RH	\$	Su	162.02
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Su	229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	Su	334.69
1	DOOR WAIST SEAL INNER REAR RH	\$	Su	115.64
1	FENDER PANEL REAR RH	\$	R	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	Su	671.45
1	WHEELARCH REAR RH	\$	Su	543.47
1	DOOR MIRROR ASSY RH	\$	Su	1,483.40

X

**Trans-cab Auto Services Pte Ltd**

AAD1811-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 518Y**

1	ROCKER PANEL INNER GARNISH RH	\$	<i>Sm</i> 466.51 X
1	ROCKER PANEL INNER RH	\$	<i>Sm</i> 1,024.79 X
1	ROCKER PANEL CENTER RH	\$	<i>Sm</i> 990.25 X
		<b>\$</b>	<b>32,753.38</b>
10%		<b>\$</b>	<b>3,275.34</b>
		<b>\$</b>	<b>29,478.04</b>

**Special Nett**

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i> 70.00 X
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>nn</i> 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nn</i> 30.00 X
1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i> 30.50 X
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>nn</i> 80.00 <i>60 sn</i>
1	FRONT DOOR STICKER 'Chassis'	\$	<i>nn</i> 300.00 <i>15 sn</i>
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69
1	DOOR GUIDE SCREW	\$	<i>nn</i> 10.85
1	DOOR HINGE BOLT	\$	<i>nn</i> 10.85
1	DOOR HINGE NUT RH	\$	<i>nn</i> 14.60
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69
1	DOOR CHECK NUT	\$	<i>nn</i> 3.75
1	DOOR LOCK SCREW L70Y	\$	<i>nn</i> 6.12
1	DOOR CATCH SCREW L70Y	\$	<i>nn</i> 10.06
1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00
1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i> 12.00
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i> 10.50
1	BUMPER BRACKET CLIP FRT RH	\$	<i>nn</i> 12.00
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>nn</i> 10.50
1	REAR DOOR STICKER ' 6555-3333'	\$	<i>nn</i> 80.00

**TOTAL \$ 823.13**

**TOTAL PARTS \$ 30,301.17**

**Trans-cab Auto Services Pte Ltd**

AAD1811-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 518Y

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <sup>400l</sup>
Putty and spray painting of the affected portion.	\$	4,200.00 <sup>660l</sup>
To rust-proofing of the affected areas.	\$	170.00 <sup>60l</sup>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<sup>nn</sup> 380.00 X
To check steering geometry and computer wheel alignment	\$	<sup>nn</sup> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<sup>nn</sup> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <sup>20l</sup>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<sup>nn</sup> 380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 <sup>60l</sup>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<sup>nn</sup> 380.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<sup>nn</sup> 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<sup>nn</sup> 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<sup>nn</sup> 380.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD1811-103**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 518Y**

**TOTAL \$ 12,090.00**

**Over All Total \$ 42,391.17**

**LUMP SUM (REPAIR DAY)**

**15 DAYS**  
*2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: