

15/5/2010

INS. CASE OWNER:

CC 6/EQI1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
20/11/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
23/1/19	Documentation Check List:	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE Date/Time: Sent By:		
FINALIZATION Date/Time: Confirm with: Confirm by:		
Repair Cost:	SS	(days) Reduction: % Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT Date/Time: Confirm with: Email <input type="checkbox"/> Call <input type="checkbox"/>		
Final Liability:	%	(Agreed / Assessed) BOIA S/N No.:
Repair Cost:	SS	
Loss of Rental (LOR):	SS	(days)
Loss of Use (LOU):	SS	(\$ x days)
Loss of Income (LOI):	SS	(\$ x days)
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>		[Tick only one]
GIA/LTA Search	SS	
Medical:	SS	
Disbursement:	SS	(e.g. Tow/ Independent)
Legal Cost	SS	
Total:	SS	Global Sum SS:
FINAL PAYMENT Date/Time: Confirm with: Email <input type="checkbox"/> Call <input type="checkbox"/>		
Payee 1:	SS	Name 1:
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$160

WUP
P. Passanger

ASS. REC. BY:

REF:

EQ1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLX 31530 Yr Regn: 01, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic c.c. 1799

Colour:

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

238176

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTM-FD16309S:201131

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Westlake.

Front

R/Bal.

4

mm

Rear

R/Bal.

6

mm

L/Bal.

4

mm

L/Bal.

6

mm

D.O.A.

13/11/18

D.O.I.

13/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/11 File pass to Catherine, GIA not reply.

US \$ 1500 (Rec'd 1444.00 / 497.1)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fix/Pos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI18020717/Kpb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 15-11-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 6478X	Veh. Inspected	SLX 3153D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/11/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/11/2018	Inspection Date	13/11/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/EQ118020717/Kpb3

Date: 15.11.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLX3153D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.11.2018 at the premises of M/s Wei Lee Motor Works and have the following to report:-

Workshop Estimate Amount	: S\$	2,944.80
Revised Estimate Amount	: S\$	1,500.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

13, Nov 2018

EQ Insurance Company Ltd
5, Maxwell Road #17-00
Tower Block MND Complex S 069110

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: YN6478X
Accident involving vehicle no: SLX3153D/YN6478X
DOA: 13/11/2018 AT 10 Eunos Road

Dear officer incharge
Re: Estimate of repair for vehicle no: SLX3153D
To supply—

Not Notched
11 By @ 150ch
Reusing After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Description	Qty	Amount
Front bumper	1 <i>Br</i>	576.00 ✓
Front bumper enforcement	1 <i>R</i>	210.00 X
Front bumper retainer	1 <i>Q.1</i>	42.00 ✓
Front fender	1 <i>B</i>	537.00 ✓
Headlamp	1 <i>Sn</i>	242.00 ✓
Headlamp lower bracket	1 <i>R</i>	48.00 X
Bumper foglamp	1 <i>Sn</i>	276.00 X
Total		1,931.00
Parts less 20%		386.20
		1,544.80

To remove damaged parts and attachments.
Repair/reshape damaged areas.
Replace/align all parts into position
To spray paint.

850.00 *400*
550.00 *400*

2,944.80

Shu Pei (LKKAUTO)

From: Justin Wong <justin.wong@eqinsurance.com.sg>
Sent: Friday, 16 November 2018 9:29 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Hsiao Tong (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving YN6478X (OI : EQI - TBA) AND SLX3153D (TP : LKK REF - CC6/EQI18020717/Kpb3) on 13.11.2018
Attachments: OI GIA - YN6478X.PDF

Dear Shu Pei,

Please find our insured's GIA report and proceed with direct settlement.

Thank you.

Regards,
Justin Wong
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Friday, November 16, 2018 8:58 AM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Direct Settlement - Accident Involving YN6478X (OI : EQI - TBA) AND SLX3153D (TP : LKK REF - CC6/EQI18020717/Kpb3) on 13.11.2018

WITHOUT PREJUDICE

Dear Justin,

We refer to the above matter.

We have inspected TP vehicle SLX 3153D at M/s Wei Lee Motor Works on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQ18020717/Kpb3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 24-01-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 6478X	Veh. Inspected	SLX 3153D	
Policy No.	DMCPHQ18-004966	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JHMFD16309S201131	Colour	METALLIC RED	
Odometer	238176	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55R16	WEST LAKE	4 mm	
L/H Front Tyre	205/55R16	WEST LAKE	4 mm	
R/H Rear Tyre	205/55R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/55R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/11/2018	Inspection Date	13/11/2018	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 3153D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BROKEN	576.00	576.00
1	FRONT BUMPER ENFORCEMENT	TO REPAIR SEE LABOUR	210.00	-
1	FRONT BUMPER RETAINER	DISTORTED	42.00	42.00
1	FRONT FENDER	BENT	537.00	537.00
1	HEADLAMP	CUT	242.00	242.00
1	HEADLAMP LOWER BRACKET	TO REPAIR SEE LABOUR	48.00	-
1	BUMPER FOGLAMP	SERVICEABLE	276.00	-
	LESS 20% DISCOUNT		-386.20	-279.40
			1,544.80	1,117.60
<u>LABOUR</u>				
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS. REPAIR / RESHAPE DAMAGED AREAS. REPLACE / ALIGN ALL PARTS INTO POSITION. INCLUSIVE OF THE REPAIR OF FRONT BUMPER ENFORCEMENT AND HEADLAMP LOWER BRACKET.		850.00	400.00
	TO SPRAY PAINT.		550.00	400.00
			1,400.00	800.00
GRAND TOTAL			2,944.80	1,917.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CC6/EQ118020717/Kpb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.