

INS. CASE OWNER:

CC3, QBE 180 70-118, 1/2/18

LAC:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$5

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 14/10/19 - vic

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5 1,850.00 (2 days) Reduction: 95 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 24

If NO or B 28, Ass. Lin:

Repair Cost: (w/acc)

\$5 1,979.80

(LOD RATE ENDED TP)

Loss of Rental (LOR):

\$5 105.84 (4 days) X \$101.40

Loss of Use (LOU):

\$5 - (\$ x days)

Loss of Income (LOI):

\$5 - (\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$5 7.49

Medical:

\$5 -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

\$5 -

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

\$5 -

3) Survey fee:

\$400.00

Total:

\$5 2,392.83

Global Sum \$5: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$5 2,392.83

Name 1:

TRANG-CAP AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

ASS. REC. BY:

REF: QBE1Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Tues Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S141-692B Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Peugeot Contuche c.c. 1995Colour: N. White / Red A/C: Insured / Std / NI / NASp. Reading: 241687 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABCLISAUC 281168Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NTI / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 12/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/11 File pass to Catherine11 Eyr 5/18501(Rate: 43 8083.64 (95%))

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - SI

Fixes

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I.: (\$ _____)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/QBE18020718/Kja3

Date: 19/11/2018

The Motor Claims Department
M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHF 692B

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/11/2018 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio have the following to report:-

Workshop Estimate Amount	: S\$	39,933.69	(est.)
Revised Estimate Amount	: S\$	1,850.00	(est.)
"Check" Items Amount	: S\$	-	(est.)
Total (Including Check Items)	: S\$	1,850.00	(est.)
Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

AAD1811-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHF 692B

Not Authored
1/1 Sep & 1/8501

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHF 692B

VF1ABL15AUC281168

RENAULT

LATITUDE

12.11.2018

QBE

PART**LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPER BRACKET SIDE RH REAR
- 5 1 BUMPER RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPER BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 OUTER PANEL REAR (End Panel)
- 14 1 OUTER PANEL REAR (End Panel)TRIM
- 15 1 TAILLAMP RH
- 16 1 TAILLAMP PANEL RH
- 17 1 TAILLAMP LH
- 18 1 TAILLAMP PANEL LH
- 19 1 BOOT REAR
- 20 1 BOOT FINISHER
- 21 1 BOOT WHEATERSTRIP
- 22 1 BOOT REFLECTOR LAMP LH
- 23 1 BOOT REFLECTOR LAMP RH
- 24 1 BOOT BADGE 'RENAULT'
- 25 1 BOOT BADGE
- 26 1 BOOT STRUT LH
- 27 1 BOOT STRUT RH
- 28 1 BOOT HINGE LH
- 29 1 BOOT HINGE RH

\$	<i>Per/Rea</i>	1,108.46	✓
\$	<i>Per/LH</i>	768.84	✓
\$	<i>SH</i>	113.47	} X
\$	<i>SH</i>	135.97	
\$	<i>SH</i>	44.99	
\$	<i>SH</i>	43.61	
\$	<i>SH</i>	135.97	
\$	<i>SH</i>	44.99	
\$	<i>SH</i>	43.61	
\$	<i>R</i>	777.52	
\$	<i>R</i>	225.95	
\$	<i>R</i>	225.95	
\$	<i>R</i>	1,471.77	
\$	<i>SH</i>	404.56	
\$	<i>SH</i>	552.55	
\$	<i>R</i>	986.70	
\$	<i>SH</i>	552.55	
\$	<i>R</i>	986.70	
\$	<i>R</i>	2,872.68	
\$	<i>SH</i>	470.06	
\$	<i>SH</i>	323.05	
\$	<i>SH</i>	493.35	
\$	<i>SH</i>	493.35	
\$	<i>SH</i>	225.36	
\$	<i>SH</i>	225.36	
\$	<i>SH</i>	276.08	
\$	<i>SH</i>	276.08	
\$	<i>R</i>	367.84	
\$	<i>R</i>	367.84	

Trans-cab Auto Services Pte Ltd

AAD1811-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 692B

30	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45 X
31	1 BOOT SWITCH	\$	<i>Sn</i> 168.13 X
32	1 BOOT LOCK	\$	<i>R</i> 202.67 X
33	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40 X
		\$	16,046.87
		10% \$	7.44
		\$	16,039.43

Specical Nett

1	1SET PARKING AID	\$	<i>Sn</i> 700.00 X
2	1SET REAR BUMPER CLIP	\$	<i>R</i> 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>R</i> 33.00 ✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>R</i> 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>R</i> 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>R</i> 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>R</i> 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>R</i> 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>R</i> 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	<i>R</i> 17.82 X
11	2 REAR WINDSCREEN SELANT	\$	<i>R</i> 80.00 X
12	1 WINDSCREEN MOULDING	\$	<i>R</i> 100.00 X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>R</i> 100.00 X

TOTAL \$ 1,244.82**TOTAL PARTS \$ 17,284.25****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>220%</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 <i>200%</i>

Trans-cab Auto Services Pte Ltd**AAD1811-103**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 692B

To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>4</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
TOTAL	\$	6,610.00	

Over All Total \$ 39,933.69**(LUMP SUM)****Repair Days***10 DAYS**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

3878K

Vehicle Details

Vehicle No.:

SHF692B

Vehicle to be Exported:

Yes

Intended Deregistration Date:

13 Nov 2018

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour:

Red

Manufacturing Year:

2014

Engine No.:

M9R8839C002446

Chassis No.:

VF1ABL15AUC281168

Maximum Power Output:

127.0 kW (170 bhp)

Open Market Value:

\$19,998.00

Original Registration Date:

31 Dec 2014

First Registration Date:

31 Dec 2014

Transfer Count:

0

Actual ARF Paid:

\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

30 Dec 2022

PARF Rebate Amount:

\$9,373.00

Intended COE Rebate Details

COE Expiry Date:

30 Dec 2022

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$51,668.00

COE Rebate Amount:

\$26,667.00

Total Rebate Amount:

\$36,040.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Nov 2018

OK

Mei Kwan (LKKAuto)

From: Janice Goh Siew Geok <janice.goh@qbe.com>
Sent: Tuesday, 8 October, 2019 10:04 AM
To: Mei Kwan (LKKAuto)
Cc: Vic (LKKAuto); Admin A; Jenny Toh
Subject: RE: Direct Settlement - Accident Involving GBA7452D (OI : QBE - TBA) and SHF692B (TP : LKK REF - CC3/QBE18020718/Kja3) on 12/11/2018
Attachments: GBA7452D.pdf

Re-send

Janice Goh

Executive, Claims

Claims | Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6477 1243

[Website](#) [LinkedIn](#) [Twitter](#)



From: Janice Goh Siew Geok
Sent: Tuesday, 8 October 2019 10:03 AM
To: 'Mei Kwan (LKKAuto)' <Meikwan@lkkauto.com>
Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Jenny Toh <jenny.toh@qbe.com>
Subject: RE: Direct Settlement - Accident Involving GBA7452D (OI : QBE - TBA) and SHF692B (TP : LKK REF - CC3/QBE18020718/Kja3) on 12/11/2018

Hi Mei Kwan

As requested, please refer to the attachment.

Thank you.

Janice Goh

Executive, Claims

Claims | Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6477 1243

[Website](#) [LinkedIn](#) [Twitter](#)



From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 8 October 2019 9:54 AM
To: Jenny Toh <jenny.toh@qbe.com>; Janice Goh Siew Geok <janice.goh@qbe.com>
Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/QBE18020718/Kha3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 19-12-2019



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7452D	Veh. Inspected	SHF 692B
Policy No.	8-V0016347MVA	Coverage (\$)	0.00
Claim No.	VC011922	Excess (\$)	0.00
Assign From		Assign Date	14/11/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC281168	Colour	METALLIC WHITE / RED
Odometer	241687	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	7 mm
L/H Rear Tyre	215/60 R16	GITI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/11/2018	Inspection Date	14/11/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 692B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BUCKLED / DENTED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-

Report Ref No. CC3/QBE18020718/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
	LESS 10% DISCOUNT		-1,604.68	-187.73
			14,442.18	1,689.57
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			1,244.82	165.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	220.00

Report Ref No. CC3/QBE18020718/Kha3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR,BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,OUTER PANEL REAR (END PANEL),TAILLAMP PANEL RH,TAILLAMP PANEL LH,BOOT REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK AND BOOT LOCK CATCH.		2,200.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			6,610.00	480.00
GRAND TOTAL			22,297.00	2,334.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,850.00

Report Ref No. CC3/QBE18020718/Kha3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.