



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte
60 Woodlands Industrial Park E4
FAX Number : 63685592
Estimator Telephone Number : 61
Accident Reporting Number : 68



Date Generated : 14/11/2018

User ID : TanAhLeo

Section A - Accident Details	
Registration Number	SMB5081T
Case Reference Number	BUS/11/18/1004
Registration Date	1/9/2015
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Zainuddin Bin Abu Bakar
Type of Accident	Side Swipe
Accident Date and Time	1/11/2018 4:00 PM
Accident Reported Date and Time	2/11/2018 3:51 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB5081T - LEFT CENTRE PORTION PH9559H (TP) - RIGHT VIEW MIRROR. INSURED WITH CHINA TAIPING
Prepared Date and Time	14/11/2018 12:59 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$200.00	\$0.00
<b>TOTAL COST</b>	<b>\$0.00</b>	<b>\$0.00</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2
Prepared / Adjusted By	Tan Ah Leong	
ARC / Surveyor Sign Off Date	14/11/2018 1:03 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte  
60 Woodlands Industrial Park E4  
FAX Number : 63685592  
Estimator Telephone Number : 61  
Accident Reporting Number : 68

Date Generated : 14/11/2018

User ID : TanAhLeon

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION CENTER	\$1,060.00	800
Total Labour	\$1,060.00	

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	700
Total Spray Painting & Panel Beating	\$878.00	

### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PIXEL STENCIL LHS MID	\$200.00	NEC (SNETT)
Total Other Costs	\$200.00	

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									

### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

NA2 LK1C

14/11/18

14/11/18

L/S

2 DAYS

AFTER REPAIR PHOTOS.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: