

ASS. REC. BY:

REF: CS/AGI18020723 / Ksd3

n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Albert Hong

of

AGI

Date/Time: 15/11/18 3:32pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KW 2313H

Insured:

8KA 4625K

at Workshop m/s

Tong Luck Auto

Tel:

6250 0088

of

160 Sin Ming Drive #07-01/06

Policy No:

Claim No:

C10002238

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/11/18

CA / REV / REP. / REV 24 HRS 'up'

16/11/2018

H.O.D. Endorsement:

Date/Time: 4

15/11/18

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

8KW 2313H-X

8KA 4625K-X

Surveyor

REF: AGI

ASSIGNMENT

From: Date: 16/11/2018

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 2313H
at Workshop m/s Tong Luck Auto
of 160 sin Ming Drive #07-01/06

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2-3 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKW 2313H Yr Regn: 10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3

c.c.

1496

Colour: M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading: 32904

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM 6BM 42A 8G-031894

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

205/80R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Atxen

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 14/11/18

D.O.I. 16/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/11 File notes to Corbin

22/11/18 Confirmed e/p \$1,934.84 @ 3 days with Kenneth
(\$3,143.88 Red - 62%)

RECEIVED 22 NOV 2018

Date/Time, File Pass to?

22/11/18

1) Typist
Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$ 1,934.84 p/p)

TOTAL

250

Nivitha (LKK Auto)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Thursday, 15 November 2018 3:32 PM
To: 'assignments'
Cc: 'SUR'
Subject: Appoint LKK to conduct TP survey; Our Ref: C10002238
Attachments: SKW2313H - NOA.pdf

Hi Team,

Please accept survey request and liaise with TP workshop.

Kenneth was selected by TP workshop.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: Operation / Yu Ching <operation@tlauto.com.sg>
Sent: Thursday, 15 November, 2018 2:46 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: ACCIDENT INVOLVING VEHICLE NO.: SKW2313H & SKA4625K ON 14/11/2018 @ 0705 HRS ALONG CTE TOWARDS PIE FLYOVER TOWARD CHANGI

Dear All,

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop

Kindly let us have the surveyor list and arrange for the vehicle to be inspect at an earlier date

Thanks & regards,
Yu Ching



Tong Luck Auto Pte Ltd

160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LIMITED

15 November 2018

190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

Attn: MOTOR CLAIMS DEPT

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SKW2313H & SKA4625K ON 14/11/2018 @ 07:05 HRS
ALONG CTE TOWARDS PIE FLYOVER TOWARD CHANGI

We hereby authorized by our client **DAIMLER FLEET MANAGEMENT S'PORE PTE LTD**, the owner/driver of the above mentioned vehicle No.: **SKW2313H**

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: **SKA4625K**

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: **SKW2313H** and vehicle No.: **SKA4625K** by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at: **TONG LUCK AUTO PTE LTD**
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/11/2018 14:30
Date Of Accident	14/11/2018 07:05
Exact Location Of Accident	CTE TOWARD PIE FLYOVER TOWARD CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW2313H
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	DERRICK.LEE@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-82821711

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	

Driver

Name of Driver	BEH CHEE KEONG
NRIC No	S8461229D
Date Of Birth	21/11/1984
Occupation	OUTDOOR
Date Of Driving Pass	06/09/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96476656
Fax Number	
Contact Number	
Email Address	BENNETH.CHEEKEONG@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PANG CHANG XIANG GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along CTE TOWARDS PIE flyover my vehicle was stationary due to heavy traffic suddenly vehicle GZ4458S front collided onto vehicle SKA4625K rear and vehicle SKA4625K front collided onto my vehicle SKW2313H rear. No injuries involved CHAIN COLLISION TOTAL OF 3 VEHICLES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING VIDEO FROM INSURED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA4625K
Vehicle Make/Model/Colour	NISSAN/JUKE 1.6 A/T/BROWN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM MEIXIA, LARENE
NRIC/Passport Number	S8200562E
Contact Number	82680905
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GZ4458S

Vehicle Make/Model/Colour

MITSUBISHI/FB70ABOSRDEB/WHITE

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

YANG YANBO

NRIC/Passport Number

S8260848F

Contact Number

86869980

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if possible.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
Mohamed Saifullah S/O Syed
Masood
Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was travelling along CTE TOWARDS PIE flyover my vehicle was stationary due to heavy traffic suddenly vehicle GZ4458S front collided onto vehicle SKA4625K rear and vehicle SKA4625K front collided onto my vehicle SKW2313H rear. No injuries involved

CHAIN COLLISION TOTAL OF 3 VEHICLES.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SAIFULLAH S/O SYED MASOOD

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

14 November 2018 at 12:32 PM



Date/Time:

14 November 2018 at 12:32 PM

Identification Card

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8461229D



Name
BEH CHEE KEONG

马 志 强

Race
CHINESE

Date of birth
21-11-1984

Sex
M

Country/Place of birth
MALAYSIA

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S8461229D

Name
BEH CHEE KEONG

Birth Date 21 Nov 1984

Issue Date 05 Nov 2014



002362339E

Identification Card

9330737



NRIC No. S8461229D



Nationality
MALAYSIAN

Date of issue
14-05-2014

PT BLK 589D MONTREAL DRIVE #02-116
SINGAPORE 754589


NRIC No. S8461229D Date 08/01/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg	06 Sep 2010

NP 428A

Licence No: S8461229D





TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCCOUNT DEPT

YOUR REF NO : SKA4625K

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AUTO & GENERAL INSURANCE (SINGAPORE) F

ACCIDENT DATE : 14/11/2018

TP VEH REG NO : SKA4625K

ESTIMATE

NO : QUOT201811-000046(00)

DATE : 15/11/2018

POLICY NO : 999995580

VEH REG NO : SKW2313H

MAKE/MODEL : MAZDA MAZDA3 4-DOOR
SEDAN 1.5L SP.6EAT

CHASSIS NO : JM6BM42A8G0318941

ENGINE NO : P520318195

REG. DATE : 2015

Not Authored

Resurvey B4 point

2-3 days

Estimate Repair Cost to Vehicle No : SKW2313H

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Rear end panel	1	535.10	535.10 X
2 Rear bumper	1	1,094.80	1,094.80 ✓
3 Rear bumper reinforcement	1	587.30	587.30 X
4 Rear bumper centre bracket	1	55.30	55.30 X
5 Rear bumper side retainer - LH/RH	2	89.20	178.40 X
6 Rear bumper clips	15	9.00	135.00 160
			2,585.90
		Less 20%	517.18
			2,068.72
SPECIAL NET			
7 Rear bumper sensor (set)	1	350.00	350.00 200.00
			350.00
LABOUR			
8 To remove and refix rear bumper sensor	1	100.00	100.00 50.00
9 To check and rectify wiring system	1	80.00	80.00 15.00
10 To remove and refix rear interior garnishes and trimboard to facilitates the repairs	1	160.00	160.00 X
11 To panel beat straighten rear chassis frame, rear floorboard panel, to cut and weld rear end panel including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 300.00
12 To putty and spray same on affected areas	1	1,200.00	1,200.00 450.00
13 To apply rust proofing on repaired and replaced panels	1	120.00	120.00 X
			2,660.00

TOTAL S\$ 5,078.72

ADD GST @ 7% 355.51

GRAND TOTAL S\$ 5,434.23

SINGAPORE DOLLAR FIVE THOUSAND FOUR HUNDRED THIRTY-FOUR AND CENTS TWENTY-THREE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts/area
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FOR TONG LUCK AUTO PTE LTD

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER

SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCCOUNT DEPT

YOUR REF NO : SKA4625K

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AUTO & GENERAL INSURANCE (SINGAPORE) F

ACCIDENT DATE : 14/11/2018

TP VEH REG NO : SKA4625K

ESTIMATE

NO : QUOT201811-000046(00)

DATE : 15/11/2018

POLICY NO : 999995580

VEH REG NO : SKW2313H

MAKE/MODEL : MAZDA MAZDA3 4-DOOR
SEDAN 1.5L SP.6EAT

CHASSIS NO : JM6BM42A8G0318941

ENGINE NO : P520318195

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SKW2313H

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Rear-end panel	1	535.10	535.10 X
2 Rear bumper	1	1,094.80	1,094.80 ✓
3 Rear bumper reinforcement	1	587.30	587.30 ?
4 Rear bumper centre bracket	1	55.30	55.30 ?
5 Rear bumper side retainer - LH/RH	2	89.20	178.40 X
6 Rear bumper clips (necessary)	15	9.00	135.00 760
			2,585.90
		Less 20%	517.18
			2,068.72
SPECIAL NET			
7 Rear bumper sensor (set)	1	350.00	350.00 2001n
			350.00
LABOUR			
8 To remove and refix rear bumper sensor	1	100.00	100.00 501
9 To check and rectify wiring system	1	80.00	80.00 151
10 To remove and refix rear interior garnishes and trimboard to facilitates the repairs	1	160.00	160.00 X
11 To panel beat straighten rear chassis frame, rear floorboard panel, to cut and weld rear end panel including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 301
12 To putty and spray same on affected areas	1	1,200.00	1,200.00 4501
13 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00 X
			2,660.00
parts : \$ 875.84		TOTAL	S\$ 5,078.72
S/N : \$ 260.00		ADD GST @ 7%	355.51
Labour : \$ 815.00		GRAND TOTAL	S\$ 5,434.23

SINGAPORE DOLLAR FIVE THOUSAND FOUR HUNDRED THIRTY-FOUR AND CENTS TWENTY-THREE ONLY

\$ 1,950.84 1934.84
 7% 136.56
 \$ 2,087.40

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI18020723/Ksd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 28-11-2018	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKA 4625K	Veh. Inspected	SKW 2313H
Policy No.		Coverage (\$)	0.00
Claim No.	C10002238	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	15/11/2018
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0318941	Colour	METALLIC PEARL WHITE
Odometer	32904	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	NEXEN	8 mm
L/H Front Tyre	205/60 R16	NEXEN	8 mm
R/H Rear Tyre	205/60 R16	NEXEN	8 mm
L/H Rear Tyre	205/60 R16	NEXEN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/11/2018	Inspection Date	16/11/2018
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 2313H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR END PANEL	TO REPAIR SEE LABOUR	535.10	-
1	REAR BUMPER	BENT	1,094.80	1,074.80
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	587.30	-
1	REAR BUMPER CENTRE BRACKET	TO REPAIR SEE LABOUR	55.30	-
2	REAR BUMPER SIDE RETAINER-LH/RH @\$89.20	SERVICEABLE	178.40	-
	LESS 20% DISCOUNT		-490.18	-214.96
			1,960.72	859.84
15	REAR BUMPER CLIPS @\$9.00 (SN)	NECESSARY	135.00	60.00
	LESS 20% DISCOUNT		-27.00	-
			108.00	60.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER SENSOR (SN)	SHORTED	350.00	200.00
			350.00	200.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIX REAR BUMPER SENSOR.		100.00	50.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	15.00
	TO REMOVE AND REFIX REAR INTERIOR GARNISHES AND TRIMBOARD TO FACILITATE THE REPAIRS.	NOT NECESSARY	160.00	-
	TO PANEL BEAT STRAIGHTEN REAR CHASSIS FRAME, REAR FLOORBOARD PANEL, TO CUT AND WELD REAR END PANEL INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL, REAR BUMPER REINFORCEMENT AND REAR BUMPER CENTRE BRACKET.		1,000.00	300.00
	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS.		1,200.00	450.00
	TO APPLY RUST PROOFING ON REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			2,660.00	815.00
	GRAND TOTAL		5,078.72	1,934.84
	RECOMMENDED COST OF REPAIRS			1,934.84

Report Ref No. CS/AGI18020723/Ksd3n2



Report Ref No. CS/AGI18020723/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.