

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

15 NOV 2018

E S T I M A T E

Estimate No. : b1 49118
Date Estimated : 15/11/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Low Wee Hong Jimmy
100 Edgedale Plains
#04-42

Singapore 828690

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF4949B	WE60132	30/07/2018	520i	0

DESCRIPTION

VALUE

To replace rear left door. To repair on front left side panel, front left door, rear left side panel, rear bumper & all attachments cause by accident.

4250- 5,100.00

Painting on front left side panel, front left door, rear left door, rear left side panel & rear bumper

4/20- 4,578.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function.

451 531.00

To check electrical wiring systems for proper fnction.

150 177.00

To carry out body cavity preservation.
(Per panel) Rear left door

600 118.00

Sundries.

? 150.00

Total Labour 1: 10,654.00

DESCRIPTION

QTY PRIC

VALUE

REAR LH DOOR ALUMINIUM
EMBLEM (M)

1 1,863.20
1 81.90

66- 1,863.20
re- 81.90

REAR LH DOOR WINDOW GUIDE

1 109.35

? 109.35

REAR LH DOOR TOP WINDOW FRAME FINIS

1 239.15

? 239.15

RR LH DOOR COLUMN B COVER (GLANZSCH

1 49.10

? 49.10

LH WINDOW GUIDE WEB COVER (GLANZSCH

1 100.70

? 100.70

REAR LH DOOR OUTER CHANNEL COVER (G

1 114.80

? 114.80

REAR LH DOOR LOWER SEAL

1 42.60

? 42.60

LH TRIM AIR DUCT SIDE PANEL (GLANZS

1 64.60

? 64.60

Total Parts : 2,665.40

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49118
Date Estimated : 15/11/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF4949B	WE60132	30/07/2018	520i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 19/12/18 Excess S\$ _____

Surveyor's Name Tan Sign [Signature]

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tan@hamp.wm

No. of Working Days Recommend 8-9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	10,654.00
Parts	:	2,665.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	932.36
Grand Total	:	14,251.76

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **