



凱摩多服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 15/11/2018

Attn: The Motor Claims Department
Your Insured veh no : SKV 4631 G
AIG ASIA PACIFIC INSURANCE PTE LTD.
78 Shenton Way
07-16 Chartis Building
Singapore 079120

TP AIG

Xiao Tony

WITHOUT PREJUDICE

(By Email Only)

call Adrian
15.11.2018

Dear Sir / Madam

Estimate Cost repair Bill To Honda City No SJW 6823 M & SKV 4631 G on 10/11/2018 @20:00:00

To Supply:

1pc	Front bonnet	Dented		\$ 402.20	✓
1pc	Front grille	Crushed		\$ 106.60	✓
1pc	Front bumper	Repair		\$ 459.80	✓
1pc	Front number plate	But		\$ 55.00	✓
2pcs	Front bumper retainer	2 new	\$ 16.80	\$ 33.60	✓
1pc	Rear bumper lamp	new		\$ 215.70	+
1pc	Rear bumper	Replaced		\$ 463.70	✓
8pcs	Rear bumper clip	new	1057.50	\$ 50.00	31
1pc	Rear panel	Repair	846	\$ 323.90	+
				\$2,110.50	
			less	20%	\$ 422.10
					\$1,688.40
1set	Reverse sensor	2nd	200	\$ 280.00	200 nett
			less	10%	\$ 28.00
					\$ 252.00

To check wiring functions.

\$ 60.00 30

To remove reverse sensor.

\$ 80.00 50

To dismantle and replace of the accident damaged parts, knocking, repair, adjust and reshape of same.

\$ 850.00 500

To putty, apply primer & spray paint on the affected portion.

\$ 900.00 600

\$3,830.40

- LKK Auto Consultants hence notify the Repairer of the following:
- To display damaged parts during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Limy. tel: 2226
L/S 20/12/18 4/S: 1750
OS Amp