



Section A - Accident Details

Registration Number	SHC47125
Case Reference Number	TAX/11/18/2032
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN WIL LIAM
Type of Accident	Side Swipe
Accident Date and Time	8/11/2018 7:48 AM
Accident Reported Date and Time	8/11/2018 10:53 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	Yes
Towed Back Date and Time	8/11/2018 8:35 AM
Replacement Vehicle Issued?	No
Job Card Number	24098548
Special Instruction to ARC, if any	TOWED S40 / CHINA - LKK
Prepared Date and Time	9/11/2018 2:10 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



b014

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,383.00	\$700.00
Total Spray Cost	\$3,348.00	\$1,000.00
Total Spare Part Cost	\$17,643.80	\$8,051.00
Total Other Cost	\$1,806.00	\$560.00
TOTAL COST	\$23,980.80	\$10,311.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Naz (LKK) / China Tsiping
ARC / Surveyor Sign Off Date	12/11/2018 4:32 PM	12/11/2018 4:30 PM
Signature		
Remarks	Initial estimates = 8 days Request number of days to extend 2 days SUP = 1 DAYS	
	PART BY PART REPAIR, 5 DAYS. CHECK ITEMS PHOTOS, BEFORE PAINT PHOTOS	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Henderson Industrial Park E.C, Singapore 151796
TAX Number: EN00102
Telephone Number: 6800102
Accident Reporting Number: 6800101

Date Generated: 28/06/2019
User ID: 1 Fieldson

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0289	Invoice Number	
Quotation Date	24.06.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR DOOR LH	\$200.00	\$100.00 ✓
TO REPAIR FRONT LH PORTION	\$1,183.00	\$600.00 ✓
Total Labour	\$1,383.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$50.00 ✓
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00 ✓
TO RESPRAY REAR DOOR LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$3,348.00	\$1,580.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$40.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$60.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$250.00	\$250.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00 ✓
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$100.00 ✓
TO REMOVE AND REFIT WIRE HARNESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,606.00	\$540.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
20 Woodlands Industrial Park 24, Singapore 757128
TAX Number: 8000033
Estimate Number: 00000000
Accident Report Number: 00000000

Estimate Generated: 20/06/2019
User ID: PchDun

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator	Surveyor	
67002471	02		PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,249.60	25.00	\$937.20	Approved Replace	Approved Replace	EF
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	NEC
986104704	0		CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Check	X
687201215	1		HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$82.10	0.00	\$0.00	Replace	Check	X
687401212	0		HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$92.10	0.00	\$0.00	Replace	Check	X
682104705	1A1		DOOR OUTER HANDLE FRONT, LH	1.00	\$378.90	25.00	\$284.18	Replace	Replace	SC
681264703	0		GLASS, FRONT DOOR FIX WINDOW, LH	1.00	\$309.90	25.00	\$232.43	Replace	Replace	NEC
682164701	0		WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	0.00	\$74.30	0.00	\$0.00	Replace	Check	X
681024723	0		GLASS SUB-ASSY, FRONT DOOR, LH	0.00	\$796.70	0.00	\$0.00	Replace	Not Given	X
990404710	0		LOCK ASSY, FRONT DOOR LH	0.00	\$544.70	0.00	\$0.00	Replace	Check	X
684102011	0		DOOR LOCK STRIKER	0.00	\$36.00	0.00	\$0.00	Replace	Check	X
757524701	0		MOULDING, FRONT DOOR WINDOW FRAME, FRONT	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
757204704	0		MOULDING ASSY, FRONT DOOR BELT, LH	0.00	\$88.60	0.00	\$0.00	Replace	Check	X
879404744	0		MIRROR ASSY, OUTER REAR VIEW, LH	1.00	\$1,283.90	10.00	\$1,155.51	Replace	Replace	CRK
879454706	0A1		COVER, OUTER MIRROR, LH	1.00	\$89.50	25.00	\$67.13	Replace	Replace	CRK
670044721	0		PANEL SUB-ASSY, REAR DOOR, LH	0.00	\$1,243.90	0.00	\$0.00	Replace	Not Given	X
676964701	0		WEATHERSTRIP, REAR DOOR, NO. 2, LH	0.00	\$33.20	0.00	\$0.00	Replace	Not Given	X
757404704	0		MOULDING ASSY, REAR DOOR BELT, LH	0.00	\$109.80	0.00	\$0.00	Replace	Not Given	X
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
758604790	0		MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$576.00	25.00	\$432.00	Replace	Replace	DEF
52119479	02		COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.53	Replace	Replace	CRK
52128479	06		COVER, FR BUMPER LH	1.00	\$26.10	25.00	\$19.58	Replace	Replace	MIS
			NUMBER PLATE	0.00	\$35.00	0.00	\$0.00	Replace	Not Given	X
			NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given	X
52161160	10		CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	X
53112472	40		GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Check	X
52116470	50		SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Check	X
81220470	20		LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Check	X
52611471	40		ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X
52021471	10		REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check	X
52616470	30		ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check	X
52132470	10		REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Check	X
52103470	10		EXTENSION SUBASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X
52102470	20		EXTENSION SUBASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X
51420470	30		COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check	X
53301471	10		HOOD SUB-ASSY	0.00	\$938.40	0.00	\$0.00	Replace	Check	X
75656470	20		MOULDING LH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X
51014470	10		PILLAR, FRONT BODY, LH	0.00	\$339.40	0.00	\$0.00	Replace	Check	X
501184702	0		COVER SUB-ASSY, FRONT PILLAR, UPR LH	0.00	\$96.90	0.00	\$0.00	Replace	Check	X
53214470	10		SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X
61185476	91		UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	SC
53802471	00		FENDER SUB-ASSY, FR LH	1.00	\$833.10	25.00	\$624.83	Replace	Replace	DEF



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park East, Singapore 757106
TAX Number: A0200000
Company Telephone Number: 63455153
Accident Reporting Number: 00020470

Date Generated: 28/05/2018
User: BT

75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	X	NEC
53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Check	X	
53852470 41	RAD. FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Check	X	
53702471 01	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$944.20	0.00	\$0.00	Replace	Check	X	SUL
53820470 70	PROTECTOR, FR FENDER LH	0.00	\$90.40	0.00	\$0.00	Replace	Check	X	
	TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	X	partially
42811-47450	WHEEL, DISC FRONT	1.00	\$1,595.10	100.00	\$0.00	Replace	Repair	X	
48520804 92	ABSORBER SET, SHOCK, FRONT LH	0.00	\$398.10	0.00	\$0.00	Replace	Check	X	
48820470 40	LINK ASSY, FRONT STABILIZER, RH & LH	0.00	\$196.70	0.00	\$0.00	Replace	Check	X	
48069470 80	LOWER ARM SUBASSY, FRONT LH	0.00	\$631.60	0.00	\$0.00	Replace	Check	X	SUL
43330191 15	JOINT ASSY, LWR BALL, RH & LH	0.00	\$200.10	0.00	\$0.00	Replace	Check	X	
43212470 40	KNUCKLE, STEERING, LH	0.00	\$555.20	0.00	\$0.00	Replace	Check	X	
Total			\$20,404.04		\$6,741.57				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
	BODY LH	69217470 20	DOOR FRONT, COVER OUTER HANDLE, LH	1.00	\$17.30	25.00	\$12.98	Replace	Replace	SUR
		81220470 20	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	CRK
		88720121 51	HINGE ASSY, FRONT DOOR, UPPER LH	1.00	\$82.10	25.00	\$61.58	Replace	Replace	BT
		88740121 20	HINGE ASSY, FRONT DOOR, LOWER LH	1.00	\$92.10	25.00	\$69.08	Replace	Replace	ST
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	REPORT
		53876471 10	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace	TN
	BODY LH	88202470 40	DOOR FRAME INNER HANDLE FRONT, LH	1.00	\$187.70	25.00	\$140.78	Replace	Replace	BT
Total					1,543.70		1,309.33			

28558.24

$$\begin{array}{r} 8051.00 \\ + 700.00 \\ + 1560.00 \\ \hline 10,311.00 \end{array}$$

FINALIZED PART, BY PART REPAIR \$10,311.00 / 6 REPAIR DAYS

NAZ LKK

H

1/7/19



Case Details

Case Reference Number : TAX/11/18/2032

Type of Repair : Accident Repair

Vehicle Registration Number : SHC47125

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-4448-ID

Assigned By : Kok Wah Wong

Insurance Company Name : China Taping Insurance (Singapore) Pte Ltd

Accident Date and Time : 07/11/2018 11:45 PM

Vehicle Age(In Months) : 11

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	937.20	Replace ✓ DEF
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ✓ NEL
One Time Key In	Main			CHECK ASSY, FRONT DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Check ✓ ? } Svc
One Time Key In	Main			HINGE ASSY, FRONT DOOR, UPPER LH	1	82.10	82.10	25.00	61.57	Replace	0	0	Check ✓ ? } Svc
One Time Key In	Main			HINGE ASSY, FRONT DOOR, LOWER LH	1	92.10	92.10	25.00	69.07	Replace	0	0	Check ✓ ? } Svc
One Time Key In	Main			DOOR OUTER HANDLE FRONT, LH	1	378.90	378.90	25.00	284.17	Replace	1	284.17	Replace ✓ Svc
One Time Key In	Main			GLASS, FRONT DOOR FIX WINDOW, LH	1	308.90	308.90	25.00	232.42	Replace	1	232.42	Replace ✓ NEL
One Time Key In	Main			WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	1	74.30	74.30	25.00	55.72	Replace	0	0	Check ✓ ? Svc
One Time Key In	Main			GLASS SUB-ASSY, FRONT DOOR, LH	1	796.70	796.70	25.00	597.53	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			LOCK ASSY, FRONT DOOR LH	1	544.70	544.70	10.00	490.23	Replace	0	0	Check ✓ ? } Svc
One Time Key In	Main			DOOR LOCK STRIKER	1	38.00	38.00	25.00	28.50	Replace	0	0	Check ✓ ? } Svc
One Time Key In	Main			MOULDING, FRONT DOOR WINDOW FRAME, FRONT LH	1	37.40	37.40	25.00	28.05	Replace	0	0	Check ✓ ? } Svc
One Time Key In	Main			MOULDING ASSY, FRONT DOOR BELT, LH	1	89.60	89.60	25.00	67.20	Replace	0	0	Check ✓ ? } Svc
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, LH	1	1,283.90	1,283.90	10.00	1,155.51	Replace	1	1,155.51	Replace ✓ CRX
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	89.50	89.50	25.00	67.13	Replace	1	67.13	Replace ✓ CRX
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	1,243.90	25.00	932.93	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			WEATHERSTRIP, REAR DOOR, NO.2, LH	1	33.20	33.20	25.00	24.90	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			MOULDING ASSY, REAR DOOR BELT, LH	1	109.80	109.80	25.00	82.35	Replace	0	0	Not Give ✓ X Svc
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give ✓ ANN

Total Spare Part Cost 15,334.49

Surveyor Total 6,741.64

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 15,334.49

Final Sur Total 6,741.64

SMRT Recommendation										Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dhs(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	576.00	25.00	432.00	Replace	1	432.00	Replace * /OK
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace * /OK
One Time Key In	Main			COVER, FR BUMPER LH	1	26.10	26.10	25.00	21.08	Replace	1	21.08	Replace * /MIS
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give * X SUC
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give * X SUC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace * /NGL
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Check * ?
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Check * ?
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check * ?
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check * ?
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check * ?
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Check * ?
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Check * ?
One Time Key In	Main			EXTENSION SUBASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check * ?
One Time Key In	Main			EXTENSION SUBASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check * ?
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Check * ?
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	0	0	Check * ?
One Time Key In	Main			MOULDING LH	1	83.30	83.30	25.00	62.47	Replace	0	0	Check * ?
One Time Key In	Main			PILLAR, FRONT BODY, LH	1	339.40	339.40	25.00	254.55	Replace	0	0	Check * ?
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR, UPR LH	1	96.90	96.90	25.00	72.68	Replace	0	0	Check * ?
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check * ?
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace * /SQ
One Time Key In	Main			FENDER SUB-ASSY, FR, LH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace * /DGP
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace * /NGL
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0	Check * ?
One Time Key In	Main			PAD, FR WHEEL LH	1	57.70	57.70	25.00	43.28	Replace	0	0	Check * ?
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER, LH	1	944.20	944.20	25.00	708.15	Replace	0	0	Check * ?
Total Spare Part Cost										16,334.49	Surveyor Total	6,741.64	
Lump Sum Discount (%)										0.00	Lump Sum Dis (%)	0	
Final Spare Part Cost										16,334.49	Final Sur Total	6,741.64	

SMRT Recommendation										Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			PROTECTOR, FR FENDER LH	1	90.40	90.40	25.00	67.80	Replace	0	0	Check * ? Src
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace * ? pm4met
One Time Key In	Main			WHEEL DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair * xR
One Time Key In	Main			ABSORBER SET, SHOCK, FRONT LH	1	398.10	398.10	25.00	298.58	Replace	0	0	Check * ?
One Time Key In	Main			LINK ASSY, FRONT STABILIZER, RH & LH	1	196.70	196.70	25.00	147.52	Replace	0	0	Check * ? } Src
One Time Key In	Main			LOWER ARM SUBASSY, FRONT LH	1	631.60	631.60	25.00	473.70	Replace	0	0	Check * ?
One Time Key In	Main			JOINT ASSY, LWR BALL, RH & LH	1	200.10	200.10	25.00	150.07	Replace	0	0	Check * ?
One Time Key In	Main			KNUCKLE, STEERING, LH	1	555.20	555.20	25.00	416.40	Replace	0	0	Check * ?
Total Spare Part Cost									15,334.49	Surveyor Total 6,741.64			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0			
Final Spare Part Cost									15,334.49	Final Sur Total 6,741.64			

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT LH PORTION	1,183.00	600	
Total:		1,183.00	600.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO REPSRAY FRONT HOOD	378.00	0	CHECK
3	TO REPSRAY FRONT SUPPORT PANEL	180.00	0	CHECK
4	TO REPSRAY FRONT PILLAR LH	180.00	0	CHECK
5	TO REPSRAY FRONT FENDER LH	378.00	200	
6	TO REPSRAY APRON PANEL LH	180.00	0	CHECK
7	TO REPSRAY RIM	180.00	50	
8	TO REPSRAY FRONT DOOR LH	378.00	200	
9	TO REPSRAY VIEW MIRROR	180.00	50	
10	TO REPSRAY ROCKER PANEL MOULDING	180.00	100	
11	TO REPSRAY REAR DOOR LH	378.00	0	NN
Total:		2,976.00	800.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	55.00	0	
Total:		1,606.00	520.00	