



Case Details

Case Reference Number : TAX/11/18/2018

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-4424-ID

Accident Date and Time : 03/11/2018 06:35 PM

Vehicle Registration Number : SHB5516R

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 12

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace 1CEK
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace 1NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace 1NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace 1NEC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace 1NEC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace 1NEC
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give XSUC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace 1CEK
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace 1NEC
									Total Spare Part Cost	2,395.41			
									Lump Sum Discount (%)	0.00	Surveyor Total	906.44	
									Final Spare Part Cost	2,395.41	Lump Sum Dis (%)	0	
											Final Sur Total	906.44	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give
Total Spare Part Cost									2,395.41				
Lump Sum Discount (%)									0.00				
Final Spare Part Cost									2,395.41				
											Surveyor Total	906.44	
											Lump Sum Dis (%)	0	
											Final Sur Total	906.44	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY FILLER RR BUMPER LH	180.00	0	CHECK
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	-----------	-------------------------	-------------------------	---------

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
2	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
3	TO REPLACE SUNDRY PARTS	100.00	0	NN
4	TO WASH AND VACUUM	60.00	0	NN
Total:		360.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,395.41	906.44
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	360.00	20.00
Overall Total	3,651.41	1,326.44
Lump Sum Repair Option		☐
Lump Sum Total	0.00	1,326.44
Surveyor Approved Amount		1,326.44
No of Repair Days*	3	2
Remarks		PART BY PART REPAIR. 2 DAYS. CHECK ITEMS PHOTOS. BEFORE PAINT PHOTOS.
Surveyor Name		Naz
Signature		
Survey Date	07/11/2018	Save Clear

NAZ LKK
 7/11/18
 PIP
 2 DAYS
 - CHECK ITEM PHOTOS
 - BEFORE PAINT PHOTOS.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: