

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5793B**AAD1811-114***Not Authorized
L1 Sup & 82006*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5793B

VF1ABL15AUC280912

RENAULT

LATITUDE

14.11.2018

III

PART		LIST	
1	1 BUMPER COVER REAR	\$ Bu	1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ Pd 10.1	768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ Dis	113.47 ✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$ Su	135.97 X
5	1 BUMEP R RETAINER RH REAR	\$ Su	44.99 X
6	1 BUMPER REFLECTOR RH	\$ Su	43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$ Su	135.97 X
8	1 BUMEP R RETAINER LH REAR	\$ Su	44.99 X
9	1 BUMPER REFLECTOR LH	\$ CM	43.61 ✓
10	1 BUMPER BEAM REAR	\$ Bz	777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ Bz	225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$ Dis	225.95 ✓
13	1 BOOT REAR	\$ Bu	2,872.68 ✓
14	1 BOOT FINISHER	\$ Su	470.06 X
15	1 BOOT WHEATERSTRIP	\$ Cu	323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$ Su	493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$ Su	493.35 X
18	1 BOOT BADGE 'RENAULT'	\$ Ru	225.36 ✓
19	1 BOOT BADGE	\$ Ru	225.36 ✓
20	1 BOOT STRUT LH	\$ Su	276.08 } 276.08 }
21	1 BOOT STRUT RH	\$ Su	276.08 }
22	1 BOOT HINGE LH	\$ R	367.84 }
23	1 BOOT HINGE RH	\$ R	367.84 }
24	1 BOOT INNER TRIM	\$ Su	586.45 }
25	1 BOOT SWITCH	\$ Su	168.13 }
26	1 BOOT LOCK	\$ R	202.67 }
27	1 BOOT LOCK CATCH	\$ R	74.40 }
28	2 LICENCE PLATE LAMP	\$ Su	50.52 }
29	2 BOOT RUBBER PLUG	\$ Su	221.81 }

Trans-cab Auto Services Pte Ltd

AAD1811-114

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5793B

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	
31	1 WHEELARCH REAR LH	\$	Sh	543.47	
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sh	671.45	
33	1 FENDER PANEL REAR RH	\$	R	3,299.13	
34	1 WHEELARCH REAR RH	\$	Sh	543.47	
35	1 TAILLAMP RH	\$	Sh	552.55	
36	1 TAILLAMP PANEL RH	\$	R	986.70	
37	1 TAILLAMP LH	\$	Sh	552.55	
38	1 TAILLAMP PANEL LH	\$	R	986.70	
39	1 OUTER PANEL REAR (End Panel)	\$	B	1,471.77	✓
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	ms dis	404.56	✓
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
42	1 SPARE WHEEL PANEL TRIM	\$	Sh	612.21	X
43	1 EXHAUST REAR	\$	R	7,489.05	X
44	1 EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	35,197.49
10%	\$	3,519.75
	\$	31,677.74

Specical Nett

1	1SET PARKING AID	\$	Shon	700.00	boorn
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sh	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X

Trans-cab Auto Services Pte Ltd**AAD1811-114**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5793B

18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00	} X
19	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00	
20	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00	
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00	
22	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i> 385.00	}
25	1 SPARE TYRE	\$	<i>sn</i> 330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 33,902.76****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>6601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>6001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>602</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 <i>601</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1811-114**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5793B

To supply and re-do rear luggage floor panel insulation padding.	\$	<i>un</i> 380.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>↪</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>↪</i> 220.00	<i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00	<i>X</i>

TOTAL \$ 12,540.00**Over All Total \$ 46,442.76****(LUMP SUM)****Repair Days***20 DAYS*
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: