

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Nov-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1389 G

1 pc	Emblem I30	X	\$	27.80
1 pc	Emblem CRDI	X	\$	29.40
1 pc	Emblem Hyundai	X	\$	29.40
1 pc	Rear bumper	X <i>rep</i>	\$	811.11
1 pc	Rear bumper sponge	X	\$	79.20
1 pc	Rear bumper reinforcement	X	\$	815.64
1 pc	Rear bumper reinforcement centre	X	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket	X	\$	104.40

KK Auto Consultants
the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during repair
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed
 is subject to final approval from Insurance Company

Less 20%

S/NETT

1 set	Rear bumper clips	X	\$	48.00
1 set	Reverse sensor	X	\$	280.00
1 set	Tailgate stickers	X	\$	100.00
	<i>Rear Bumper top protector</i>			
	Sundry		\$	50.00 X
	To dismantle and replace reverse sensor and test system		\$	80.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, tailgate lower garnish, etc		\$	850.00 100
	To putty and spray painting on the rear bumper, tailgate lower garnish, end panel		\$	700.00 180
	To apply rustproofing on the repaired and replaced panels		\$	120.00 X
Total			\$	3,988.92

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvi 10/11/18
15/11/18 1005hrs
2 hrs
PIP
After Rear photo