

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7749Y**AAD1811-117***Not Notified*
11 Sep & 4450h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7749Y

KL1LA69RJBB097133

CHEVROLET

EPICA 2.0

14.11.2018

AIG

PART			LIST	
1	1	Rear Bumper	\$	<i>Bu</i> 1,202.00 <i>—</i>
2	1	Rear Bumper Beam	\$	<i>Bu</i> 239.94 <i>—</i>
3	1	Rear Bumper Centre Absorber	\$	<i>CM</i> 260.00 <i>—</i>
4	1	Rear Bumper Side Retainer RH	\$	<i>SL</i> 68.76 <i>X</i>
5	1	Rear Bumper Side Retainer LH	\$	<i>SL</i> 68.76 <i>X</i>
6	1	Rear Bumper Reflectors RH	\$	<i>Bu</i> 119.74 <i>—</i>
7	1	Rear Bumper Reflectors LH	\$	<i>Bu</i> 119.74 <i>—</i>
8	1	Rear Bumper Tow Hook Cover	\$	<i>SL</i> 93.00 <i>X</i>
9	1	Rear End Panel Outer	\$	<i>Bu</i> 623.76 <i>—</i>
10	1	Rear End Panel Inner Trim	\$	<i>SL</i> 263.84 <i>X</i>
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00 <i>X</i>
12	1	Rear Luggage Floor Panel Insulator	\$	<i>SL</i> 63.50 <i>X</i>
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>SL</i> 378.00 <i>X</i>
14	1	Bootlid	\$	<i>Bu</i> 973.00 <i>—</i>
15	1	Bootlid inner trim board	\$	<i>SL</i> 400.00 <i>X</i>
16	1	Bootlid Weatherstrip	\$	<i>CM</i> 344.28 <i>508m 172.145m</i>
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56 <i>X</i>
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>SL</i> 120.62 <i>—</i>
19	1	Bootlid Logo	\$	<i>SL</i> 138.84 <i>—</i>
20	1	Bootlid 'EPICA LT' Badge	\$	<i>SL</i> 119.84 <i>—</i>
21	1	Bootlid Reflector Centre	\$	<i>SL</i> 217.97 <i>X</i>
22	1	Bootlid Reflector RH	\$	<i>SL</i> 128.40 <i>X</i>
23	1	Bootlid Reflector LH	\$	<i>SL</i> 128.40 <i>X</i>
24	1	Rear Tail Lamp RH	\$	<i>SL</i> 479.30 <i>X</i>
25	1	Rear Tail Lamp LH	\$	<i>CM</i> 479.30 <i>—</i>
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00 <i>X</i>
27	1	Rear Fender RH	\$	<i>R</i> 1,145.00 <i>X</i>
28	1	Rear Fender Inner Trim RH	\$	<i>SL</i> 418.44 <i>X</i>
29	1	Rear Fender LH	\$	<i>R</i> 1,145.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1811-117**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7749Y

30	1	Rear Fender Inner Trim LH	\$	<i>Pin</i>	418.44	X
----	---	---------------------------	----	------------	--------	---

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Specical Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i>	40.00	X
2	1Set	Rear Bumper Parking Sensor	\$	<i>Pin</i>	300.00	X
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i>	44.00	✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i>	30.00	} X
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i>	30.00	
6	1	Rear Exhaust Mounting	\$	<i>Pin</i>	300.00	
7	2	Rear Windscreen Sealant	\$	<i>Pin</i>	80.00	
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	
9	1	Spare Tyre	\$	<i>Pin</i>	180.00	
10	1	Spare Wheel Rim	\$	<i>Pin</i>	126.74	
11	1	Rear boot advertisement sticker	\$	<i>nn</i>	300.00	
12	1	Rear bumper advertisement sticker	\$	<i>nn</i>	300.00	

TOTAL	\$	1,830.74
--------------	-----------	-----------------

TOTAL PARTS	\$	13,267.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	<i>Good</i>
----	----------	-------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>2ok</i>
----	--------	------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>Good</i>
----	--------	-------------

Putty And Spray Painting Of The Affected Portion.

\$	3,000.00	<i>Good</i>
----	----------	-------------

To reinstall rear bumper parking sensor.

\$	170.00	<i>Good</i>
----	--------	-------------

Trans-cab Auto Services Pte Ltd**AAD1811-117**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7749Y

To transfer of end panel fittings and conduct
water seepage test.

\$ 170.00 *691*

To transfer of boot fittings and conduct water
seepage test.

\$ 170.00 *691*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 *X*

\$ 7,950.00

TOTAL \$ 21,217.43

Repair Days (LUMP SUM)***10 DAYS******5 days***

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: