

INS. CASE OWNER:

CC 3 / CT 1 180

LKK:

IDAC:

## ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(\$ / Assessed)

BOLA S/N No.:

10

Repair Cost:

S\$

4,159.84

Loss of Rental (LOR):

S\$

622.74

(6 days)

103.79

Loss of Use (LOU):

S\$

-

(\$ x days)

Loss of Income (LOI):

S\$

240

(\$ 40 x 6 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

2.77

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

5,024.58

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

5,024.58

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP VIDEO

SHOWED OI TURNING

FROM S/RW/STEP L.

G21119





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC3/CTI18020770/K1ja3

Date: 19/11/2018

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHB 8358K**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/11/2018 at the premises of M/s Premier Automotive Services Pte Ltd - Changi and have the following to report:-

Workshop Estimate Amount	: S\$	<u>5,257.78</u>
Revised Estimate Amount	: S\$	<u>3,887.70</u>
"Check" Items Amount	: S\$	<u>-</u>
Total (Including Check Items)	: S\$	<u>3,887.70</u>
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

**Description of Damage:**

The vehicle sustained damages at the  
N/S Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

[> Back to OneMotoring](#)

## Enquire Transfer Fee

### Vehicle Details

Vehicle No. :	SHB8358K
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1 :	Air-Con (Taxi)
Vehicle Scheme :	Taxi (Company)
Vehicle Make :	HYUNDAI
Vehicle Model :	I30 GDH 1.6 TCI 5DR DCT
Chassis No. :	TMAD281UVHJ121480
Propellant :	Diesel
Engine No. :	D4FBGZ105467
Engine Capacity :	1582 cc
Maximum Power Output :	100.0 kW ( 134 bhp )
Maximum Laden Weight :	1940 kg
Unladen Weight :	1496 kg
Year Of Manufacture :	2016
Original Registration Date :	28 Sep 2016
Lifespan Expiry Date :	27 Sep 2024
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid :	\$42,672.00
COE Expiry Date :	27 Sep 2024
Road Tax Expiry Date :	27 Mar 2019
PARF Eligibility Expiry Date :	27 Sep 2024
Inspection Due Date :	27 Mar 2019
Intended Transfer Date :	18 Jan 2019
CO2 Emission :	127.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$7,500.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 27 Mar 2019. You may renew the road tax from 28 Dec 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 27 Mar 2019, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable (From 28 Mar 2019 to 27 Sep 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	2,635.00	-	2,635.00
<b>Total Amount Payable :</b>			<b>2,660.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H  
Owner ID Type: Company  
Owner Name: PREMIER TAXIS PTE. LTD.  
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443  
Mailing Address: -  
Birth Date: -

**Vehicle Particulars**

Vehicle No.: SHB8358K  
Previous Vehicle No.: -  
Effective Date of Ownership: 28 Sep 2016  
Original Regn Date: 28 Sep 2016  
Registration Date: 28 Sep 2016  
Year of Manufacture: 2016  
Vehicle Type: Public Transport Taxi (Motor Car)  
Vehicle Scheme: Taxi (Company)  
Vehicle Attachment 1: Air-Con (Taxi)  
Vehicle Attachment 2: -  
Vehicle Attachment 3: -  
Vehicle Make: HYUNDAI  
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT  
Primary Colour: Silver  
Secondary Colour: -  
Passenger Capacity: 4  
Chassis No.: TMAD281UVHJ121480  
Engine No.: D4FBGZ105467  
Engine Capacity/Power Rating: 1582 cc / -  
Maximum Power Output: 100.0 kW (134 bhp)  
Propellant: Diesel  
Max Unladen Weight: 1496 kg  
Maximum Laden Weight: 1940 kg  
Open Market Value: \$20,131.00  
PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 27 Sep 2024  
Minimum PARF Benefit: \$7,610.00  
No. of Transfers: 0  
IU Label No.: 1050681030  
COE No.: 2016092801004223Z  
COE Expiry Date: 27 Sep 2024  
COE Category: A - Car (up to 1600cc & 97kW (130bhp))  
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))  
Quota Premium (QP) / Prevailing Quota Premium: - / \$53,339.00  
PQP Paid: \$42,672.00  
QP (Regn Cat): -  
OPC Cash Rebate Eligibility: No

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

15-Nov-18

## ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHB 8358 K

1 pc	Rear n/s fender	<i>bulb</i>	\$	1,525.73
1 pc	Rear n/s fender inner shield	<i>tan</i>	\$	205.29
1 pc	Rear bumper n/s side bracket	<i>on</i>	\$	32.50
1 pc	Rear bumper	<i>cra</i>	\$	811.11
1 pc	Rear bumper n/s reflector	<i>X</i>	\$	107.50
1 pc	fuel cap	<i>X repair</i>	\$	34.10
1 pc	rim	<i>X repair</i>	\$	246.00
			\$	2,962.23
			\$	592.45
			\$	2,369.78

LKK Auto  
the Repair  
• To resurvey  
• To display  
• Parts prices  
• Third party  
• No illegal modification  
• Supplementary  
is subject to final approval

Acknowledged by Repairer  
Signature:  
Date:

Less 20%

### S/NETT

1 set	Rear bumper clips	<i>ac</i>	\$	48.00
1 set	Bootlid stickers	<i>ac</i>	\$	100.00
1 set	n/s door sticker	<i>ac</i>	\$	100.00
1 pc	Rear n/s fender sticker	<i>ac</i>	\$	60.00
Sundry <i>nc</i>			\$	<del>50.00</del> 20
To dismantle / refit reverse sensor to new bumper and reset to the same			\$	<del>120.00</del> 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			\$	<del>180.00</del> 50
To dismantle and fit the rear n/s fender quarter glass to facilitate repair on the rear n/s fender			\$	<del>80.00</del> 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the same etc			\$	<del>1,000.00</del> 600
To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, tailgate lower garnish, n/s rocker panel			\$	<del>1,000.00</del> 720
To apply rustproofing on the repaired and replaced panels.			\$	<del>150.00</del> 50
			\$	5,257.78

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

17/12/18  
Total P11 \$3887.70/51/2

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

15-Nov-18

## ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHB 8358 K

1 pc	Rear n/s fender	\$	1,525.73
1 pc	Rear n/s fender inner shield	\$	205.29
1 pc	Rear bumper n/s side bracket	\$	32.50
1 pc	Rear bumper	\$	811.11
1 pc	Rear bumper n/s reflector	\$	107.50
1 pc	fuel cap	\$	34.10
1 pc	rim	\$	246.00

LKK Auto

the Repair

- To reserve
- To display
- Parts price
- Third party
- No illegal
- Supplementary

Acknowledged by Repairer

Less 20%

Signature:

Date:

\$ 2,962.23

\$ 592.45

\$ 2,369.78

### S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Bootlid stickers	\$	100.00
1 set	n/s door sticker	\$	100.00
1 pc	Rear n/s fender sticker	\$	60.00

Sundry

To dismantle / refit reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To dismantle and fit the rear n/s fender quarter glass to facilitate repair on the rear n/s fender

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the same etc

To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, tailgate lower garnish, n/s rocker panel

To apply rustproofing on the repaired and replaced panels.

\$ 50.00 20

\$ 120.00 30

\$ 180.00 50

\$ 80.00 50

\$ 1,000.00 600

\$ 1,000.00 720

\$ 150.00 50

\$ 5,257.78

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

## Mei Kwan (LKKAUTO)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Thursday, 22 November, 2018 3:11 PM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** Elaine Cheong  
**Subject:** RE: Direct Settlement - Accident Involving SJT5748U (OI : CTI - SNM18D05395C02) and SHB8358K (TP : LKK REF - CC3/CTI18020770/K1ja3) on 14/11/2018  
**Attachments:** leeSZ\_SNM18D05395C01-SJT5748U-LKKDirectSettlementAccidentLtr\_CLCR95.022.pdf; MSAT18147956-SJT5748U.pdf  
**Categories:** HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

Lucas Lee  
Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6181  
Fax (65) 6222 7175/6224 7478  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 19 November, 2018 7:25 PM  
**To:** Claims Dept of CTI  
**Cc:** Elaine Cheong; Lucas Lee; Joy Irene (LKKAUTO); Asher Sng (LKKAUTO); Admin A  
**Subject:** Direct Settlement - Accident Involving SJT5748U (OI : CTI - TBA) and SHB8358K (TP : LKK REF - CC3/CTI18020770/K1ja3) on 14/11/2018

**'WITHOUT PREJUDICE'**



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079609  
Tel: 6389 6111 Fax: 6222 1033  
Website: www.sg.cntaiping.com  
Co. Reg. No. 200206384E

Our Reference: **SNM18D05395/C01/8**

Date : **22 NOVEMBER 2018**

via Ordinary & Registered Mail

**HARRIS CONSTRUCTION PTE LTD  
BLK 808 FRENCH ROAD  
#03-02 KITCHENER COMPLEX  
SINGAPORE 200808**

Dear Sir / Madam

**ACCIDENT INVOLVING SJT5748U AND SHB8358K ON 14 NOVEMBER 2018  
ALONG EUNOS ROAD 8**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHB8358K** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,  
Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd  
Attn : JOY  
Ref : CC3/CTI18020770/K1JA3  
Contact No : 68412409  
via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0420A) - INXPRESS INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

**Gary Shi**

---

**From:** Gary Shi  
**Sent:** Wednesday, 20 March, 2019 3:10 PM  
**To:** 'Joy Irene (LKKAUTO)'  
**Cc:** AccReport; CS A Team; Admin A  
**Subject:** RE: LOD / Accident involving SHB8358K & SJT5748U on 14.11.18 (China Taiping case)  
**Attachments:** SHB8358K - DV.pdf

WITHOUT PREJUDICE

Dear Joy,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHB8358K, our client agreed to direct settle the above claims at \$5024.58

We enclosed hereby Discharge voucher & ATA for your kind attention, original copies will pass to Mr Calvin.

Kindly let us have your settlement sum of S\$5024.58 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi  
Senior Executive, Claims  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
**Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511**  
Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

---

**From:** Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]  
**Sent:** Wednesday, 20 March, 2019 10:24 AM  
**To:** Gary Shi  
**Cc:** AccReport; CS A Team; Admin A  
**Subject:** RE: LOD / Accident involving SHB8358K & SJT5748U on 14.11.18 (China Taiping case)

WITHOUT PREJUDICE

Dear Gary,

DV and ATA attached for your necessary action.

Thank you.

**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H  
Owner ID Type: Company  
Owner Name: PREMIER TAXIS PTE. LTD.  
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443  
Mailing Address: -  
Birth Date: -

**Vehicle Particulars**

Vehicle No.: SHB8358K  
Previous Vehicle No.: -  
Effective Date of Ownership: 28 Sep 2016  
Original Regn Date: 28 Sep 2016  
Registration Date: 28 Sep 2016  
Year of Manufacture: 2016  
Vehicle Type: Public Transport Taxi (Motor Car)  
Vehicle Scheme: Taxi (Company)  
Vehicle Attachment 1: Air-Con (Taxi)  
Vehicle Attachment 2: -  
Vehicle Attachment 3: -  
Vehicle Make: HYUNDAI  
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT  
Primary Colour: Silver  
Secondary Colour: -  
Passenger Capacity: 4  
Chassis No.: TMAD281UVHJ121480  
Engine No.: D4FBGZ105467  
Engine Capacity/Power Rating: 1582 cc / -  
Maximum Power Output: 100.0 kW (134 bhp)  
Propellant: Diesel  
Max Unladen Weight: 1496 kg  
Maximum Laden Weight: 1940 kg  
Open Market Value: \$20,131.00  
PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 27 Sep 2024  
Minimum PARF Benefit: \$7,610.00  
No. of Transfers: 0  
IU Label No.: 1050681030  
COE No.: 2016092801004223Z  
COE Expiry Date: 27 Sep 2024  
COE Category: A - Car (up to 1600cc & 97kW (130bhp))  
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))  
Quota Premium (QP) / Prevailing Quota Premium: - / \$53,339.00  
PQP Paid: \$42,672.00  
QP (Regn Cat): -  
OPC Cash Rebate Eligibility: No

### Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number** : 5095103893

**Cover** : Third Party

1. Index mark and Registration Number of Vehicle  
Chassis Number

: SHB8358K  
: TMAD281UVHJ121480

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 31 Jan 2019

5. Persons or Classes of Persons entitled to drive\*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use\*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

**This Policy does not cover**

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

# IGOMOTO MOTORS PTE. LTD.

Alexandra Service Centre 253 Alexandra Road Singapore 159936 Tel : 64735588 Fax : 64721633

## Vehicle Discharge Form

Vehicle Number : SHB 83581C

Job No: 2018043579

Date in :	<u>15.11.18</u>	Date out :	<u>23.11.18</u>
Time in :	<u>15:50</u>	Time out :	<u>16:30 hrs</u>
Mileage in:	<u>278359</u>	Mileage out:	<u>278361</u>
Tow In Date & Time:		Call Date & Time:	<u>23.11.18</u> <u>14.04</u>
<div>Service <input type="checkbox"/> Mechanical Repair <input type="checkbox"/> Accident Repair <input checked="" type="checkbox"/></div>			
Remarks : <u>Accident - 3rd Party</u>			
Replacement Vehicle Yes / No			

Signature of Driver

Driver's Name : Chen

I/C No.:

Contact No. 93387412

Signature of Customer Service Officer

CSO Name: Edde Ang



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18020770/K1ja3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 04-04-2019



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 5748U	Veh. Inspected	SHB 8358K
Policy No.	DMPCSN3066471801	Coverage (\$)	0.00
Claim No.	SNM18D05395C02	Excess (\$)	0.00
Assign From		Assign Date	15/11/2018

## 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	TMAD281UVHJ121480	Colour	SILVER
Odometer	278358	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	7 mm
L/H Front Tyre	195/65 R15	MAXXIS	7 mm
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	14/11/2018	Inspection Date	15/11/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8358K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR N/S FENDER	BUCKLED	1,525.73	1,525.73
1	REAR N/S FENDER INNER SHIELD	TORN	205.29	205.29
1	REAR BUMPER N/S SIDE BRACKET	CRACKED	32.50	32.50
1	REAR BUMPER	CRACKED	811.11	811.11
1	REAR BUMPER N/S REFLECTOR	SERVICEABLE	107.50	-
1	FUEL CAP	TO REPAIR SEE LABOUR	34.10	-
1	RIM	TO REPAIR SEE LABOUR	246.00	-
	LESS 20% DISCOUNT		-592.45	-514.93
			2,369.78	2,059.70
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			358.00	328.00
<b>LABOUR</b>				
	TO DISMANTLE/REFIT REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO DISMANTLE AND FIT THE REAR N/S FENDER QUARTER GLASS TO FACILITATE REPAIR ON THE REAR N/S FENDER.		80.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE THE REAR N/S FENDER INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME ETC. INCLUSIVE OF THE REPAIR OF FUEL CAP AND RIM.		1,000.00	600.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR N/S FENDER, REAR N/S DOOR, TAILGATE LOWER GARNISH, N/S ROCKER PANEL.		1,000.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
			2,530.00	1,500.00
GRAND TOTAL			5,257.78	3,887.70
RECOMMENDED COST OF REPAIRS				3,887.70

Report Ref No. CC3/CT118020770/K1ja3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.