	15/5/2010	Gerald	CC 4/ 4 180 7	0773,-	TI fa302 LKK	
	INS, CASE OWNER	VRCRID			PohKin .	7.1
	Surveyor.	Tauflich	DOI: ASSIGNMI		Date / Tiess:	2/11/18
	n				Registered in Merimen:	
	Pre-assign / CCU /	7.7	286UR		10/10/12	1000/02/19
	Insured Vehicle No	- 1	0 10 000	Claim No.	: 8 18 18	Acodonica
A A	Name of Insured	: New Ar	HOW K WILL	Policy No.		
K-M	Insured Tel No.		HP: CENTET	Make / Model	4	
100			1 / 11/25/		Dan Ac	/
	Excess Sec II :SS		D.O.A: (411/8	Place of Accide	nt: Mill INC	7
	Is driver the owner?	(YES/NO)	Nature of Accident :		\sim	
	If NO, Driver Nam Driver Tel N	[1] [1] [1] [1] [1] [1] [1] [1] [1] [1]	(V/L: (YE\$ / NO)	OI GIA REPOR Insured Liability	T:/YES/NO; TP GIA REP y: % Final?	0
	8051106					
1	INSRS:	INSRS		INSRS:	INS	SRS:
H 7		Uhi WSP:		WSP:	ws	P;
H H	Tel: Liability:	Tel: Liabilit	· H H	Tel: Liability:	Tel	; bility ;
(F)	RMKS:	RMKS.	150 -4/1	RMKS:	1/0 -0/1	iks:
	Date/ Time			#95.500A		
	- M.,	GOZ 110 Cn - CUL PATA	10003886 Kmaln : 001	4. Wy how	STAGE	DATE / PIC
	NIN	CASMINO X	An Sea O. Bassalett . Little	1 15-11-0	Non-Reporting ltr (1st):	DATE/TIC
	CPL	01389 6KVV	/		Non-Reporting ltr (2nd);	
	011	email habity Char	/		Non-Reporting ltr (Final): Notification ltr (if non-pickup):	
			/		Call OI:	
		perdly trally			After call itr to OI:	
					Documentation Check List:	Handler Typist
550000		pendiny LDD .	/		Notification ltr (if non-pickup) After call ltr to OI:	
		Alle pass for type	mendate report		Authorisation To Act:	
			1111		Release Voucher;	
					Final Repair Bill:	V
					Car Rental Invoice:	V
					Towing Invoice	
_					LTA / GIA : Medical Bill:	
					PIR:	
					Mandate/Reject Instruction:	
					LOD	V
		better paint photo u			Payment Breakdown Form:	
PRELIM	HNARY ADVICE	Date/Time!	Sent By:		Post-Repair Photos:	
FINALE	ZATION	Date/Time:	Confirm with:		Others: Confirm by:	
Repair Co		S\$ 4,413.00 (5	days) Reduction: 36.91	%	Email	Call
-	SETTLEMENT	Date/Time: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Confirm with Jumbah		Email Call	- Can
Final Lial			Assessed) BOLA S/N No.: 27		If NO or B 28, Ass. Lia:	
Repair Co	ost: (w/457)	S\$ 4,711.11				w collidar
	ental (LOR):	S\$ 74400 (5	days) × 4140 00 + 7%) st	Literal 10 in	~
1-1-1-1	Ise (LOU):	S\$ - (\$ x S\$ - (\$ x	days)		milei.	GIVIS .
21.22.22.22.22.22.22.22.22.22.22.22.22.2	ncome (LOI):		days) OR + LOI [Tick only one]		10/11	1.9
GIA/LTA	The second secon	S\$ 7.00	Tree only one		1214	TUIL
Medical:		SS -			1) Claim status: Normal/Reje	ct/Private Settle
Disburser	The state of the s	S\$ -	(e.g. Tow/ Independent)		2) Report Format:	
Legal Co.	st	S\$ -	Clabal Para PP		3) Survey fee: 4450 U	0
Total:	PAYMENT	SS 5,472.41 Date/Time:	Global Sum SS: Confirm with:		Email Call	
Payce 1:	ALMENI	S\$ 5,472.91	Name 1: It acid (agito	Asia Pat	Email Call	
-	(Strike if N.A.)	S\$ >,4/12.41	Name 1: 17179(1) [09170]	pesta fati	TIC ITE VIEW	
	(Strike if N.A.)	\$\$	Name 3:			
ACCORDINATE OF RE-					The second secon	



Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

1 1 11 11 11

18/18/18/VC00/021119

Our ref:

CC4/LPC18020773/T1fa3

Date: 27.11.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SDZ 110G

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.11.2018 at the premises of M/s Hitachi Capital Asia Pacific Pte. Ltd. and have the following to report:-

Workshop Estimate Amount	: S\$	6,995.75
Revised Estimate Amount	: S\$	4,011.75
"Check" Items Amount	: S\$	1,242.00
Total (Including Check Items)	: S\$	5,253.75
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the

Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

5.0 days

Yours faithfully,

MOHD. TAUFIKH

Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	24661
Vehicle Details	
Vehicle No.:	SDZ110G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	2AZ4A49623
Chassis No.:	ACR507132874
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$35,926.00
Original Registration Date:	04 Nov 2016
First Registration Date:	04 Nov 2016
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$42,297.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Nov 2026
PARF Rebate Amount:	\$31,722.00
Intended COE Rebate Details	
COE Expiry Date:	03 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,410.00
COE Rebate Amount:	\$44,947.00
Total Rebate Amount:	\$76,669.00

The information contained herein is correct as at 15 Nov 2018

Hitachi Capital Asia Pacific Pte. Ltd. Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705

Tel: 64663022 Fax: 68966591

Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

Lamage			OU	OTE NO	*			
Lonpac					: 14/	11/2018@0930	hrs	
			VRI			Z110G		
ATTN: MOTOR CLAIMS DEPT			МО	DEL	: Toy	ota Estima		
			TP	VRN	: GT:	3864R		
		Qty		S\$ Unit		S\$ Amt	5	S\$ Labor
PARTS REPLACEMENT								
1. Body Repair								
1 Rear Bumper		1	\$	582.00	\$	582.00 de		
2 Rear Bumper Clips		10	\$	5.50	\$	55.00 A	1	
3 Rear Bumper Outer Bracket LH/RH		2	\$	60.00	\$	120.00 X		
4 Rear Bumper Inner Bracket LH/RH		2	\$	60.00	\$	120.00 🔀	1	
5 Rear Bumper Reflector LH/RH		2	\$	60.00	\$	120.00 ★	6	LI)
6 Rear Bumper Tow Cover		2	\$	38.00	\$	76.00⊀	1	
7 End Panel		1	\$	660.00	\$	660.00 RY	0	
8 Rear End Panel Upper Garnish Top		1	\$	271.00	\$	271.00 %	wn	
9 Rear End Panel Upper Garnish Low		1	\$	255.00	\$	255.00 🗓	NN	Ž.
10 Tailgate		1	\$	1,700.00	\$	1,700.00 6+		
11 Tailgate Auto Lock		1	\$	475.00	\$	475.00 7	bt-	
12 Tailgate Estima Logo		1	\$	47.00	\$	47.00 mg	/	8
13 Tailgate Toyota Logo		1	\$	75.00	\$	75 00 al	-	
14 Tailgate Wheatherstrip		1	\$	355.00	\$	355.00 🕅	NN	(•
17 Rear Windscreen Moulding		1	\$	90.00	\$	90.00	/	ë
15 Rear Bumper Sensor	s/nett	1	\$	200.00	\$	200.00		
16 Sealant	s/nett	1	\$	45.00	\$	45.00	4/	
			23		557	68		3024
Discount 25%					\$	(1,250.25)		2268
							SN	245
			TC	DTAL	\$	3,995.75		
2. Labor Charges								750.
1 Panel, beat, cut, weld re-align and	replace da	mage	d pa	arts of REAR	porti	on	\$	1,000.00
2 Spray painting on REAR portion of							\$	1,000.0075
3 Check wiring, re-align taillamps and				ction			\$	80.0030
4 Remove & reinstall 2 pieces bumpe	er parking	sensor	S				\$	120.0030
5 Cavity treatment on new parts							\$	80.00 40.
6 Remove & reinstall rear reverse ca							\$	120.00 30
7 Remove & reinstall rear tailgate wir		Nest-					\$	180.00/20
8 Transfer tailgate lock & mechanism	i to new ta	iigate					\$	150.00 6Q 120.00 3Q
9 Conduct water seepage test 10 Remove & reinstall rear trim compa	artment to	facilita	te c	cutting and re	nairir	na work	\$	150.00 60
To remove a remarantear timi compa	artinerit to	iaomia		atting and re	Pairii	ig work	9	
			Su	ıb Total	:		\$	3,000.00

Grand Total : \$ 6,995.75

Add 7% GST : \$ 489.70 Nett Total : \$ 7,485.45

No. of repair days: 7

100

CUSTOMER SIGNATURE

HITACHI CAPTIAL ASIA PACIFIC PTE LTD (MANAGER)

1900 - 2268 SW - 245 Wen - 1900 \$ 44/5

Taufin 97495749

17/14/18 C 1130

Sur e/Mantourn

5 days

Resury before point

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAuto)

From:

GERALD POH WEE BIN < geraldpoh@lonpac.com>

Sent:

Monday, 26 November, 2018 2:38 PM

To:

Mei Kwan (LKKAuto)

Cc:

MT Claim SG

Subject:

RE: SDZ110G TP CLAIM GT3864R (Lonpac) *** LKK REF: CC4/LPC18020773/fa3

Attachments:

26112018143550.pdf

Categories:

HMK

Dear Mei Kwan,

Attached copy of insured 's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Monday, 26 November, 2018 1:36 PM
To: GERALD POH WEE BIN; Poh Kin (LKKAuto)
Cc: MT_Claim_SG; assignments; Admin A; CS A Team

Subject: RE: SDZ110G TP CLAIM GT3864R (Lonpac) *** LKK REF: CC4/LPC18020773/fa3

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

LPC ref: 18/18/18/VC00/021119 LKK REF: CC4/LPC18020773/fa3

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Poh Kin and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Please refer to above subject matter.

Attached GIA report and Estimate for your arrangement.

Kindly Assign Survey, Vehicle Is Not IN No.8 Fourth lok yang road S/629705

Please call to arrange

Regards

Ng Jiong How Motor Claims Advisor Auto Servicing Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd. Jun Taiyo Service Centre (Automobile Leasing & Workshop) 8 Fourth Lok Yang Road Singapore 629705

t: 6833 6282

e: jionghow.ng@hcspl.com.sg w: www.hitachi-capital.com.sg

> HITACHI Inspire the Next

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED. This email is intended solely for the attention and use of the name addressee(s).

If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.

Nivitha (LKK Auto)

From:

GERALD POH WEE BIN < geraldpoh@lonpac.com>

Sent:

Thursday, 15 November 2018 3:16 PM

To:

JiongHow, Ng

Cc:

MT_Claim_SG; Admin-D (LKKAuto)

Subject:

RE: SDZ110G TP CLAIM GT3864R (Lonpac)

WITHOUT PREJUDICE

Our Ref

: 18/18/18/VC00/021119

Dear Jiong How,

Our insured has yet to lodge a report.

We shall appoint LKK Auto Consultants Pte Ltd for the survey.

Aside to LKK - Attn:Catherine, Kindlly proceed accordingly 15-11-2018 @ 3.785pm

Best Regards Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: JiongHow, Ng [mailto:jionghow.ng@hcspl.com.sg]

Sent: Thursday, 15 November, 2018 2:53 PM

To: assignments

Cc: Vonn, LM Siow; Jamilah, Binte MohdKassim; GERALD POH WEE BIN

Subject: SDZ110G TP CLAIM GT3864R (Lonpac)

Dear all.

Please refer to above subject matter.

Attached GIA report and Estimate for your arrangement.

Kindly Assign Survey, Vehicle Is Not IN No.8 Fourth lok yang road S/629705

Please call to arrange

Regards

Ng Jiong How Motor Claims Advisor Auto Servicing Total Vehicle Solutions Department Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

t: 6833 6282

. . / .

e: jionghow.ng@hcspl.com.sg w: www.hitachi-capital.com.sg

HITACHI Inspire the Next

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.

This email is intended solely for the attention and use of the name addressee(s).

If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.

Catherine Chong (LKK Auto)

From:

GERALD POH WEE BIN < geraldpoh@lonpac.com>

Sent:

Thursday, 15 November, 2018 3:16 PM

To:

JiongHow, Ng

Cc:

MT_Claim_SG; Admin-D (LKKAuto)

Subject:

RE: SDZ110G TP CLAIM GT3864R (Lonpac)

WITHOUT PREJUDICE

Our Ref

: 18/18/18/VC00/021119

Dear Jiong How,

Our insured has yet to lodge a report.

We shall appoint LKK Auto Consultants Pte Ltd for the survey.

Aside to LKK - Attn:Catherine, Kindlly proceed accordingly

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: JiongHow, Ng [mailto:jionghow.ng@hcspl.com.sg]

Sent: Thursday, 15 November, 2018 2:53 PM

To: assignments

Cc: Vonn, LM Siow; Jamilah, Binte MohdKassim; GERALD POH WEE BIN

Subject: SDZ110G TP CLAIM GT3864R (Lonpac)

Dear all,

Please refer to above subject matter.

Attached GIA report and Estimate for your arrangement.

Kindly Assign Survey, Vehicle Is Not IN No.8 Fourth lok yang road S/629705

Please call to arrange

Regards

Ng Jiong How Motor Claims Advisor Auto Servicing Total Vehicle Solutions Department Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

t: 6833 6282

e: jionghow.ng@hcspl.com.sg

w; www.hitachi-capital.com.sg

HITACHI Inspire the Next

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.

This email is intended solely for the attention and use of the name addressee(s).

If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.

From:

GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent:

Tuesday, 26 February 2019 8:34 AM

To:

Poh Kin (LKKAuto)

Cc: Subject: MT_Claim_SG RE: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GT

3864R (OI) AND SDZ 110G (TP) ON 14-11-2018; LKK ref : CC4/LPC18020773/T1fa3;

Lonpac ref: 18/18/18/VC00/021119 [External Confidential]

Lonpac External - Confidential

Dear Poh Kin

Kindly proceed as proposed


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]

Sent: Tuesday, 19 February, 2019 7:34 PM

To: GERALD POH WEE BIN Cc: MT Claim SG; Admin A

Subject: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GT 3864R (OI) AND SDZ 110G (TP)

ON 14-11-2018; LKK ref: CC4/LPC18020773/T1fa3; Lonpac ref: 18/18/18/VC00/021119

Importance: High

Without Prejudice

Our Ref:

CC4/LPC18020773/T1fa3

Your Ref:

18/18/18/VC00/021119

Dear Gerald,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GT 3864R (OI) AND SDZ 100G (TP) ALONG ANG MO KIO AVENUE 5 ON 14/11/2018

We refer to the above matter.

Liability: The accident occurred when our Insured Driver collided into rear of third party vehicle. Liability is down against our Insured.

Summary to offer to third party repairer, Hitachi Capital Asia Pacific Pte Ltd is as follows: -

From:

Poh Kin (LKKAuto)

Sent:

Tuesday, 26 February 2019 9:31 AM

To:

'Jamilah, Binte MohdKassim'

Cc:

Admin A

Subject:

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GT 3864R AND SDZ 110G ON

14.11.2018

Attachments:

DV SDZ 110G.pdf

Importance:

High

WITHOUT PREJUDICE SAVE AS TO COSTS

Our Ref:

CC4/LPC18020773/T1fa3

Your Ref:

SDZ 110G

Dear Jamilah,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GT 3864R AND SDZ 110G ON 14.11.2018

We refer to the above matter and your letter of demand dated 26st February 2019.

We hereby confirmed settlement as per your letter of demand:

1. Cost of Repair (4,413.00 +7%GST)	S\$ 4,721.91
2. Loss of Rental (\$140.00 x 5days)+7%gst	S\$ 749.00
3. GIA search fee	<u>\$\$</u> 2.00
15e #1701 St	S\$ 5,472.91

Please duly sign the DV attached and return with your Authorization to ACT to us (LKK) for payment processing.

We need Original copy DV.

Your prompt action is very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Poh Kin (LKKAuto)

Sent:

Tuesday, 19 February 2019 7:34 PM

To: Cc: GERALD POH WEE BIN MT_Claim_SG; Admin A

Subject:

SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GT 3864R (OI) AND SDZ 110G (TP) ON 14-11-2018; LKK ref : CC4/LPC18020773/T1fa3; Lonpac

ref: 18/18/18/VC00/021119

Attachments:

LKK Adjustment report.pdf; LKK Inspection report.pdf; LKK Resurvey photo.pdf; LKK

survey photo.pdf; TP LOD_SDZ 110G.pdf

Importance:

High

Without Prejudice

Our Ref:

CC4/LPC18020773/T1fa3

Your Ref:

18/18/18/VC00/021119

Dear Gerald,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GT 3864R (OI) AND SDZ 100G (TP) ALONG ANG MO KIO AVENUE 5 ON 14/11/2018

We refer to the above matter.

Liability: The accident occurred when our Insured Driver collided into rear of third party vehicle. Liability is down against our Insured.

Summary to offer to third party repairer, Hitachi Capital Asia Pacific Pte Ltd is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 7,485.45 (\$6,995.75 + 7%gst)	\$ 4,721.91 (\$4,413.00 + 7% gst)
2. Loss of Rental	\$ 749.00 (\$140.00 x 5 days)	\$ 749.00 (\$140.00 x 5 days)
3. GIA search fee	\$ 2.00	\$ 2.00
Total	\$ 8,236.45	\$ 5,472.91

^{**05} days recommendation for repair

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.

From:

Poh Kin (LKKAuto)

Sent:

Friday, 18 January 2019 10:57 AM

To:

'Jamilah, Binte MohdKassim'; Taufikh (LKKAuto)

Cc:

Subject:

RE: Finalisations for vehicle SDZ 110G; DOA: 14/11/2018

Importance:

High

'WITHOUT PREJUDICE' SAVE AS TO COSTS

Our Ref:

CC4/LPC18020773/T1fa3

Your Ref:

SDZ 110G

Dear Jamilah,

We refer to the above matter.

For COR, our surveyor had recommended amount at P/P \$4,413.00 (before GST) with 5 repair days.

Please note that: All finalisation is subject to our Principal insurer's approval.

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

We need original copy LOD.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Save the Earth Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From:

Poh Kin (LKKAuto)

Sent:

Wednesday, 28 November 2018 10:51 AM

To:

'JiongHow, Ng'; Mei Kwan (LKKAuto)

Cc:

Admin A

Subject:

RE: SDZ110G TP CLAIM GT3864R (Lonpac)

Importance:

High

WITHOUT PREJUDICE

Our Ref:

CC4/LPC18020773/T1fa3

Your Ref:

SDZ 110G

Dear Jiong How,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GT 3864R AND SDZ 110G ON 14/11/2018

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

0115	A O INIQUIDANICE	Affiliated to Federation Internation	Ref : CC4/LPC180207	
ONF.	PAC INSURANCE	BHD	Rei . CC4/Li C100201	70/1 Hadriz
00 E	BEACH ROAD 04/07 THE CONCO	URSESINGAPORE 199555	Date: 24-04-2019 Code: LPC2	
		Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.	GT 3864R	Veh. Inspected	SDZ 110G
	Policy No.	Z/18/VC00/102289	Coverage (\$)	0.00
	Claim No.	18/18/18/VC00/021119	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	15/11/2018
2.		Vehicle Part	iculars & Condition	
	Make & Model	TOYOTA ESTIMA	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	ACR507132874	Colour	WHITE
	Odometer	57015	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condi	tions of Tyres	
	1	Size	Make	Balance
	R/H Front Tyre	235/50 R18	DUNLOP	6 mm
	L/H Front Tyre	235/50 R18	DUNLOP	6 mm
	R/H Rear Tyre	235/50 R18	DUNLOP	6 mm
	L/H Rear Tyre	235/50 R18	DUNLOP	6 mm
4.			tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE R	EAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gener	ral Information	
	Accident Date	14/11/2018	Inspection Date	22/11/2018
	Survey held at	HITACHI CAPITAL (S) PTE LT	D	
		JUN TAIYO SERVICE CENTR NO. 8 FOURTH LOK YANG R SINGAPORE 629705	E OAD	
5a.			Remarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	ITHOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	IS. ED REPAIRS.
5b.			e Days of Repair	SERVICE SERVIC
100 (0.00)	TECTIMATED NOR	MAL PERIOD FOR REPAIR:	5 Working Day	'S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDZ 110G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	582.00	582.00
	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
	REAR BUMPER OUTER BRACKET LH/RH @\$60.00	NOT NECESSARY	120.00	- 5
	REAR BUMPER INNER BRACKET LH/RH @\$60.00	NOT NECESSARY	120.00	1-
	REAR BUMPER REFLECTOR LH/RH @\$60.00	NOT NECESSARY	120.00	72 5
	REAR BUMPER TOW COVER @\$38.00	NOT NECESSARY	76.00	94
	END PANEL	TO REPAIR SEE LABOUR	660.00	-
া	REAR END PANEL UPPER GARNISH TOP	NOT NECESSARY	271.00	52
-1	REAR END PANEL UPPER GARNISH LOWER	NOT NECESSARY	255.00	-
-1	TAILGATE	BENT	1,700.00	1,700.00
1	TAILGATE AUTO LOCK	BENT	475.00	475.00
	TAILGATE ESTIMA LOGO	NECESSARY	47.00	47.00
-	TAILGATE TOYOTA LOGO	NECESSARY	75.00	75.00
	TAILGATE WEATHERSTRIP	NOT NECESSARY	355.00	-
-	REAR WINDSCREEN MOULDING	NECESSARY	90.00	90.00
	LESS 25% DISCOUNT		-1,250.25	-756.00
		1	3,750.75	2,268.00
	SPECIAL NETT ITEMS			
	REAR BUMPER SENSOR (SN)	NOT WORKING	200.00	200.00
	SEALANT (SN)	NECESSARY	45.00	45.00
	Control Contro		245.00	245.00
	LABOUR			
	PANEL BEAT, CUT, WELD RE-ALIGN AND REPLACE DAMAGED PARTS OF REAR PORTION. INCLUSIVE OF THE REPAIR OF END PANEL.		1,000.00	750.00
	SPRAY PAINTING ON REAR PORTION OF AFFECTED AREA.		1,000.00	
	CHECK WIRING , RE-ALIGN TAILLAMPS AND ENSURE PROPER FUNCTION .		80.00	5,50,000
	REMOVE & REINSTALL 2 PIECES BUMPER PARKING SENSORS.		120.0	30.00

Report Ref No. CC4/LPC18020773/T1fa3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	CAVITY TREATMENT ON NEW PARTS.		80.00	40.00
	REMOVE & REINSTALL REAR REVERSE CAMERA.		120.00	30.00
	REMOVE & REINSTALL REAR TAILGATE WINDSCREEN.		180.00	120.00
	TRANSFER TAILGATE LOCK & MECHANISM TO NEW TAILGATE.		150.00	60.00
	CONDUCT WATER SEEPAGE TEST.		120.00	30.00
	REMOVE & REINSTALL REAR TRIM COMPARTMENT TO FACILITATE CUTTING AND REPAIRING WORK.		150.00	60.00
	The second secon		3,000.00	1,900.00
	GRAND TOTAL		6,995.75	4,413.00

RECOMMENDED COST OF REPAIRS	4,413.00
-----------------------------	----------

Report Ref No. CC4/LPC18020773/T1fa3n2

MOHAMAD TAUFIKH

pupin.

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.