

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: EQ	DATE	: 14/11/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT:			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLS5574K		
MODEL	: TOYOTA CHR HYBRID		ZYX102046066.
CHASSIS NO			Xiao Long
<u>ACCIDENT DETAILS</u>		DATE	: 14/11/2018
		TIME	: 09:05HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Repair</i>	1	\$ 1,366.90	\$ 1,366.90
2	BOOT LID LOGO <i>Rec</i>	1	\$ 80.00	\$ 80.00
3	BOOT LID EMBLEM 'CH-R' <i>rec</i>	1	\$ 72.00	\$ 72.00
4	BOOT LID EMBLEM 'HYBRID SYNERGY DRIVE' <i>rec</i>	1	\$ 95.30	\$ 95.30
5	BOOTLID WEATHERSTRIP <i>rec</i>	1	\$ 240.30	\$ 240.30
6	BOOTLID DETECTOR <i>checked</i>	1	\$ 180.30	\$ 180.30
7	BOOTLID WINDSCREEN MOULDING <i>rec</i>	1	\$ 211.30	\$ 211.30
8	REAR BUMPER <i>del</i>	1	\$ 850.00	\$ 850.00
9	REAR BUMPER LOWER LID <i>del</i>	1	\$ 580.00	\$ 580.00
10	REAR BUMPER SIDE RETAINER <i>rec</i>	2	\$ 62.40	\$ 124.80
11	REAR BUMPER REINFORCEMENT <i>del</i>	1	\$ 555.00	\$ 555.00
12	REAR BUMPER TOWING COVER <i>del</i>	1	\$ 66.50	\$ 66.50
13	REAR BUMPER REFLECTOR HOUSING <i>2nd</i>	2	\$ 182.30	\$ 364.60
14	REAR BUMPER BRAKE LIGHT <i>1st</i>	1	\$ 230.50	\$ 230.50
15	REAR END PANEL <i>del</i>	1	\$ 860.30	\$ 860.30
16	REAR END PANEL TOP GARNISH <i>del</i>	1	\$ 189.20	\$ 189.20

3337.10

TOTAL PRICE \$ 6,067.00

2502.82

LESS 25% \$ 1,516.75

SUB TOTAL PRICE \$ 4,550.25

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not in</i>	1	\$ 50.00	\$ 50.00
2	BOOTLID WINDSCREEN SEALANT <i>Green</i>	1	\$ 100.00	\$ 100.00
3	BOOTLID WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00
4	REAR BUMPER CLIP(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
5	REAR BUMPER TOP CHROME <i>Best</i>	1	\$ 280.00	\$ 280.00
6	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00

400

TOTAL \$ 750.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	600	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	600	
3	TUFF COAT	\$ 250.00	50	
4	WIRING CHECK	\$ 160.00	30	
5	UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	50	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50	
7	TRANSFER BOOT LID MECHANISM	\$ 80.00	x	
8	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 160.00	x	

1380

TOTAL \$ 3,420.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,300.25
TOTAL LABOUR COST : \$ 3,420.00
TOTAL REPAIR COST : \$ 8,720.25

APPROVED DETAILS

EXCESS :

NO. OF DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting.
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim. total: 4282.82
L/s 15/11/18 w/s: 3.4K.
050m/s.