

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111
ATTN: Motor Claim Department

FAX: 62247175

Xiao Tony

Estimate No: EST1800358

Date: 15 Nov 2018

Veh Reg No: SLK7654S

Make/Model: TOYOTA AQUA
HYBRID 1.5L CVT ABS
D/AIRBAG 2WD

Chasis No: NHP102551490

Reg. Date: 25/01/2017

Your Ref No: SKL40R

Claim Type: Third Party

Accident Date: 13/11/2018

TP Veh Reg No: SKL40R

Estimate Repair Cost to Vehicle No :SLK7654S

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR DOOR LH <i>Distorted</i>	858.50 ✓	
2	2 PCS REAR DOOR HINGE LH <i>lower Bent</i>	165.60 82.80 ✓	
3	1 PC REAR DOOR CHECK LH <i>new</i>	131.80 +	
4	1 PC REAR DOOR RUBBER LH <i>new</i>	175.90 ✓	
5	1 PC REAR DOOR LOCK LH <i>Bent</i>	424.70 ✓	
6	1 PC REAR DOOR LOCK CHECKER LH <i>new</i>	94.60 +	
7	1 PC REAR DOOR OUTER CHROME MOULDING LH <i>new</i>	128.30 +	
8	1 PC REAR DOOR FRAME BLACK STICKER LH <i>new</i>	67.90 -	
9	1 PC REAR DOOR REGULATOR LH <i>Bent</i>	194.80 ✓	
10	1 PC REAR DOOR GLASS CHANNEL LH	129.70 +	
11	1 PC REAR DOOR GLASS CHANNEL PILLAR LH <i>new</i>	133.70 -	
12	1 PC REAR LH DOOR TRIM <i>cracked</i>	832.70 530 ✓	
13	1 PC REAR DOOR REGULATOR MOTOR LH <i>new</i>	433.20 +	
14	1 PC FRT DOOR LH <i>Bent</i>	1,021.70 -	
15	1 PC FRT DOOR RUBBER LH <i>new</i>	181.90 ✓	
16	1 PC FRT LH DOOR OUTER MOULDING <i>new</i>	128.30 +	
17	1 PC FRT DOOR FRAME BLACK STICKER LH <i>new</i>	76.30 ✓	
18	1 PC FRT DOOR GLASS CHANNEL LH <i>new</i>	129.70 +	
19	1 PC REAR FENDER LH <i>Distorted</i>	891.70 ✓	
20	1 PC REAR AXLE <i>Bent</i>	2,633.80 ✓	
21	1 PC REAR TYRE RIM LH <i>ut</i>	494.70 250 (sw) ✓	
22	1 PC REAR SHOCK ABSORBER LH <i>Bent</i>	398.70 ✓	
23	1 PC REAR WHEEL HUB & BEARING <i>Bent</i>	613.60 ✓	
24	1 PC REAR LH BRAKE DISC ROTOR <i>new</i>	343.30 +	
25	1 PC REAR TYRE RIM RH <i>ut</i>	494.70 250 (sw) ✓	
26	1 PC REAR SHOCK ABSORBER RH <i>Bent</i>	398.70 ✓	
27	1 PC REAR WHEEL HUB & BEARING RH <i>Bent</i>	613.60 ✓	
28	1 PC REAR RH BRAKE DISC ROTOR <i>new</i>	343.30 +	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST1800358
Date: 15 Nov 2018
Veh Reg No: SLK7654S
Make/Model: TOYOTA AQUA
HYBRID 1.5L CVT ABS
D/AIRBAG 2WD
Chasis No: NHP102551490
Reg. Date: 25/01/2017
Your Ref No: SKL40R

Claim Type: Third Party
Accident Date: 13/11/2018
TP Veh Reg No: SKL40R

Estimate Repair Cost to Vehicle No :SLK7654S

Quantity	Description	List Price	Amount
		SS	SS
		12,535.40	
	Less 25%	3,133.85	9,401.65
	Special Net		
29	1 PC REAR TYRE LH <i>cut</i>	380.00 150	
30	1 PC REAR TYRE RH <i>cut</i>	380.00 180	
	<i>Rear Rim Cover LH 2</i>	60 ✓	
	<i>Rear Rim Cover RH 2</i>	60 ✓	
	Labour		760.00
31	1 TO CHECK WIRING	50.00 30	
32	1 TO REMOVE AND REFIX FRT DOOR GLASS <i>fitting</i>	120.00 80	
33	1 TO REMOVE AND REFIX REAR DOOR GLASS <i>fitting</i>	120.00 80	
34	1 TO REMOVE AND REFIT REAR CUSHION	250.00 100	
35	1 TO REMOVE AND REFIT UNDERCARRIAGE	580.00 480	
36	1 TO CHECK WHEEL ALIGNMENT	120.00 80	
37	1 TO REMOVE AND REFIT PETROL TANK	150.00 80	
38	1 TO SPRAY UNDERSEAL	150.00 80	
39	1 TO SPRAY PAINTING	1,200.00 800	
40	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00 1000	
		4,340.00	4,340.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST1800358

Date: 15 Nov 2018

Veh Reg No: SLK7654S

Make/Model: TOYOTA AQUA
HYBRID 1.5L CVT ABS
D/AIRBAG 2WD

Chasis No: NHP102551490

Reg. Date: 25/01/2017

Your Ref No: SKL40R

Claim Type: Third Party

Accident Date: 13/11/2018

TP Veh Reg No: SKL40R

Estimate Repair Cost to Vehicle No :SLK7654S

Quantity	Description	List Price	Amount
		S\$	S\$
		Total	S\$ 14,501.65
		Add GST @ 7%	1,015.12
		Total Amount Payable	S\$ 15,516.77

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND FIVE HUNDRED SIXTEEN AND CENTS
SEVENTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim, total: 10665.70
1/s 15/10/18. 2/s 8.5K
08 Aug. 8.5K

McWell Ventures Pte Ltd

51 Ubi Avenue 1 #01-05

Paya Ubi Industrial Park

Singapore 408933

Phone Number: 6844 4640

Fax Number: 6844-4641

Customer:		Date:	17/11/2018 4:03 AM
Company:		VIN	
License NO:	SLK7654S	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

TOYOTA, AQUA NHP10, 11-13 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	---	4°15'	5°45'	---
		Right	---	4°15'	5°45'	---
	Camber	Left	-0°18'	-1°00'	0°30'	-0°18'
		Right	-0°24'	-1°00'	0°30'	-0°24'
	Toe	Left	-0°27'	-0°03'	0°08'	-0°27'
		Right	0°27'	-0°03'	0°08'	0°27'
Total		0°00'	-0°05'	0°17'	0°00'	
Rear	Camber	Left	-0°48'	-1°30'	-0°30'	-0°48'
		Right	-0°06'	-1°30'	-0°30'	-0°06'
	Toe	Left	0°12'	0°03'	0°20'	0°12'
		Right	-0°27'	0°03'	0°20'	-0°27'
		Total	-0°15'	0°06'	0°41'	-0°15'
	Thrust Angle		-0°19'	---		-0°19'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	---	11°25'	11°25'	---
		Right	---	11°25'	11°25'	---
Included Angle		Left	---	---	---	---
		Right	---	---	---	---
Toe Out On Turns		Left	---	---	---	---
		Right	---	---	---	---
Max Turn Inside		Left	---	---	---	---
		Right	---	---	---	---
Toe Curve Change		Left	---	---	---	---
		Right	---	---	---	---
Setback		Front	-0.0"	---	---	-0.0"
		Rear	0.1"	---	---	0.1"
Track Width Diff.			0.7"			0.7"
Wheel Base Diff.			-0.1"			-0.1"
Front Ride Height		Left	---	---	---	---
		Right	---	---	---	---
Rear Ride Height		Left	---	---	---	---
		Right	---	---	---	---
Frame Angle			---			---