

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 19 Nov 2018

Preliminary Advice

Vehicle No	: SDL8883E	Accident Date	: 10/11/2018
Make	: JAGUAR XF	Policy No.	: DMPCSN3002701801
Assignment Date	: 15/11/2018	Excess	: S\$750.00
Date of Inspection	: 16/11/2018	Est. Duration of Repair	: 0
Inspection At	: Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road Singapore 159105		

Point of Impact / General Description of Damages

The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection.

Repairer's Estimate (Gross)	:S\$	75,013.50
Revised Amount	:S\$	75,013.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	75,013.50
Lump Sum Repair		:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	102,497.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,503.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :