

ASS. REC. BY:

REF:

EGI18020785/ Avd3 72

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of EGI

Date/Time: 16/11/18 @ 10:26am

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 6969E

Insured: GBD 5949K

at Workshop m/s: Custom Spray Painting

Tel: 9673 9893

of BIK 3019A ubi Rd 1, 408 713

Policy No: Claim No: GBD5949K / SA / P

Sum Insured: Excess: 14/11/2018

Make of Veh: (Client's Record) D.O.A. 8/11/2018

CA / REV / REP. / REV 24 HRS (wp) 19/11/2018

H.O.D. Endorsement:

Date/Time: 10:35am @ 16/11/18 Person Contacted: Francis Vehicle: IN / (OUT)

Date/Time	Action/Instruction (✓) Estimate obtain estimate & advise damage consistency
	SLM 6969E - X
	GBD 5949K - X
19/11/18	Informed Pei Li pending workshop est by email
5/12/18	Adrian confirmed \$ 4218.07 (Red 2770.93, 40%)

Adrian

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 6 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLM6969E Yr Regn: 2017, March.  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Altis c.c. 1598  
 Colour: Silver A/C: Insured / Std / Nil / NA  
 Sp. Reading: 54361 T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MROS3REH104580032  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 215/45 R17  
 R: 215/45 R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. <u>14/11/2018</u>	D.O.I. <u>19/11/18</u>

Survey held at Custom Spray  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Ergo</u>
<u>5/12/18</u>	<u>Email preli revised to Pei Li</u>
<b>RECEIVED 06 DEC 2018</b>	

Date/Time, File Pass to?	Date/Time, File Return to?
1) <u>5/12 - typist</u>	2)
3)	4)
5)	6)
Preli. Report:	
Final Report:	

Part Prices Check:	
IN	OUT

Survey Fee:	Date:
Basic & Add.	
<u>S + RS</u> SI	
Photos	
Others	
TOTAL	<u>250</u>



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: GBD5949K/SA/pl

Our ref: CS/EGI18020785/Avd3

Date : 5/12/2018

The Motor Claims Department  
M/s: ERGO INSURANCE PTE LTD

*Without Prejudice*

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SLM 6969E**


We thank you for your instruction on 16/11/2018.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19/11/2018 at the premises of M/s CUSTOM SPRAY PAINTING PTE LTD

Workshop Estimate Amount	: S\$6,989.00
Revised Estimate Amount	: S\$4,218.07
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING  
B.Eng.,AMSOE,AMIRTE,AMSAE-A,M.MATAI  
Licensed Appraiser

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 5 December 2018 3:44 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: GBD5949K / TP : SLM6969E/LKK / DOA : 08/11/2018  
**Attachments:** SLM 6969E PRELI REVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLM 6969E  
Date of survey: 19/11/2018  
Number of days : 6 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 19 November 2018 5:11 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: GBD5949K / TP : SLM6969E/LKK / DOA : 08/11/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLM 6969E on 19/11/2018.

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 16 November 2018 10:42 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: GBD5949K / TP : SLM6969E/LKK / DOA : 08/11/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 19/11/2018.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

**Sent:** Friday, 16 November 2018 10:26 AM

**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Cc:** SUR ([sur@lkkauto.com](mailto:sur@lkkauto.com)) <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** OI : GBD5949K / TP : SLM6969E/LKK / DOA : 08/11/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CUSTOM SPRAY PAINTING PTE LTD**,

ADDRESS : BLK 3019A UBI ROAD 1  
SINGAPORE 408713

PERSON TO CONTACT : FRANCIS NEO @ 9673 3893

ERGO OFFICER-IN-CHARGE : SITI

***Note: To survey on WITHOUT PREJUDICE basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,  
Yee Pei Li  
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID.: +65 6829 9194  
Tel.: +65 6829 9199  
Fax: +65 6829 9247

# ERGO

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 19 November 2018 5:11 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: GBD5949K / TP : SLM6969E/LKK / DOA : 08/11/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLM 6969E on 19/11/2018.

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 16 November 2018 10:42 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: GBD5949K / TP : SLM6969E/LKK / DOA : 08/11/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 19/11/2018.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Friday, 16 November 2018 10:26 AM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** SUR ([sur@lkkauto.com](mailto:sur@lkkauto.com)) <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** OI : GBD5949K / TP : SLM6969E/LKK / DOA : 08/11/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CUSTOM SPRAY PAINTING PTE LTD,**

ADDRESS : BLK 3019A UBI ROAD 1  
SINGAPORE 408713

PERSON TO CONTACT : FRANCIS NEO @ 9673 3893

ERGO OFFICER-IN-CHARGE : SITI

***Note: To survey on WITHOUT PREJUDICE basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,  
Yee Pei Li  
Claims Assistant (Motor)


ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID: +65 6829 9194  
Tel: +65 6829 9199  
Fax: +65 6829 9247

# ERGO

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Friday, 16 November 2018 10:26 AM  
**To:** 'admin-d@lkkauto.com'  
**Cc:** SUR (sur@lkkauto.com)  
**Subject:** OI : GBD5949K / TP : SLM6969E/LKK / DOA : 08/11/2018  
**Attachments:** GBD5949K - SAS.pdf; SLM6969E - SAS.pdf; SLM6969E - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CUSTOM SPRAY PAINTING PTE LTD**,

ADDRESS : BLK 3019A UBI ROAD 1  
SINGAPORE 408713

PERSON TO CONTACT : FRANCIS NEO @ 9673 3893

ERGO OFFICER-IN-CHARGE : SITI

***Note: To survey on WITHOUT PREJUDICE basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and third party's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Regards,  
Yee Pei Li  
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID: +65 6829 9194  
Tel: +65 6829 9199  
Fax: +65 6829 9247

**ERGO**

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers




**REPUBLIC OF SINGAPORE** **DRIVING LICENCE**


License Number: **S69432681**  
Name: **TAN SENG ENG**

Birth Date: **11 Dec 1969**  
Issue Date: **02 Apr 2003**

000345457K



**REPUBLIC OF SINGAPORE**  
**IDENTITY CARD NO. S69432681**



Name: **TAN SENG ENG**

**陳 声 榮**  
Race: **CHINESE**


Date of Birth: **11-12-1969** Sex: **M**

Country of Birth: **SINGAPORE**

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES**

		PAES DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	04 Apr 1989
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	06 Jul 1994
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	07 Sep 1994

NP 428A



0933



NRIC No. S69432681



Blood Group: O+      Date of issue: 04-05-1993

118 PUNGGOL WALK, TWIN WATERFALLS #10-39  
SINGAPORE 828769

NRIC No: S69432681      Date: 21/10/2015

# CUSTOM SPRAY PAINTING PTE LTD

BLK 3019A, UBI ROAD 1, #01-32, SINGAPORE 408713

TEL: 6742 0982 FAX: 6748 8318

Email: csp.ubi@gmail.com

M/s:ERGO Insurance Pte Ltd.  
5, Temasek Boulevard.  
#04- 01, Suntec Tower Five.  
Singapore 038985.

TP Ergo  
Veron

Date:15-11-2018.

Motor Claim Department  
Dear Sir / Madam.

Re:Estimate of repair

Regn No: SLM 6969 E Toyota Altis 4 Door Saloon Auto.

With abovementioned vehicle the Estimate Of Repair as follow:-

<u>Spare parts supply.</u>		\$	
1pc	Rear bumper <i>Dented</i>	498.50	✓
10pcs	Rear bumper clips <i>new</i>	57.80	← 30
1pc	Rear bumper reflector o/s <i>2 new</i>	48.60	+
1pc	Rear bumper reflector n/s <i>2 new</i>	48.60	+
1pc	Rear bumper bracket <i>2 new</i>	65.30	X
1pc	Rear bumper side retainer o/s <i>2 new</i>	72.50	✓
1pc	Rear bumper side retainer n/s <i>2 new</i>	72.50	✓
1pc	Rear bumper re-enforcement <i>Best</i>	379.00	✓
1pc	Rear boot cover <i>Dented</i>	754.60	✓
1pc	Rear boot cover inner lock <i>Damaged</i>	396.30	-
1pc	Rear boot tail light o/s <i>2 cracked</i>	345.70	✓
1pc	Rear boot tail light n/s <i>2 cracked</i>	345.00	✓
1pc	Rear boot centre chrome moulding <i>2 new</i>	231.40	X
1pc	Rear toyota logo emblem <i>2 new</i>	65.80	-
1pc	Rear Altis emblem emblem <i>2 new</i>	48.60	✓
1pc	Rear number plate lamp o/s <i>2 new</i>	62.50	+
1pc	Rear number plate lamp n/s <i>2 new</i>	62.50	+
1pc	Rear boot inner rubber seal <i>new</i>	166.50	+
1pc	Rear tail end panel <i>Repair</i>	581.50	X
1pc	Rear tail end panel garnish <i>Dented</i>	215.60	✓
1pc	Rear tail lamp o/s <i>2 new</i>	346.40	X
1pc	Rear tillamp n/s <i>2 new</i>	386.40	X
		5251.60	
Less 25%		1312.90	
		<u>3939.00</u>	
		3938.70	
<u>Special nett item</u>			
1set	Rear reversed sensor <i>Damaged</i>	250.00	200.

3224-10  
2418-07

200

# CUSTOM SPRAY PAINTING PTE LTD

BLK 3019A, UBI ROAD 1, #01-32, SINGAPORE 408713

TEL: 6742 0982 FAX: 6748 8318

Email: csp.ubi@gmail.com

## Labour to Repair

Labour to panel beat rear accident affected portion straighten and align back to shape.

~~1800.00~~ sw

Labour to putty and spray painting on accident affected portion and spray anti-rust.

~~1000.00~~ sw . 1600

6988.70

Total estimate of repair      \$ 6,989.00

This estimate is not inclusive of additional parts and repair at current status.

Adrian Lij  
P/P 17/18/18  
O&Kyp.

total: 4218.07 (P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18020785/Avd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 12-12-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 5949K	Veh. Inspected	SLM 6969E
Policy No.		Coverage (\$)	0.00
Claim No.	GBD5949K/SA/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	16/11/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH104560032	Colour	SILVER
Odometer	54361	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	MICHELIN	6 mm
L/H Front Tyre	215/45 R17	MICHELIN	6 mm
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/11/2018	Inspection Date	19/11/2018
Survey held at	CUSTOM SPRAY PAINTING PTE LTD BLK 3019A UBI ROAD 1 #01-31/32 SINGAPORE 408713		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 6969E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	498.50	498.50
10	REAR BUMPER CLIPS	NECESSARY	57.80	30.00
1	REAR BUMPER REFLECTOR O/S	NOT NECESSARY	48.60	-
1	REAR BUMPER REFLECTOR N/S	NOT NECESSARY	48.60	-
1	REAR BUMPER BRACKET	NOT NECESSARY	65.30	-
1	REAR BUMPER SIDE RETAINER O/S	NECESSARY	72.50	72.50
1	REAR BUMPER SIDE RETAINER N/S	NECESSARY	72.50	72.50
1	REAR BUMPER RE-ENFORCEMENT	BENT	379.00	379.00
1	REAR BOOT COVER	DENTED	754.60	754.60
1	REAR BOOT COVER INNER LOCK	DAMAGED	396.30	396.30
1	REAR BOOT TAIL LIGHT O/S	CRACKED	345.70	345.70
1	REAR BOOT TAIL LIGHT N/S	CRACKED	345.00	345.00
1	REAR BOOT CENTRE CHROME MOULDING	NOT NECESSARY	231.40	-
1	REAR TOYOTA LOGO EMBLEM	NECESSARY	65.80	65.80
1	REAR ALTIS EMBLEM	NECESSARY	48.60	48.60
1	REAR NUMBER PLATE LAMP O/S	NOT NECESSARY	62.50	-
1	REAR NUMBER PLATE LAMP N/S	NOT NECESSARY	62.50	-
1	REAR BOOT INNER RUBBER SEAL	NOT NECESSARY	166.50	-
1	REAR TAIL END PANEL	TO REPAIR SEE LABOUR	581.50	-
1	REAR TAIL END PANEL GARNISH	DEFORMED	215.60	215.60
1	REAR TAIL LAMP O/S	NOT NECESSARY	346.40	-
1	REAR TAIL LAMP N/S	NOT NECESSARY	386.40	-
	LESS 25% DISCOUNT		-1,312.90	-806.03
			3,938.70	2,418.07
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR REVERSED SENSOR (SN)	DAMAGED	250.00	200.00
			250.00	200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	LABOUR TO PANEL BEAT REAR ACCIDENT AFFECTED PORTION STRAIGHTEN AND ALIGN BACK TO SHAPE. INCLUSIVE OF THE REPAIR OF REAR TAIL END PANEL.		1,800.00	800.00
	LABOUR TO PUTTY AND SPRAY PAINTING ON ACCIDENT AFFECTED PORTION AND SPRAY ANTI-RUST.		1,000.00	800.00
			2,800.00	1,600.00
	<b>GRAND TOTAL</b>		<b>6,988.70</b>	<b>4,218.07</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,218.07</b>

Report Ref No. CS/EGI18020785/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.