

Surveyor:

NAZ

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

Nature of Accident:

(V/L: YES NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLQ 6102T

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

27/11
joy

SLQ 6102T X; SHA 3682L X

H2R

- MANDATE APPROVED.
- ALL DOCS IN ORDER.
- TO CLOSE.

8-679

LOG IN . FOR MANDATE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

3,836.40

A

days)

Reduction:

63

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

5-7-19

Confirm with

GERALDINE

Email ☐ Call ☐

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No. : 27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

4,115.65

(OLD RATE-ENVELOPE TP)

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

240

(\$60 x 4 days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

4,355.65

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

4,355.65

Name 1:

WORLD AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

+

Name 2:

X

Payee 3: (Strike if N.A.)

SS

-

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

2500.00

ASSIGNMENT

From: Date: 15/11/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLQ 6102T

at Workshop n/s World Auto

of No.1 Kranji loop

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLQ 6102T Yr Regn: 17 JUL 2017

Type: ☒ M.Chr / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA VEZEL HYBRID c.c 1,496

Colour: SILVER A/C: ☒ Insured / ☐ Std / ☐ NI / NA

Sp. Reading: 73,725 T/Radio: ☒ Insured / ☐ Std / ☐ NI / NA

Eng/No:

C/No: RU3 - 1227211

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 215/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 6TICF MICCR

Front

Rear

R/Bal. 6 mm R/Bal. 5 mm

L/Bal. 6 mm L/Bal. 5 mm

D.O.A. 14/11/18 D.O.I. 15/11/18

Survey held at WORLD AUTO

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28-3-19 \$ 3,846.40

R (\$6,690.40/63%)

Date/Time, File Pass In?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS - \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

Joy

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000390

Date : 15/11/2018

Vehicle Num. : SLQ 6102T (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 14/11/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS :		
1.	1	REAR BOOT LID	1600	1,300.00
2.	1	REAR BOOT HYBRID EMBLEM (VEZEL)		89.00
3.	1	REAR BOOT VEZEL EMBLEM (VEZEL)		89.00
4.	1	REAR BOOT LOCK ASSY		300.00
5.	1	REAR WINDSCREEN GLASS MOULDING		250.00
6.	2	REAR BOOT REFLECTOR LAMP	580.00	1,160.00
7.	1	REAR BOOT WEATHER STRIP		180.00
8.	1	REAR END PANEL		680.00
9.	1	REAR END PANEL TOP GARNISH		260.00
10.	1	REAR BUMPER	800	900.00
11.	2	REAR TAIL LAMP	580.00	1,160.00
12.	2	REAR BUMPER REFLECTOR LENS	120.00	240.00
13.	2	REAR BUMPER RETAINER	89.00	178.00
14.	1	SMART BUZZER SENSOR		180.00
15.	1	REAR ANTENNA SENSOR		180.00
16.	1	REAR SIDE BUMPER - LH		250.00

List TotalS\$:

20.00% Discount S\$:

7,396.00

1,479.20

5,916.80

		SPECIAL NETT ITEMS :		
1.	1	REAR WINDSCREEN SEALANT		100.00
2.	1	REAR END PANEL TOP GARNISH CLIPS		40.00
3.	1	REAR BUMPER CLIP		40.00
4.	1	REVERSE SENSOR		280.00
5.	1	REAR TAILLAMP CLIPS		40.00

Special Nett Total S\$:

500.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000390

Date : 15/11/2018
 Vehicle Num. : SLQ 6102T (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 14/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LABOUR :		
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	180.00	60
		REMOVE & REFIT REAR WINDSCREEN GLASS	180.00	80 120
		TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.	180.00	50
		TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.	1,400.00	600
		TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS	1,100.00	500
		TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS	180.00	20
		DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME. (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	200
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	150
		Labour Total S\$:	4,120.00	

E. & O.E.

Total S\$:

10,536.80

for WORLD AUTO PTE LTD

NA2 LXX
 15/11/18
 4 Days
 P/R.
 CHECK ITEMS PHOTO

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000390

Date : 15/11/2018

Vehicle Num. : SLQ 6102T (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 14/11/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID		1,300.00 DEF
2.	1	REAR BOOT HYBRID EMBLEM (VEZEL)		89.00 NE
3.	1	REAR BOOT VEZEL EMBLEM (VEZEL)		89.00 NE
4.	1	REAR BOOT LOCK ASSY		300.00 XSVL
5.	1	REAR WINDSCREEN GLASS MOULDING		250.00 NE
6.	2	REAR BOOT REFLECTOR LAMP	580.00	1,160.00 XSVL
7.	1	REAR BOOT WEATHER STRIP		180.00 ?
8.	1	REAR END PANEL		680.00 ?
9.	1	REAR END PANEL TOP GARNISH		260.00 ?
10.	1	REAR BUMPER		900.00 CRX
11.	2	REAR TAIL LAMP	580.00	1,160.00 XSVL
12.	2	REAR BUMPER REFLECTOR LENS	120.00	240.00 ?
13.	2	REAR BUMPER RETAINER	89.00	178.00 ?
14.	1	SMART BUZZER SENSOR		180.00 ?
15.	1	REAR ANTENNA SENSOR		180.00 ?
16.	1	REAR SIDE BUMPER - LH		250.00 XSVL
List TotalS\$:				7,396.00
20.00% Discount S\$:				1,479.20
				5,916.80
SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN SEALANT		100.00 NE
2.	1	REAR END PANEL TOP GARNISH CLIPS		40.00 NE
3.	1	REAR BUMPER CLIP		40.00 NE
4.	1	REVERSE SENSOR		280.00 XSVL
5.	1	REAR TAILLAMP CLIPS		40.00 XSVL
Special Nett Total S\$:				500.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000390

Date : 15/11/2018
 Vehicle Num. : SLQ 6102T (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 14/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :				
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES			180.00	60
REMOVE & REFIT REAR WINDSCREEN GLASS			180.00	80 120
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.			180.00	50
TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.			1,400.00	600
TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS			1,100.00	500
TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS			180.00	20 (reverse sensor)
DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME. (HV HYBRID SYSTEM SAFETY PROCEDURES)			450.00	?
PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)			450.00	150
Labour Total S\$:				4,120.00

E. & O.E.

Total S\$: 10,536.80

for WORLD AUTO PTE LTD

NAZ LXX
 15/11/18
 4 Days
 P/R
 CHECK ITEMS PHOTO
 & GIVE PAINT PHOTO.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Print Received Message

This mail is associated with :

*SLQ6102T (MCT18110446)
[SHA3682L]
TP
LCRF PTE LTD
Nov 14 2018 12:00AM
[-]
World Auto Pte Ltd - Kranji

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 04/07/2019 08:56 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4355.65) - SLQ6102T - Claim Handler: Sherini Pillai

Approved:4355.65.



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

25/04/2019

Your Ref :

Our Ref : TP/2325/2018

LKK

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04/ #05 IOB BLDG

SINGAPORE 049711

Attn : Motor Claim Dept – Third Party

Dear Sirs,

ACCIDENT INVOLVING VEH.NO. SLQ6102T / SHA3682L ON 14/11/2018

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF)

Enclosed herewith are the following documents for your information and necessary actions only :-

- a) Our Final Repair Bill

Please assist in our claims of :

Final Bill	\$ 3846.40 (already finalised)
GST 7%	\$ 269.25
Loss of Use (\$60 x 4 days)	\$ 240.00
Amount	<u>\$ 4355.65</u>

Kindly let us have your reply and payment as soon as possible.

Thank you for your kind attention and much appreciated assistance.

Yours faithfully,

LETTER OF AUTHORISATION

In the matter of the following accident:-

DATE OF ACCIDENT : **14/11/2018**

CLIENT'S VEHICLE NO : **SLQ6102T**

PLACE OF ACCIDENT : **NEWTON CIRCUS**

THIRD PARTY VEHICLE NO : **SHA3682L**

I/We, **LCRF PTE LTD**

ADDRESS: **29 PAYA LEBAR ROAD, PAYA LEBAR OFFICE CENTRE**

UEN/NRIC/FIN NO : **201624597K**

Tel. (O) _____ (H) _____ (MOBILE) _____

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us in respect of the above matter up to the final conclusion of the said matter.

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us for the purpose of negotiating and enter into settlement with the tortfeasor, their insurers or solicitors appointed by the tortfeasor/insurers without the need to commence action.

I/We hereby authorize World Auto Pte Ltd to receive on my/our behalf all settlement sums and disbursements including loss of use/rental to pay to yourselves all costs you may at any time receive in connection with the above mention matter.

DATED THIS **15TH** OF **NOVEMBER** YEAR **2018**



A handwritten signature in black ink, consisting of a stylized 'L' and 'C' followed by a horizontal line.

Name: **LCRF PTE LTD**
UEN No: **201624597K**

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18110446
Claimant Ref: SLQ 6102T

We/I, WORLD AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 4,115.65 (repair cost), S\$ 240.00 (loss of use/rental), S\$ - (search fee), vehicle no. SLQ 6102T that was damaged pursuant to the accident which occurred on 14.11.2018 (date) at NEWTON CIRCUS (location) involving vehicle no. SHA 3682L (insured vehicle). This is pursuant to the inspection conducted on 15/11/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LCRF PTE LTD ("the third party claimant") of vehicle no. SLQ 6102T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLQ 6102T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,355.65 to WORLD AUTO PTE LTD

Dated this 9 day of July 2019

CLAIMANT:

Signature: _____

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____



Signed by "the workshop" (with chop)

Headline Tomy

SM00848

47 Jalan Pemimpin

#01-02, Singapore 572600

WITNESS:

Signature: _____

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

WORLD AUTO PTE LTD
47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
S'PORE-577200
Tel No. : 64513933 Fax No. : 64557576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #04 / #05 IOB BUILDING
S'PORE 049711

Attention : Motor Claim Department
Contact : 63476100 63476139-LALITA Fax No. : 62244174

Tax Invoice : F189296

Date : 24/04/2019
Vehicle Num. : SLO 6102T
Make/Model : HONDA VEZEL HYBRID
Chassis/Eng# :
Accident Date : 14/11/2018
Claim No. : TP/2325/2018
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount SS
LIST ITEMS :				
1.	1	BOOTLID		1,000.00
2.	1	BOOTLID HYBRID EMBLEM		89.00
3.	1	REAR BOOT VEZEL EMBLEM		89.00
4.	1	REAR WINDSCREEN GLASS MOULDING		250.00
5.	1	REAR BUMPER		800.00
6.	1	BUZZER SENSOR		180.00
List TotalSS :				2,408.00
20.00% Discount SS :				481.60
				1,926.40
SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN SEALANT		100.00
2.	1 SET	REAR BUMPER CLIPS		40.00
3.	1 SET	REVERSE SENSOR		280.00
Special Nett Total SS :				420.00
LABOUR :				
TRANSFER BOOTLID MECHANISM AND ACCESSORIES				60.00
REMOVE & REFIT REAR WINDSCREEN GLASS				120.00
APPLY RUSTPROOFING / TUFFCOATING TREATMENT				50.00
REMOVE REAR ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK, STRAIGHTEN,RESHAPE AND REPLACE PARTS				600.00
PUTTY & SPRAY PAINT REAR AFFECTED AREAS				500.00
WIRINGS CHECK				20.00
PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS				150.00
Labour Total SS :				1,500.00

Total SS : 3,846.40
GST 7% SS : 269.25
Amount Due SS : 4,115.65
=====

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2019 Edit Reg		15 Nov 2018 00:00 Edit Adj Rpt	S\$3,846.40 Edit Estimates	S\$3,846.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD, ID: 199303821R									
Main Claimant: LCRF PTE LTD, Co. Reg. No.: 201624597K									
Vehicle Reg. No.:	SLQ6102T	Date of Loss:	14/11/2018 00:00 - :59 [15 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18110446	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA3682L	Policy No. (Claimant):	-						
		Excess:							
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 27/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (04/07/2019): Alert - Adj Mandate Approved (S\$4355.65) - SLQ6102T - Claim Handler: Sherini Pillai - III_SG (29/03/2019): Alert - Adj Mandate Approved (S\$0.00) - SLQ6102T - Claim Handler: Sherini Pillai - III_SG (22/11/2018): Alert - Adj Mandate Approved (S\$0.00) - SLQ6102T - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ6102T (MCT18110446)
[SHA3682L]
TP
LCRF PTE LTD
Nov 14 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
World Auto Pte Ltd - Kranji

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/03/19 17:59	General View		 Load JPG	☒
2	28/03/19 17:59	General View		 Load JPG	☒
3	28/03/19 17:59	General View		 Load JPG	☒
4	28/03/19 17:59	General View		 Load JPG	☒
5	28/03/19 17:59	General View		 Load JPG	☒
6	28/03/19 17:59	General View		 Load JPG	☒
7	28/03/19 17:59	General View		 Load JPG	☒
8	28/03/19 17:59	General View		 Load JPG	☒
9	28/03/19 17:59	General View		 Load JPG	☒
10	28/03/19 17:59	General View		 Load JPG	☒
11	28/03/19 17:59	General View		 Load JPG	☒
12	28/03/19 17:59	General View		 Load JPG	☒
13	28/03/19 17:59	General View		 Load JPG	☒
14	28/03/19 17:59	General View		 Load JPG	☒
15	28/03/19 17:59	General View		 Load JPG	☒
16	28/03/19 17:59	Dismantled Parts		 Load JPG	☒
17	28/03/19 17:59	Dismantled Parts		 Load JPG	☒
18	28/03/19 18:00	Replacement Part Photo		 Load JPG	☒
19	28/03/19 18:00	Replacement Part Photo		 Load JPG	☒
20	28/03/19 18:00	Replacement Part Photo		 Load JPG	☒
21	28/03/19 18:00	Replacement Part Photo		 Load JPG	☒
22	28/03/19 18:00	Replacement Part Photo		 Load JPG	☒

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/11/18 15:32	ACKNOWLEDGEMENT EMAIL TO III DD 15.11.2018		 Load PDF	
2	22/11/18 09:16	TP ESTIMATE - MARKED		 Load PDF	
3	22/11/18 09:16	TP GIA REPORT		 Load PDF	
4	28/06/19 11:36	WORKSHOP INVOICE		 Load PDF	
5	28/06/19 11:36	LOD		 Load PDF	
6	17/07/19 11:14	DISCHARGE VOUCHER		 Load PDF	
7	17/07/19 11:14	AUTHORISATION TO ACT FORM		 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	19/11/18 09:02	Singapore Accident Statement		 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18020789/NHA3Q2

Date: 17/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No : SLQ6102T

Insured Vehicle No : SHA3682L

Date of Loss: 14/11/2018

Nature of Claim:

TP

Claim No: MCT18110446

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ6102T

Make & Model: HONDA VEZEL, 1.5 HYBRID (A)

Engine No: LEB5927223

Reg. Date: 17/07/2017 (Man. Year: 2016)

Chassis No: RU31227211

Colour: Silver

Odometer: 73725 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Giti 6 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Giti 6 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,416.80	2,346.40	4,070.40	63.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,120.00	1,500.00	2,620.00	63.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,536.80	3,846.40	6,690.40	63.50
+ GST 7.00/7.00% (S\$)	737.58	269.25	468.33	63.50
Nett Amount (S\$)	11,274.38	4,115.65	7,158.73	63.50
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		4,355.65		

INSPECTION

Date of Assignment: 15/11/2018

Date Inspected: 15/11/2018

Inspected At:

World Auto Pte Ltd - Kranji (HQ)
No 1 Kranji Loop
Singapore 739535

Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ6102T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Deformed	1,300.00 FL	*1,000.00 FL
2	1		*REAR BOOT HYBRID EMBLEM (VEZEL)	Necessary	89.00 FL	*89.00 FL
3	1		*REAR BOOT VEZEL EMBLEM (VEZEL)	Necessary	89.00 FL	*89.00 FL
4	1		*REAR BOOT LOCK ASSY	Serviceable	300.00 FL	*- FL
5	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	250.00 FL	*250.00 FL
6	2		*REAR BOOT REFLECTOR LAMP	Serviceable	1,160.00 FL	*- FL
7	1		*REAR BOOT WEATHER STRIP	Serviceable	180.00 FL	*- FL
8	1		*REAR END PANEL	Serviceable	680.00 FL	*- FL
9	1		*REAR END PANEL TOP GARNISH	Serviceable	260.00 FL	*- FL
10	1		*REAR BUMPER	Cracked	900.00 FL	*800.00 FL
11	2		*REAR TAIL LAMP	Serviceable	1,160.00 FL	*- FL
12	2		*REAR BUMPER REFLECTOR LENS	Serviceable	240.00 FL	*- FL
13	1		*REAR BUMPER RETAINER	Serviceable	178.00 FL	*- FL
14	1		*SMART BUZZER SENSOR	Cracked	180.00 FL	*180.00 FL
15	1		*REAR ANTENNA SENSOR	Serviceable	180.00 FL	*- FL
16	1		*REAR SIDE BUMPER -LH	Repair	250.00 FL	*- FL
17	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*100.00 FS
18	1		*REAR END PANEL TOP GARNISH CLIPS	Serviceable	40.00 FS	*- FS
19	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
20	1		*REVERSE SENSOR	Scratched	280.00 FS	*280.00 FS
21	1		*REAR TAILLAMP CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	7,896.00	2,828.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,479.20	481.60
Total Parts (\$\$)	6,416.80	2,346.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	New	180.00	60.00
2	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
3	TO APPLY RUSTPROOFING /TUFFCOATING TREATMENT TO REPLACED PARTS	New	180.00	50.00
4	TO DISMANTLE REAR DAMAGE PARTS ,CUT AND WELD REAR SUPPORT PANEL ,KNOCK ,STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS	New	1,400.00	600.00
5	TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS	New	1,100.00	500.00
6	TO CHECK REAR WIRES ,CONNECTORS ,REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS	New	180.00	20.00
7	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME(HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	0.00
8	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	150.00
Gross Labour Cost (\$\$)			4,120.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >