

22/03/2002

ASS. REC. BY:

REF: CS/FCI18020790/Vgd3¹²

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time:

15/11/18 @ 7:44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GW 98524

Insured:

8HC0234G

at Workshop m/s

Tan Kim Motor

Tel:

68585151

of

51 Defu Lane 10

Policy No:

Claim No:

D18008153MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/11/2018

CA / REV / REP. / REV 24 HRS (up)

20/11/18 @ 9:30am owner waiting

H.O.D. Endorsement:

Date/Time:

16/11/18 @ 9:16am

Person Contacted:

William

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GW 98524 - CS / TMI 18020584 / K/sd3
	8HC0234G - CS / TMI 18020584 / K/sd3
21/11/18 @ 2:46pm	Revised to Sithara by email.

D.O.A. 13/11/18

D.O.A. 13/11/2018

Insurance Mercus

REF: FCL

ASSIGNMENT

From: Date: 20-11-2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 6W9852U
at Workshop m/s: Tan Lim Motor
of: 51 Defu Lane 10

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 24k.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp' 3.18/2023
Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 6W9852U Yr Regn: 1203

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or LM /

Make: Toyota h.ace C.C 2986

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 613862 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LH1621010378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: N/A / S/Rim / STD A/Rim or

Tyre Size: F: 185 R14
R:

BS / DUN / EXNOVA / GY / ES / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 13/11/18 D.O.I: 20/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

7/11/18 confirmed 4/5 of 900 with willies. (Ref 8776, 46%)

* MV: \$24K; UIC: \$14945; NV: \$9055.

RECEIVED 13 DEC 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) 12/12/2018 ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) \$ + RS \$

2) Photos

3) Other

4)

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

71
900

100

50
34

174



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008153MFSH

Date: 21 November 2018

Our Ref: CS/FCI18020790/Uqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GW 9852U .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/11/2018 at the premises of M/s TAN LIM MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,676.00</u> .
Revised Estimate Amount	: S\$ <u>1,166.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the n/s front portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	15-11-2018	Our Ref No. D18008153MFSH
Accident Date	13-11-2018	Claim Type. Third Party
Insured Vehicle	SHC0234G	Third Party Vehicle. GW9852U
Survey Location	51 DEFU LANE 10	
Contact Person.	LAM WEI SHONG WILLIAM	
Contact No.	68585151/ 0	Fax No. 68580877
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN LIM MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 21 November 2018 2:46 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008153MFSH/1
Attachments: CSFCI18020790Uqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of GW 9852U.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Friday, 16 November 2018 9:18 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18008153MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 15 November 2018 7:44 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18008153MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resource



Toyota Hiace

Price Range

Depreciation

> 10 year(!)

Vehicle Type

Advance Search

Home » Used Cars » A&L Automobile Pte Ltd » Toyota Hiace (COE till 07/2023)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.

Do you know? We are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale!

Click here to see all Auspicious Numbers

Ad ~

Aus/UK Uni Foundatn Expo

UK / Australia /
US Uni
Foundation Expo
Sat 1
Suntec
3

OverseasE

Compare [1]

Toyota Hiace (COE till 07/2023)

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$25,900	
Depreciation	\$5,520 /yr	?
Reg Date	15-Aug-2003 (4yrs 8mths 11days COE left)	
Lifespan	14-Aug-2023	
Manufactured	2003	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,986 cc	
Curb Weight	1,500 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
COE	\$16,100	?
OMV	\$22,312	?
ARF	\$1,116	?
Dereg Value	\$15,121 as of today (change)	?
No. of Owners	4	?
Type of Veh	Van	
Category	COE Car, Premium Ad Car	
Availability	Available	

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 06-Oct-2018 | Last Updated on: 17-Nov-2018

Tags: Toyota Hiace, toyota hiace, 2003 Toyota Hiace, 2003 toyota hiace, Toyota, Hiace, hiace, Used Toyota

Upfront Payment

» more Financial info

Transfer Fee	\$25	?
Down Payment	\$2,590 (change)	Maximum 90% Loan ?
1st Instalment	\$573	?
Total Upfront Payment	\$3,188 (excluding insurance)	?

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.

Items for Toyota Hiace

» View All



Location Map

Seller Information

Company	A&L Automobile Pte Ltd » dealer's pricelist » 0 vehs sold 7 vehs available	
Address	11 Mandai Estate #05-09 Search cars nearby this location	
Location	Eldix	
Office No	63627228	
Contact Person(s)	Alan	9021491
	Lynn	9777968
	Sze Lin	8229958

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

[> Back to OnéMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	2200D

Vehicle Details

Vehicle No.:	GW9852U
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DIESEL
Primary Colour:	Green
Manufacturing Year:	2003
Engine No.:	5L5397738
Chassis No.:	LH1621010378
Maximum Power Output:	-
Open Market Value:	\$21,926.00
Original Registration Date:	30 Dec 2003
First Registration Date:	30 Dec 2003
Transfer Count:	1
Actual ARF Paid:	\$1,097.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$15,582.00
COE Rebate Amount:	\$14,945.00
Total Rebate Amount:	\$14,945.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 14 Nov 2018

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SHC234G
Date of Accident : 13 November 2018

Messrs Hu Sheng Marketing

Date : 15 November 2018

Estimate To Repair GW9852U - Toyota Hiace Diesel
Chassis No : LH1621010378

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper <i>grazed</i>	\$ 385.00
02	1 pc	front bumper reinforcement <i>1 in</i>	\$ 280.00
03	1 pc	front bumper moulding <i>new</i>	\$ 115.00
04	1 pc	left front bumper inner air duct <i>new</i>	\$ 85.00
05	1 pc	left front bumper side holder <i>new</i>	\$ 50.00
06	1 pc	left signal lamp <i>new</i>	\$ 135.00
07	1 pc	left headlamp cover garnish <i>grazed</i>	\$ 118.00
			\$ 1,168.00
Less 25 %			\$ 292.00
			\$ 876.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 50.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 350.00
03		Putty and spray painting of the affected portion.	\$ 400.00
			\$ 800.00
Total			\$ 1,676.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

7-888
252
666.00
500.00
1166.00
932

20
280
200
500

*not Allert
dkh
1/5 900
3dy
Whipps After repair
20/11/18*

*LKK Marcus
20/11/18 @ 1000h*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020790/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 234G	Veh. Inspected	GW 9852U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008153MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	15/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2003	
Chassis No.	LH1621010378	Colour	GREEN	
Odometer	613862	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14	FIRESTONE	6 mm	
L/H Front Tyre	185 R14	FIRESTONE	6 mm	
R/H Rear Tyre	185 R14	FIRESTONE	6 mm	
L/H Rear Tyre	185 R14	FIRESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/11/2018	Inspection Date	20/11/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 9852U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	GRAZED	385.00	385.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	280.00	-
1	FRONT BUMPER MOULDING	NECESSARY	115.00	115.00
1	LEFT FRONT BUMPER INNER AIR DUCT	MISSING	85.00	85.00
1	LEFT FRONT BUMPER SIDE HOLDER	BENT	50.00	50.00
1	LEFT SIGNAL LAMP	CRACKED	135.00	135.00
1	LEFT HEADLAMP COVER GARNISH	GRAZED	118.00	118.00
	LESS 25% DISCOUNT		-292.00	-222.00
			876.00	666.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		50.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		350.00	280.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		400.00	200.00
			800.00	500.00
	GRAND TOTAL		1,676.00	1,166.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00

Report Ref No. CS/FCI18020790/Uqd3n2

MARKET VALUE: \$24,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,945.00=NETT VALUE: \$9,055.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.